Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	linerals and Natural Resources	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283         811 S. First St., Artesia, NM 88210         District III - (505) 334-6178         1000 Rio Brazos Rd., Aztec, NM 87410         District IV - (505) 476-3460         1220 S. St. Francis Dr., Santa Fe, NM & U 0 7 2013         87505		30-025-31586
		5. Indicate Type of Lease STATE 🔽 FEE
		6. State Oil & Gas Lease No.
		B0-1431-0027
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALSYFOLDRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		North Monument G/SA Unit (302708)
1. Type of Well: Oil Well 🗸 Gas Well 🗌 Other		8. Well Number 019
2. Name of Operator		9. OGRID Number
Apache Corporation 3. Address of Operator		873 10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705		Eunice Monument; G - SA (23000)
4. Well Location		
	from the North line and $\frac{2}{2}$	
	nship 19S Range 36E	NMPM County Lea
11. Elevation	(Show whether DR, RKB, RT, GR, et 3676' GR	(c.)
<u></u>		
12. Check Appropriate B	ox to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION T	0: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR		·
TEMPORARILY ABANDON		RILLING OPNS. P AND A
		NT JOB
DOWNHOLE COMMINGLE □ CLOSED-LOOP SYSTEM □		
OTHER: Workover	OTHER:	<u> </u>
		and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
·		
Apache would like to drill out CIBP, perforate the lower Grayburg, and acidize per the attached procedure.		
л А		
Spud Date: 10/18/1992	Rig Release Date: 11/02/1992	,
I hereby certify that the information above is true and	d complete to the best of my knowled	dge and belief.
$\Delta$		
SIGNATURE	TITLE Regulatory Tech II	DATE 10/04/2013
Type or print name Fatima Vasquez	E-mail address: Fatima Vasquez	@apachecorp.com PHONE: (432) 818-1015
For State Use Only Detroleum Engineer OCT 0 8 2013		
APPROVED BY:		
Conditions of Approval (iFany):		
-		
		OCT 08 2013

NMGSAU #919 API # 30-025-31586 Sec 25, T19S, R36E Elevation: 3687' KB, 3676' GL TD: 4,500' PBTD: 4,090' Casing Record: 13-3/8" 48# @ 435' w/ 500 sxs to surface 9-5/8" 36# @ 3774' w/ 1570 sxs to surface 7" 20 & 26# K-55 @ 4,060' w/ 225 sxs

Perfs: Grayburg: 3910-17; 40-54; 62-68; 81-86; 3996-4000; 4006-14; 20-37; 40-46 w/ 2 jspf (148 holes). Grayburg: 4056-73 w/ 2 jspf (35 holes) Grayburg: 4098-4116 w/ 2 jspf (37 holes) SQZ'd

Objective: Drill out CIBP, add perforations and acidize the Grayburg. RTP

## AFE: PA-13-4457

- 1. MIRU unit. Check pressure on well.
- 2. ND WH. NU BOP. Rack 2-7/8" J-55 tubing to be used as work string and production string.
- 3. PU and RIH w/ 6-1/4" bit, bit sub on WS to CIBP @ 3,905'.
- 4. RU reverse unit. Break circulation and DO/push CIBP to CICR @ 4,090'. Circulate hole clean. POOH.
- 5. MIRU WL. RIH w/ perforator and perforate the LWR Grayburg at 4,073'-84' w/ 2 jspf 120<sup>o</sup> phasing (22 holes). TOH w/ perf guns. Correlate to Schlumberger Compensated Neutron Litho-Density Gamma Ray log dated 10/31/1992. RDMO WL.
- 6. TIH w/ SN and PKR assembly. Set PKR above perfs at  $\pm$  3,860'. Test backside to 500 psi.
- 7. MIRU acid services. Acidize the Grayburg (3,910-4,073) down the tubing with 5,000 gallons 15% NEFE w/ additives dropping XX lbs of rock salt to divert evenly spaced throughout the job as a max rate but do not exceed 5,000 psi surface treating pressure. Displace to bottom perf with 32 bbls of flush. Release PKR and wash to PBTD. TOH and set PKR at 3,860'.
- 8. RU swab equipment and recover load and swab test for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- 9. Kill well if necessary. TOH w/ PKR and WS.
  - a. If LWR Grayburg is productive, continue to step 10
  - b. If LWR Grayburg is unproductive, TIH and set CIBP @ 3,860' w/ 3 sxs cement on top and prepare the well for plugging and abandonment. RDMOPU.
- 10. RIH w/ 2-7/8" J-55 production tubing and rods as per the Monument office specification
- 11. RDMOPU. Set PU. Space out. Return well to production and place into test for 10 days.



