
Submit 1 Copy To Appropriate District Office State of New Mee District I – (575) 393-6161 Energy, Minerals and Natu 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 Bill S. First St., Artesia, NM 88210 HOBBS OFD CONSERVATION District III – (505) 334-6178 1220 South St. Frar 1000 Rio Brazos Rd., Aztec, NM 874 IOAN 31 2014 Santa Fe, NM 87 District IV – (505) 476-3460 1220 South St. Frar 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NO INECSINGD REPORTS ON WELLS (Do NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUDIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM 6-101) FOR PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injector 2. Name of Operator Occidental Permian Ltd. 3. Address of Operator HCR 1 Box 90 Denver City, TX 79323 4. Well Location	Iral Resources DIVISION ncis Dr. 7505 UG BACK TO A	Form C-103 Revised August 1, 2011 WELL API NO. 30-025-05502 5. Indicate Type of Lease STATE S FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 25 8. Well Number 121 9. OGRID Number: 157984 10. Pool name or Wildcat Hobbs (G/SA)
Unit Letter E 1650 feet from the South line and 990 feet from the West line Section 25 Township 18S Range 37E NMPM Lea County		
11. Elevation (Show whether DR, 3667' DF		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: OTHER: Image: Distribution of the proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion.		
 TIH and tag CIBP at 4100. Cap with 35' sx cmt. Circulate 10# MLF. Perf @ 2840'. Sqz w/30 sx. WOC . Tag. Perf @ 4740'. Sqz w/50 sx. WOC . Tag. Perforate at 400'. Sqz well and circulate to surface. Top Cut off wellhead and install dry hole marker with labeling Clean up location, remove anchors. 	tank and haul co disposal per ODC well-off as necess g.	ary.
Spud Date: Rig Release Date OIL CONSERVATION DIVISION - Hobbs office Must Be Notified OIL CONSERVATION DIVISION - Hobbs office Must Be Notified 24 hours prior to the beginning of Plugging Operations.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE		



.

.

4