Form 3160-5 (August 2007) DE	OCD Hobbs		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010					
			Lease Serial No.     NMLC032511F					
SUNDRY NOTICES AND REPORTS ON WELLS  BYOBBS Bo not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee of	r Tribe Name		
MAR SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree 8910088970	ement, Name and/or No.		
1. Type of Well  ☐ Dil Well RECEIVED  Other INJECTION					8. Well Name and No. STUART L-M UNIT 120			
2. Name of Operator  ENERGEN RESOURCES CORPORA EMMil: BRENDA.RATHJEN@ENERGEN.COM					9. API Well No. 30-025-11536-0	)0-S1		
3a. Address 3300 NORTH A STREET BLD MIDLAND, TX 79705	o. (include area code) 88-3323 8-3140		10. Field and Pool, or Exploratory LANGLIE					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State				
Sec 11 T25S R37E SENW 1980FNL 1650FWL					LEA COUNTY, NM			
Unit								
12. CHECK APPI	ROPRIATE BOX(ES) To	O INDICATI	E NATURE OF N	NOTICE, RE	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	□ <sup>Acidize</sup>	□ Dee		_	on (Start/Resume)	□ Water Shut-Off		
☐ Subsequent Report	Alter Casing		cture Treat	Reclama		□ Well Integrity		
Final Abandonment Notice	☐ Casing Repair☐ Change Plans	_	w Construction g and Abandon	Recomplete Temporarily Abandon		□ Other		
1 mai ribandonment redice	Convert to Injection		_					
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final Ab determined that the site is ready for final REQUEST APPROVAL TO PI	ally or recomplete horizontally, rk will be performed or provide operations. If the operation recondonment Notices shall be final inspection.)  LUG & ABANDON.	, give subsurface e the Bond No. c esults in a multip led only after all	locations and measurn file with BLM/BLA le completion or recordequirements, include	ired and true ver A. Required sub ompletion in a n ling reclamation	tical depths of all pertir sequent reports shall be ew interval, a Form 316 i, have been completed,	nent markers and zones. filed within 30 days fo-4 shall be filed once and the operator has		
PROPOSED PLUGGING PRO	OCEDURE ATTACHED V	WITH CURRE	:NT AND PROPC	OSED WELL	BORE DIAGRAMS	٠.		
THANK YOU!								
RECLAMATION PROCEDURE ATTACHED			SEE ATTACHED FOR CONDITIONS OF APPROVAL					
14. Thereby certify that the foregoing is	Electronic Submission #	235307 verifie	d by the BLM Wel	II Information	System			
•	For ENERGEN RE ted to AFMSS for process	ing by CHRIS	OPHER WALLS	on 03/11/2014	(14CRW0090SE)			
Name(Printed/Typed) RICK ADAMS			Title SR. DISTRICT ENGINEER					
Signature (Electronic S					Date 02/11/2014			
	THIS SPACE FO	OR FEDERA	AL OR STATE (	OFFICE US	E			
Approved By James Como			Title 5	EPS		3-11-14 Date		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would exhibit the applicant to conductive the applicant to conduct the applicant the applicant to conduct the applicant the	itable title to those rights in th	s not warrant or ne subject lease	Office CF	P_				
TiNe 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it	a crime for any r	person knowingly and	t willfully to ma	ke to any department or	r agency of the United		

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

#### **SLMU #120**

Stuart Langlie Mattix Unit Lea County, NM 1980' FNL and 1650' FWL Sec 11, T25S, R37E API — 30-025-11536 Completion Date: 1940

#### Plug & Abandon Procedure

- 1 MIRU Well Service Unit. NDWH, NU BOP.
- 2 RIH and tag CIBP @ 3149'. Spot 35 sxs cement on CIBP. WOC & tag.
- 3 Circulate hole to mud laden fluid
- 4 Perforate at 2425 and squeeze with 25 sxs cement, WOC & tag. 2300, SQZ cmf to 2/80
- And. 6 Perforate at 1,150' and squeeze with 100 sxs cement, WOC & tag. 1050', Soz cont to 950
  - 7 Perforate at 365'. Squeeze and circulate cement to surface. Deep Penetrating Perts. 2 casing
  - 8 Cut off all casing strings at base of cellar or 3' below restored ground level.
  - 9 Cover wellbore with metal plate welded in place or with cement cap.
  - 10 Erect capped abandonment marker inscribed with well information.
  - 11 Cut off dead man anchors and fill in cellar.
  - 12 Clean and restore location to natural condition and fulfill any and all regulatory requirements.

Prepared by: RL Adams 2/6/2014

Add. Top Salt Alug. Perforate @ 1258, SOZ ent to 1158, wood Tag. Can Combine w/ #6 Alug. by Perforating @ 1258, SOZ ent to 950. WOCTEG.

At Cut-off verify emt to surface all annulus.



#### **SLMU #120**

Stuart Langlie Mattix Unit Lea County, New Mexico 1980' FNL and 1650' FWL Sec 11, T25S, R37E

API - 30-025-11536

Spud Date:

1940

KB:

TD: 3454


Completion Date:

1940

GL:

3131

PBTD: 3149 (CIBP)



Surface Casing: 13" @ 316' w/??? sx

Intermediate Casing: 9-5/8" @ 1000' w/??? sx

CIBP Set @ 3149' (06/03)

**Production Casing:** w/??? sx

7" @ 3316'

Liner:

5", 14.87# FJ, 3291-3448

Uncemented, bottom 80' slotted

PBTD:

TD: 34541



# **SLMU #120**

Stuart Langlie Mattix Unit Lea County, New Mexico 1980' FNL and 1650' FWL Sec 11, T25S, R37E API - 30-025-11536

Spud Date:

1940

KB:

3131

TD: 3454

Completion Date:

1940

GL:

PBTD: 3149 (CIBP)


Proposed WBD

Surface Casing: 13" @ 316' w/??? sx

Perf @ 365'. Squeeze and circulate cement to surface.

Intermediate Casing:

9-5/8" @ 1000' w/??? sx



Perf @ 2,425' and squeeze 25 sxs, WOC and tag

Cap CIBP w/35 sx. WOC & tag CIBP Set @ 3149' (06/03)

**Production Casing:** w/??? sx

7" @ 3316'

Liner:

5", 14.87# FJ, 3291-3448 Uncemented, bottom 80' slotted

PBTD:

TD: 3454'



# United States Department of the Interior

#### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



HOBBS OCD

MAR 1 4 2014

In Reply Refer To: 1310

# Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

# Inspection & Enforcement

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Mike Burton
Environmental Protection Specialist
575-234-2226

Jeffery Robertson Natural Resource Specialist 575-234-2230

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Doug Hoag Civil Engineering Technician 575-234-5979

Linda Denniston Environmental Protection Specialist 575-234-5974

Solomon Hughes Natural Resource Specialist 575-234-5951

### Permitting

Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Tanner Nygren Natural Resource Specialist 575-234-5975

Amanda Lynch Natural Resource Specialist 575-234-5922

Legion Brumley Environmental Protection Specialist 575-234-5957

#### Realty, Compliance

Randy Pair Environmental Protection Specialist 575-234-6240

# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.