
## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South	St. Francis Dr. NM <b>HOBBS OCD</b>	WELL API NO. 30-025-28360	
DISTRICT II	Sunta i e,	11171-07000	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210		APR 1 1 2014	STATE X	FEE
DISTRICT III		APR II ZUIT	6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
	TICES AND REPORTS ON WE	LLS DECEIVED	7. Lease Name or Unit Agreeme	ent Name
	OPOSALS TO DRILL OR TO DEEPEN		South Hobbs (G/SA) Unit	
l ·	PPLICATION FOR PERMIT" (Form C-1			
Type of Well:  Oil Well  X	Gas Well Other		8. Well No. 157	
Name of Operator     Occidental Permian Ltd.	/		9. OGRID No. 157984	7
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			····
4. Well Location				
Unit Letter D : 1245			t From The West	Line
Section 10	Township 19-S  11. Elevation (Show whether DF, RK	Range 38-F	NMPM VIIII	Lea County
	3605' GR			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Check	Appropriate Box to Indicate National Appropriate Box to Indicate National Appropriate Nationa		Other Data SEQUENT REPORT OF	F;
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP		BANDONMENT
		-		DANDONWEN!
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	11.3OB 1 1	
OTHER:		OTHER:		
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho  3. RU wire line & run log. Fou  4. ND wellhead/NU BOP.  5. POOH and lay down tubing.  6. RIH w/bit. Tag @4256'. PO  7. RIH w/122 jts of 2-7/8" tubin  8. ND BOP/NU wellhead.	For Multiple Completions: Attach was been dead. Unseat pump and POOF and fill/bridge @3360-1420' and @OOH w/bit.  The property of the property	etails, and give pertinent dates rellbore diagram of proposed of Wrods and pump.  2425'-260'. RD wire line.	, including estimated date of st completion or recompletion.	arting any
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho  3. RU wire line & run log. Fou  4. ND wellhead/NU BOP.  5. POOH and lay down tubing.  6. RIH w/bit. Tag @4256'. PC  7. RIH w/122 jts of 2-7/8" tubin  8. ND BOP/NU wellhead.  9. RIH w/rods and pump. Load  10. Hang on horse head.  11. RDPU & RU. Clean location	For Multiple Completions: Attach was been dead. Unseat pump and POOI and fill/bridge @3360-1420' and @DOH w/bit.  The property of the production of the production of the production.	other:  etails, and give pertinent dates yellbore diagram of proposed of the wireds and pump.  2425'-260'. RD wire line.  2 & 15 jts new IPC) TAC sook.  RUPU 03/03/2014 R	tDPU 03/07/2014	
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho 3. RU wire line & run log. Fou 4. ND wellhead/NU BOP. 5. POOH and lay down tubing. 6. RIH w/bit. Tag @4256'. PO 7. RIH w/122 jts of 2-7/8" tubin 8. ND BOP/NU wellhead. 9. RIH w/rods and pump. Load 10. Hang on horse head. 11. RDPU & RU. Clean location	For Multiple Completions: Attach was been dead. Unseat pump and POOI and fill/bridge @3360-1420' and @DOH w/bit.  The property of the production of the production of the production.	etails, and give pertinent dates rellbore diagram of proposed of the wireds and pump. 2425'-260'. RD wire line.  What is the wired set of the wired set of the wireds and pump. 2425'-260'. RD wire line.  RUPU 03/03/2014 Reledge and belief. I further certify or an (attached) alternative	that any pit or below-grade tank ha	
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho 3. RU wire line & run log. Fou 4. ND wellhead/NU BOP.  5. POOH and lay down tubing. 6. RIH w/bit. Tag @4256'. PO 7. RIH w/122 jts of 2-7/8" tubin 8. ND BOP/NU wellhead. 9. RIH w/rods and pump. Load 10. Hang on horse head. 11. RDPU & RU. Clean location	For Multiple Completions: Attach was been dead. Unseat pump and POOI-nd fill/bridge @3360-1420' and @OOH w/bit.  The properties of the production of the production.  The production of the production of the production of the production.	etails, and give pertinent dates rellbore diagram of proposed of the wire diagram of the wire diag	ct @3942'  RDPU 03/07/2014  that any pit or below-grade tank has e OCD-approved	as been/will be
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho  3. RU wire line & run log. Fou  4. ND wellhead/NU BOP.  5. POOH and lay down tubing.  6. RIH w/bit. Tag @4256'. PO  7. RIH w/122 jts of 2-7/8" tubin  8. ND BOP/NU wellhead.  9. RIH w/rods and pump. Load  10. Hang on horse head.  11. RDPU & RU. Clean location  I hereby certify that the information above is to constructed or closed according to NMOCD guidelines	For Multiple Completions: Attach was been dead. Unseat pump and POOI-nd fill/bridge @3360-1420' and @OOH w/bit.  The properties of the production of the production.  The production of the production of the production of the production.	etails, and give pertinent dates rellbore diagram of proposed of the wide of t	ct @3942'  RDPU 03/07/2014  that any pit or below-grade tank has e OCD-approved	as been/will be
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho  3. RU wire line & run log. Fou  4. ND wellhead/NU BOP.  5. POOH and lay down tubing.  6. RIH w/bit. Tag @4256'. PO  7. RIH w/122 jts of 2-7/8" tubin  8. ND BOP/NU wellhead.  9. RIH w/rods and pump. Load  10. Hang on horse head.  11. RDPU & RU. Clean location  I hereby certify that the information above is to constructed or closed according to NMOCD guidelines	For Multiple Completions: Attach was head. Unseat pump and POOInd fill/bridge @3360-1420' and @DOH w/bit.  ag. (49 jts yellow band, 58 jts new I and test tubing to 1000#. Held On and return well to production.  True and complete to the best of my knowledge.  ageneral permit	etails, and give pertinent dates wellbore diagram of proposed of the words and pump. 2425'-260'. RD wire line.  When the words and pump. 2425'-260'. RD wire line.  When the words are the words and pump. 2425'-260'. RD wire line.  When the words are the words and pump. 2425'-260'. RD wire line.  When the words are the words	including estimated date of stompletion or recompletion.  Example 2 and 2 and 3942 are also as a second and a	04/09/2014 806-592-6280
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho 3. RU wire line & run log. Fou 4. ND wellhead/NU BOP.  5. POOH and lay down tubing. 6. RIH w/bit. Tag @4256'. PO 7. RIH w/122 jts of 2-7/8" tubin 8. ND BOP/NU wellhead. 9. RIH w/rods and pump. Load 10. Hang on horse head. 11. RDPU & RU. Clean location closed according to NMOCD guidelines  SIGNATURE  TYPE OR PRINT NAME Mendy A. Jo	For Multiple Completions: Attach was head. Unseat pump and POOInd fill/bridge @3360-1420' and @DOH w/bit.  ag. (49 jts yellow band, 58 jts new I and test tubing to 1000#. Held On and return well to production.  True and complete to the best of my knowledge.  ageneral permit	etails, and give pertinent dates rellbore diagram of proposed of the Wrods and pump. 2425'-260'. RD wire line.  When the Wrods and pump. 2425'-260'. RD wire line.	including estimated date of stompletion or recompletion.  Example 2 and 2 and 3942 are also as a second and a	04/09/2014 806-592-6280
13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. It. RUPU & RU.  2. Un-hang well and remove ho 3. RU wire line & run log. Fou 4. ND wellhead/NU BOP.  5. POOH and lay down tubing. 6. RIH w/bit, Tag @4256', PO 7. RIH w/122 jts of 2-7/8" tubin 8. ND BOP/NU wellhead. 9. RIH w/rods and pump. Load 10. Hang on horse head. 11. RDPU & RU. Clean location I hereby certify that the information above is to constructed or closed according to NMOCD guidelines.  SIGNATURE TYPE OR PRINT NAME Mendy A. Jo	For Multiple Completions: Attach was head. Unseat pump and POOInd fill/bridge @3360-1420' and @DOH w/bit.  ag. (49 jts yellow band, 58 jts new I and test tubing to 1000#. Held On and return well to production.  True and complete to the best of my knowledge.  ageneral permit	etails, and give pertinent dates rellbore diagram of proposed of the Wrods and pump. 2425'-260'. RD wire line.  When the Wrods and Pump. 2425'-260'. RD wire line.  When the Wrods and Pump. 2425'-260'. RD wire line.  When the Wrods and Pump. 2425'-260'. RD wire line.  When the Wrods and Pump. 2425'-260'. RD wire line.	including estimated date of stompletion or recompletion.  Example 2 and 2 and 3942 are also as a second and a	as been/will be 04/09/2014

## Work Plan Report for Well:SHOU-157D10



## **Survey Viewer**