State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

FILE IN TRIPLICATE OIL CONSEL	RVATION DIVISION	Revised 5-27-2004
DISTRICT! 1625 N. Fayngh Dr. Habby NM avHOBBS OCD	outh St. Francis Dr.	WELL API NO. 30-025-05484
DISTRICT II	Fe, NM 87505	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 85UN 0 3 2014		STATE X FEE
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDR RECEIVED AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form		North Hobbs (G/SA) Unit Section 24
Type of Well: Oil Well Gas Well Other	Injector X	8. Well No. 131
2. Name of Operator	пусски д	9. OGRID No. 157984
Occidental Permian Ltd. 3. Address of Operator		10. D. J
HCR 1 Box 90 Denver City, TX 79323		10. Pool name or Wildcat Hobbs (G/SA)
4. Well Location		
Unit Letter _ I, _ : _ 2310	1315Fee	t From The WEST Line
Section 24 Township 18-S	Range 37-E	E NMPM LEA County
11. Elevation (Show whether DI 3671° GR	F, RKB, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure	ě	
Pit Type 3: Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness : mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate	Natura of Nation Papart or (Other Date
Check Appropriate Box to Indicate NOTICE OF INTENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPT	
		NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: nt details, and give pertinent dates	PLUG & ABANDONMENT IT JOB including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertinent)	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: nt details, and give pertinent dates	PLUG & ABANDONMENT IT JOB including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact. 1. RUPU&RU. 2. ND wellhead/NU BOP.	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: nt details, and give pertinent dates	NS. PLUG & ABANDONMENT IT JOB including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertined proposed work) SEE RULE 1103. For Multiple Completions: Attact. 1. RUPU&RU.	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of	PLUG & ABANDONMENT IT JOB including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead.	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates ch wellbore diagram of proposed of During this procedur the closed-loop syst	PLUG & ABANDONMENT IT JOB In including estimated date of starting any completion or recompletion. The we plan to use the with a steel
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of During this procedur the closed-loop systems and haul conte	PLUG & ABANDONMENT IT JOB Including estimated date of starting any completion or recompletion. The we plan to use the starting any completion or recompletion. The we plan to use the starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertine proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of the closed-loop system tank and haul contections of the closes of the cl	ns. PLUG & ABANDONMENT including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required to the requi
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact I. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD.	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of the closed-loop system tank and haul contections of the closes of the cl	PLUG & ABANDONMENT IT JOB Including estimated date of starting any completion or recompletion. The we plan to use the starting any completion or recompletion. The we plan to use the starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertine proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of the closed-loop syste tank and haul conte disposal per ODC Ru Condition of	ns. PLUG & ABANDONMENT including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required to the requi
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours I hprior of running Miles estre and chargete to the best of my known and the control of the	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of the closed-loop syste tank and haul conte disposal per ODC Ru Condition of	ns. PLUG & ABANDONMENT including estimated date of starting any completion or recompletion. The we plan to use the most of the required to the required to the required to the required to the plants to the required to the plants. The proval: notify office 24 hours
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours 1 hprior of running Mit by estre Chart te to the best of my known to the constructed or closed according to NMOCD guidelines ageneral permit	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates ch wellbore diagram of proposed of the closed-loop system tank and haul contect disposal per ODC Ru Condition of OCD Hobbs nowledge amprior of truming or an (attached) alternative	ns. PLUG & ABANDONMENT IT JOB In including estimated date of starting any completion or recompletion. The we plan to use the with a steel that to the required the 19.15.17 Approval: notify office 24 hours The we plan to use the plan
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours I hprior of running Miles estre and chart for the best of my known to t	COMMENCE DRILLING OPE CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates ch wellbore diagram of proposed of the closed-loop system tank and haul content disposal per ODC Ru Condition of OCD Hobbs nowledge apprior of running or an (attached) alternative plan	re we plan to use em with a steel ints to the required ile 19.15.17 Approval: notify office 24 hours
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours I hprior of running Miles estre Chart ete to the best of my known closed according to NMOCD guidelines 1. a general permit	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of the closed-loop systetank and haul contection of a Condition of a Condition of a OCD Hobbs TITLE Injection Well A	including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required ale 19.15.17 Approval: notify office 24 hours OCD-approved Analyst DATE 5-29-14
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours 1 bprior of running Mit boyestra Chart tet to the best of my known to be a constructed or closed according to NMOCD guidelines 1 a general permit	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates ch wellbore diagram of proposed of the closed-loop system tank and haul contect disposal per ODC Ru Condition of OCD Hobbs TITLE Injection Well A	including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required ale 19.15.17 Approval: notify office 24 hours OCD-approved Analyst DATE 5-29-14
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact N. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours I hprior of running Milible estre and permit a general permit Type OR PRINT NAME Robbie Underhill E-mail address: For State Use Only APPROVED BY	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates ch wellbore diagram of proposed of the closed-loop system tank and haul contect disposal per ODC Ru Condition of OCD Hobbs TITLE Injection Well A	including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required ale 19.15.17 Approval: notify office 24 hours OCD-approved Analyst DATE 5-29-14
PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours 1 hprior of running Millibrestra Chart ete to the best of my known to be a general permit of the state of the section of the	COMMENCE DRILLING OPE CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of During this procedur the closed-loop syste tank and haul conte disposal per ODC Ru Condition of OCD Hobbs TOTALE Injection Well / Robert Underhill@oxy.com	including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required alle 19.15.17 Approval: notify office 24 hours MAPPIPEST CHAPT has been/will be to OCD-approved Analyst DATE 5-29-14 The Telephone No. 806-592-6287
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Failed MIT Testing 13. Describe Proposed or Completed Operations (Clearly state all pertiner proposed work) SEE RULE 1103. For Multiple Completions: Attact 1. RUPU&RU. 2. ND wellhead/NU BOP. 3. Determine failure and repair. 4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection Condition of Approval: notify OCD Hobbs office 24 hours I hprior of running Miliblest & Chartete to the best of my known to be a general permit of the properties of the properties of the permit of the properties of the permit of th	COMMENCE DRILLING OPE CASING TEST AND CEMEN OTHER: Int details, and give pertinent dates the wellbore diagram of proposed of During this procedur the closed-loop syste tank and haul conte disposal per ODC Ru Condition of OCD Hobbs TOTALE Injection Well / Robert Underhill@oxy.com	including estimated date of starting any completion or recompletion. The we plan to use the with a steel to the required ale 19.15.17 Approval: notify office 24 hours OCD-approved Analyst DATE 5-29-14