(November 1994)

determined that the site is ready for final inspection.)

NM OIL CONSERVATION OCD-HOBBS ARTESIA DISTRICT

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 2 2 2014

OMB No. 1004-0135 Expires July 31, 1996

Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenteREACEIVED

NMLC 054667 6. If Indian, Allottee or Tribe Name

abandoned well.								
SUBMIT IN TRIPL	7. If Unit or CA/Agreement, Name and/or No.							
1. Type of Well X Oil Well Gas Well 2. Name of Operator	ICATE - Other instru	OCT OF	EIVEO	8. Well Name and No. GREGORY EL PASO FEDERAL #1				
DC ENERGY, LLC.		. BER		3				
3a. Address c/o Mike Pippin I	LLC	3b. Phone No. (inclu	de area code)	30-025-20491				
3104 N. Sullivan, Farmingto	505-327-4573		10. Field and Pool, or Exploratory Area					
				Crosby Dev	onian			
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Descript	ion)						
660' FSL & 1650' FEL Unit (O			AND				
Sec. 33, T25S, R37E	Lea County, New Mexico							
12. CHECK APPROPRIATE BOX	X(ES) TO INDICATE NA	TURE OF NOTICE, RI	EPORT, OR O	THER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation Recomplete	te ily Abandon	Water Shut-Off Well Integrity Cother Recomplete To San Andres			

MIRUSU. TOH w/all production equipment. Run 4-3/4" bit & csg scraper on 2-7/8" tbg & CO as deep as possible. (Devonian perfs @ 8308'-78', model "D" pkr @ 8125', & Junk in hole @ 8000'). TOH. Set 5-1/2" CIBP as deep as possible & top w/25 sx cmt. Circ hole w/P&A mud (25 sx gel/1000 bbl water). W/tbg @ 7537', pump 75 sx (710') cmt to cover DV tool @ 7487' & old csg leak @ 6890'. WOC & tag cmt. Set a 5-1/2" CIBP @ 5055'. Run cased hole neuton log from 5055' to 8-5/8" csg shoe @ 3779'.

Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once Tesing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operator has

Using new cased hole neutron log, perf ~3780'-4000' w/~35-0.41" holes. Stimulate w/1500 gal 15% HCL acid, & frac Wabout 100,000# 16/30 sand in X-linked gel. CO after frac to CIBP @ 5055'. Land 2-7/8" 6.5# J-55 tbg @ ~4500'. Run pump & rods. Release rig. Complete as a single Sa

					SODIFICITO DIECE					
<u>D</u>		CDA	OV		PPROV	JAL BY ST	ATE	! !		
14. I hereby certify that the foregoing is true and correct					ACCO!	Jec Ioi Isc	Ola			
Name (Printed/Typed)	Title				(B)	NMOCD 9	1-26-	./4		
Mike Pippinmike@pippinllc.com			Petroleur	rEngine	er (Age	mi a a a a	-	Čeroba, s		
Signature MAE Veller	Date		Ju	ne 23, 2	APF	ROVE	D			
THIS SPACE FOR FEDERA			TATE USE				7			
Approved by		Title		Date	SEI	1 8 2014				
Conditions of approval, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subjection would entitle the applicant to conduct operations thereon.	Office	K-85		PK	Swast	2				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department fraudulent statements or representations as to any matter within its jurisdiction.					GARLSB	LANKE MAYNE AD FIELD OFF	ENGENT ICE	Aus OI		

SEE ATTACHED FOR CONDITIONS OF APPROVAL

CIIDICAT TAIIID

Conditions of Approval

DC Energy, LLC Gregory El Paso - 01 API 3002520491, T25S-R37E, Sec 33

September 18, 2014

- 1. A NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the notice of intent package when recompletion changes a well's Pool designation.
- 2. Before casing or a liner is added, replaced, or repaired prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Notify BLM 575-393-3612 as work begins. Some procedures are to be witnessed.
- 5. Surface disturbance beyond the existing pad must have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 10. The BLM PET witness is to run tbg tally and agree to cement volumes and placement. Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.
- 11. BLM plugback procedures for this wellbore require:
 - A. CIBP set less than 100ft above the top perf of 8308 and a cement plug.
 - B. A "H" cement plug set from a minimum depth of 50ft below the DV Tool at 7487ft.
 - C. A "C" cement plug set from a minimum depth of 50ft below Glorieta formation top at 5110ft.
 - D. Tag with tubing each cement plug. A BLM witness required.
- 12. This procedure is subject to the statements numbered 16 through 18.

- 13. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ½" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- 14. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 15. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 16. After setting the top plug and before perforating, perform a charted casing integrity test of 1000 psig. Call BLM 575-393-3612 and arrange for a BLM witness of that pressure test. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Verify all annular casing vents are plumbed to the surface and open during this pressure test. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.
- 17. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 8000 or below to top of cement taken with 0psig casing pressure. The CBL may be attached to a pswartz@blm.gov email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 18. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 19. Submit the BLM Form 3160-**4 Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 20. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 21. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) before 10/20/2014.
- 22. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

PRS

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.