## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISIO	N			
<u>DISTRICT I</u>	1220 South St. Francis Dr.		V	VELL API NO.		
1625 N. French Dr. , Hobbs, NM 88240	Santa Fe	, NM 87505 OBBS		30-025-07342		
DISTRICT II		11924		5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210	•	OCT 17	201/	STATE 5. State Oil & Gas Lease No.	FEE X	
DISTRICT III  1000 Rio Brazos Rd, Aztec, NM 87410		ULILO	EU IT	o. State Oil & Gas Lease No.		
<u></u>	TICES AND REPORTS ON WI	ELLS		7. Lease Name or Unit Agreer	nent Name	
(DO NOT USE THIS FORM FOR PE	ROPOSALS TO DRILL OR TO DEEPER	N OR PLUG BAC <b>RECEN</b>		North Hobbs (G/SA) Unit		
DIFFERENT RESERVOIR. USE "A	APPLICATION FOR PERMIT" (Form C	-101) for such proposals.)	S	Section 18	•	
Type of Well:				342 B. Well No.	~	$\Box$
Oil Well	Gas Well Other I	njector				
Name of Operator     Occidental Permian Ltd.	_		9	9. OGRID No. 157984		
3. Address of Operator				10. Pool name or Wildcat	Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX	79323				110005 (0,011)	
4. Well Location						
Unit Letter O : 330	Feet From The South	Line and 2310	_ Feet Fr	om The East	Line	_
Section 18	Township 18-S	Range	- 38-Е	NMPM	– Lea County	, 🐪
Section 18	11. Elevation (Show whether DF, F		36-E	VIIIIIIII	Lea county	
	3669' KB	, , ,				
Die Die Lander						
Pit or Below-grade Tank Application	or Closure					
Pit Type Depth of Groun					ırface water	
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction	on Materi	al		
12. Chec	k Appropriate Box to Indicate N	ature of Notice. Repor	t. or Oth	er Data		
E-PERMITTING	<u> </u>		SUBSE	QUENT REPORT O	F:	
PEJ P&A NR	P&A R	REMEDIAL WORK		X ALTERING	S CASING	
TEI INT TO P&A	COMP	COMMENCE DRILLIN	IG OPNS		ABANDONMENT	$\equiv$
	CHG Loc-	CASING TEST AND C			AB/ANDONWEIVI	ш
	OMS CHART		CIVICINI .			
OTI IA RBL	JWIS CHARTEN	OTHER:				<u> </u>
13. Describe Proposed or Completed Op					starting any	
proposed work) SEE RULE 1103.  1. RUPU & RU.	For Multiple Completions: Attach	wellbore diagram of prop	osed con	ipletion or recompletion.		
2. ND wellhead/NU BOP.						
3. RIH w/RBP set @994'						
	•					
4. ND BOP/NU wellhead.	hongo DIIDII 04/12/2014 DINE	NI 06/12/2014				
<ul><li>4. ND BOP/NU wellhead.</li><li>5. RDPU &amp; RU for wellhead of</li></ul>	change. RUPU 06/12/2014 RDF	PU 06/12/2014				
4. ND BOP/NU wellhead.	hange. RUPU 06/12/2014 RDF	PU 06/12/2014				
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> </ol>	-					
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> <li>RIH w/bit &amp; drill collars. T</li> </ol>	ag CIBP @4003'. RU power swi	vel & stripper head. Dr	ill CIBP	from 4003-4004'. Push	to bottom @4260	·.
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> <li>RIH w/bit &amp; drill collars. TRD power swivel &amp; stripper</li> </ol>	-	vel & stripper head. Dr	ill CIBP	from 4003-4004'. Push	to bottom @4260	· .
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> <li>RIH w/bit &amp; drill collars. T</li> </ol>	ag CIBP @4003'. RU power swir head. POOH w/bit & drill collar	vel & stripper head. Dr			to bottom @4260	, .
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> <li>RIH w/bit &amp; drill collars. TRD power swivel &amp; stripper</li> </ol>	ag CIBP @4003'. RU power swir head. POOH w/bit & drill collar	vel & stripper head. Dr s. tached sheet for additior	nal data*	**		,
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of the RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> <li>RIH w/bit &amp; drill collars. To RD power swivel &amp; stripper 10. RIH w/CIBP set @4195'.</li> </ol>	ag CIBP @4003'. RU power swir head. POOH w/bit & drill collar	vel & stripper head. Dr s. tached sheet for addition wledge and belief. I further	nal data*:	** any pit or below-grade tank l		·.
<ol> <li>ND BOP/NU wellhead.</li> <li>RDPU &amp; RU for wellhead of RUPU &amp; RU.</li> <li>ND wellhead/NU BOP.</li> <li>POOH and lay down RBP.</li> <li>RIH w/bit &amp; drill collars. TRD power swivel &amp; stripper 10. RIH w/CIBP set @4195.</li> </ol>	ag CIBP @4003'. RU power swir head. POOH w/bit & drill collar	vel & stripper head. Dr s. tached sheet for additionwledge and belief. I further where or an (attached) alte	nal data*:	** any pit or below-grade tank l		·.
4. ND BOP/NU wellhead. 5. RDPU & RU for wellhead of RUPU & RU. 7. ND wellhead/NU BOP. 8. POOH and lay down RBP. 9. RIH w/bit & drill collars. TRD power swivel & strippet 10. RIH w/CIBP set @4195'.	ag CIBP @4003'. RU power swir head. POOH w/bit & drill collar	vel & stripper head. Dr s. tached sheet for addition wledge and belief. I further of the plan	nal data* certify that	** any pit or below-grade tank l CD-approved	nas been/will be	·.
4. ND BOP/NU wellhead. 5. RDPU & RU for wellhead of RUPU & RU. 7. ND wellhead/NU BOP. 8. POOH and lay down RBP. 9. RIH w/bit & drill collars. TRD power swivel & stripper 10. RIH w/CIBP set @4195.	Fag CIBP @4003'. RU power swir head. POOH w/bit & drill collar  ***see att  true and complete to the best of my known, a general permit	vel & stripper head. Dr s.  tached sheet for addition wledge and belief. I further or an (attached) alter plan  TITLE Administr	nal data** certify that rnative O	**  cany pit or below-grade tank leads to the company of the compa	nas been/will be  10/16/2014	
4. ND BOP/NU wellhead. 5. RDPU & RU for wellhead of RUPU & RU. 7. ND wellhead/NU BOP. 8. POOH and lay down RBP. 9. RIH w/bit & drill collars. TRD power swivel & stripper 10. RIH w/CIBP set @4195'.  1 hereby certify that the information above is constructed or closed according to NMOCD guidelines  SIGNATURE  TYPE OR PRINT NAME Mendy A. J	Fag CIBP @4003'. RU power swir head. POOH w/bit & drill collar  ***see att  true and complete to the best of my known, a general permit	vel & stripper head. Dr s. tached sheet for addition wledge and belief. I further of the plan	nal data** certify that rnative O	** any pit or below-grade tank l CD-approved	nas been/will be  10/16/2014	
4. ND BOP/NU wellhead. 5. RDPU & RU for wellhead of RUPU & RU. 7. ND wellhead/NU BOP. 8. POOH and lay down RBP. 9. RIH w/bit & drill collars. TRD power swivel & stripper 10. RIH w/CIBP set @4195.	Fag CIBP @4003'. RU power swir head. POOH w/bit & drill collar  ***see att  true and complete to the best of my known, a general permit	vel & stripper head. Dr s.  tached sheet for addition wledge and belief. I further or an (attached) alter plan  TITLE Administr	nal data** certify that rnative O	**  cany pit or below-grade tank leads to the company of the compa	E 10/16/2014 806-592-6280	
4. ND BOP/NU wellhead. 5. RDPU & RU for wellhead of RUPU & RU. 7. ND wellhead/NU BOP. 8. POOH and lay down RBP. 9. RIH w/bit & drill collars. TRD power swivel & stripper 10. RIH w/CIBP set @4195'.  1 hereby certify that the information above is constructed or closed according to NMOCD guidelines  SIGNATURE  TYPE OR PRINT NAME Mendy A. J	Fag CIBP @4003'. RU power swir head. POOH w/bit & drill collar  ***see att  true and complete to the best of my known, a general permit	vel & stripper head. Dr s.  tached sheet for addition wledge and belief. I further or an (attached) alter plan  TITLE Administr	nal data** certify that rnative O	**  cany pit or below-grade tank leads to the company of the compa	E 10/16/2014 806-592-6280	


OCT 2 2 2014

## NHU 18-342 API #30-025-07342


- 11. RIH w/treating packer set @4187'. RU acid truck and pump 1000 gal of 15% HCL acid. RD acid truck. POOH w/treating packer.
- 12. RIH w/CICR set @3950'. RU Warrior Energy and pump 300 sacks of .2% Super CBL cement. 47 bbl into formation. RD Warrior.
- 13. RIH w/bit & drill collars. Tagged @3946'. RU power swivel & stripper head. Drill out CICR from 3946-3950'. Drill on cement from 3950-4192'. Tagged top of CIBP @4195'. Pressure tested casing to 800 PSI. Held OK. Drilled out CIBP from 4195-4196'. Fell thru to bottom of hole. Tagged @4260'. Drill from new formation from 4260-4368'. (new TD). RD power swivel & stripper head. POOH w/bit & drill collars.
- 14. RU wire line & run CNL/GR/CCL log from TD (wire line tagged @4364') to 3375'. RD wire line.
- 15. RU Archer wire line & perforate casing @4188-4210'. RD wire line.
- 16. RIH w/treating packer set @4181'. RU Warrior Energy and pump 3500 gal of acid with 2000# of rock salt. Flush with 1000 bbl of fresh water. RD Warrior.
- 17. RIH w/bit. Tagged @4368'. POOH w/bit.
- 18. RIH w/Arrowset 1-X Dbl Grip packer set on 127 jts of 2-7/8" Duoline 20 tubing. Packer set @4167'.
- 19. ND BOP/NU wellhead.
- 20. Test casing to 550 PSI for 30 minutes and chart for the NMOCD.
- 21. RDPU & RU. Clean location and return well to injection.

RUPU 07/24/2014 RDPU 08/21/2014





## Work Plan Report for Well: NHSAU 342-18



## **Survey Viewer**

