

	(August 2007) Hobbs DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.	
	RTS ON WELLS		NMLC062486			
a	abandoned we	is form for proposals to II. Use form 3160-3 (AP	um of to re-enter an D) for such proposals. ເມດາຄຸຄ		6. If Indian, Allottee	or Tribe Name
S	SUBMIT IN TRI	PLICATE - Other instruc	11 11 12 12 12 12 12 12 12 12 12 12 12 1		7. If Unit or CA/Agree 8910063990	eement, Name and/or No
1. Type of Well	Gas Well 🛛 Oth	ner: INJECTION	JAN O	6 2015	8. Well Name and No DRICKEY QUEE	N SAND UNIT 816
2. Name of Operator LEGACY RESE		Contact: TING E-Mail: Ipina@lega	LAURA PINA acylp.com	MED	9. API Well No. 30-005-00985-0	00-S1 -
3a. Address PO BOX 10848 MIDLAND, TX	8 79702		3b. Phone No. (include area code Ph: 432-689-5200 Ext: 527	^{:)} 73	10. Field and Pool, or CAPROCK-QU	r Exploratory EEN
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish,	and State
Sec 4 T14S R31E NWNE 665FNL 1980FEL					CHAVES COU	NTY, NM
12.	CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA
TYPE OF SUB	BMISSION		ТҮРЕ О	F ACTION		
Notice of Inte	ant	□ Acidize	Deepen	Productio	on (Start/Resume)	U Water Shut-Off
— .		Alter Casing	□ Fracture Treat	🗖 Reclamat	tion	Well Integrity
□ Subsequent R	-	Casing Repair	□ New Construction	🗖 Recompl		□ Other
Final Abando	onment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Tempora Water Di	rily Abandon	
1)MIRU, ND W 2) RIH w/BP & Circulate mud t					· · · · ·	
Circulate mud 1 3) RIH w/packe at 1890' and R 4) Squeeze the pressure, bleed packer and re- pressure before 5) POOH w/pa 6) RU wireline	er, set and test. D wireline. e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD	vireline w/1500 psi packoff. Po If well squeezes with more to tting packer and reversing cle Leave well SI for 4 hrs with fi Circulate hole full with salt no wireline, RIH w/packer and so v/packer. RBIH after a minimu	erforate (3) han nominal ean. Reset nal squeeze nud and POOI queeze the		RBDMS
Circulate mud f 3) RIH w/packe at 1890' and R 4) Squeeze the pressure, bleec packer and re- pressure befor 5) POOH w/pa 6) RU wireline perforations at	er, set and test. D wireline e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (1220' with a m hat the foregoing is	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v true and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro	vireline w/1500 psi packoff. Po If well squeezes with more to tting packer and reversing cle Leave well SI for 4 hrs with fi Circulate hole full with salt n wireline, RIH w/packer and so v/packer. RBIH after a minimu 286379 verified by the BLM We ESERVES OPERATING, sent to cessing by DAVID GLASS on 1	erforate (3) han nominal ean. Reset nal squeeze hud and POOI queeze the um 4 total hrs ell Information o the Roswell 12/29/2014 (15E	WOC System DRG0009SE)	RBDM
Circulate mud 1 3) RIH w/packe at 1890' and RI 4) Squeeze the pressure, bleec packer and re- pressure beforn 5) POOH w/pa 6) RU wireline perforations at	er, set and test. D wireline. e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (1220' with a m hat the foregoing is	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v true and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro	vireline w/1500 psi packoff. Po If well squeezes with more to tting packer and reversing cle Leave well SI for 4 hrs with fi Circulate hole full with salt n wireline, RIH w/packer and so v/packer. RBIH after a minimu 286379 verified by the BLM We ESERVES OPERATING, sent to cessing by DAVID GLASS on 1	erforate (3) han nominal ean. Reset nal squeeze hud and POOP queeze the um 4 total hrs ell Information o the Roswell	WOC System DRG0009SE)	RBDMS
Circulate mud f 3) RIH w/packe at 1890' and R 4) Squeeze the pressure, bleec packer and re- pressure befor 5) POOH w/pa 6) RU wireline perforations at	er, set and test. D wireline e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (1220' with a m hat the foregoing is	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v true and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro INA	ireline w/1500 psi packoff. Po If well squeezes with more to tting packer and reversing cle Leave well SI for 4 hrs with fi Circulate hole full with salt n wireline, RIH w/packer and so v/packer. RBIH after a minimu 286379 verified by the BLM We ESERVES OPERATING, sent to cessing by DAVID GLASS on 1 Title REGUI Date 12/29/2	erforate (3) han nominal ean. Reset nal squeeze hud and POO queeze the um 4 total hrs che Roswell 12/29/2014 (15E LATORY TEC	WOC System PRG0009SE) H	RBDMS
Circulate mud f 3) RIH w/packe at 1890' and RI 4) Squeeze the pressure, bleed packer and re- pressure before 5) POOH w/pa 6) RU wireline perforations at 14. I hereby certify th Name (Printed/Typ	er, set and test. D wireline e perforations a d off and check pressure well to e COOH. locker. RBIH and and perforate (1220' with a m hat the foregoing is Co <i>ped</i>) LAURA P	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v true and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro INA	vireline w/1500 psi packoff. Po If well squeezes with more to tting packer and reversing cle Leave well SI for 4 hrs with fi . Circulate hole full with salt no wireline, RIH w/packer and so v/packer. RBIH after a minimu 286379 verified by the BLM We SERVES OPERATING, sent to cessing by DAVID GLASS on to Title REGUI	erforate (3) han nominal ean. Reset nal squeeze hud and POO queeze the um 4 total hrs che Roswell 12/29/2014 (15E LATORY TEC	WOC System PRG0009SE) H	RBDMS
Circulate mud f 3) RIH w/packe at 1890' and RI 4) Squeeze the pressure, bleec packer and re- pressure befor 5) POOH w/pa 6) RU wireline perforations at 14. Thereby certify th Name (<i>Printed/Typ</i> Signature	er, set and test. D wireline. e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (1220' with a m hat the foregoing is co ped) LAURA P (Electronic S	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v true and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro INA Submission) THIS SPACE FO	ireline w/1500 psi packoff. Po If well squeezes with more ti tting packer and reversing cle Leave well SI for 4 hrs with fi Circulate hole full with salt n wireline, RIH w/packer and so v/packer. RBIH after a minimu 286379 verified by the BLM We SERVES OPERATING, sent to cessing by DAVID GLASS on 1 Title REGUI Date 12/29/2 DR FEDERAL OR STATE	erforate (3) han nominal ean. Reset nal squeeze hud and POOF queeze the um 4 total hrs b the Roswell 12/29/2014 (15E LATORY TEC 2014 OFFICE US	WOC System DRG0009SE) H	RBDMS
Circulate mud t 3) RIH w/packe at 1890' and RI 4) Squeeze the pressure, bleed packer and re- pressure beforn 5) POOH w/pa 6) RU wireline perforations at 14. I hereby certify th Name (<i>Printed/Typ</i> Signature 	er, set and test. D wireline. e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (1220' with a m hat the foregoing is co ped) LAURA PI (Electronic S ID_R GLASS , if any, are attached tholds legal or equ	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v strue and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro INA Submission) THIS SPACE FO d. Approval of this notice does uitable title to those rights in the	rireline w/1500 psi packoff. Po If well squeezes with more to tting packer and reversing cle Leave well SI for 4 hrs with fi Circulate hole full with salt no wireline, RIH w/packer and so v/packer. RBIH after a minimut 286379 verified by the BLM We ESERVES OPERATING, sent to cessing by DAVID GLASS on 1 Title REGUI Date 12/29/2 DR FEDERAL OR STATE	erforate (3) han nominal ean. Reset nal squeeze hud and POOF queeze the um 4 total hrs b the Roswell 12/29/2014 (15E LATORY TEC 2014 OFFICE US	WOC System DRG0009SE) H	RBDMS CHART
Circulate mud t 3) RIH w/packe at 1890' and RI 4) Squeeze the pressure, bleed packer and re- pressure beforn 5) POOH w/pa 6) RU wireline perforations at 14. I hereby certify th Name (<i>Printed/Typ</i> Signature 	er, set and test. D wireline. e perforations a d off and check pressure well to e COOH. icker. RBIH and and perforate (1220' with a m hat the foregoing is co ped) LAURA Pl (Electronic S ID_R GLASS	t 1890' w/minimum 40 sx for flowback before unse o final squeeze pressure. I tag TOC at/above 1790' 3) at 1220' and 157'. RD inimum of 40 sx. POOH v true and correct. Electronic Submission # For LEGACY RE mmitted to AFMSS for pro INA Submission) THIS SPACE FO d. Approval of this notice does intable title to those rights in the ict operations thereon. U.S.C. Section 1212, make it a	A subject lease	erforate (3) han nominal ean. Reset nal squeeze hud and POOF queeze the um 4 total hrs ell Information o the Roswell 2/29/2014 (150 LATORY TEC 2014 OFFICE US EUM ENGINE	WOC System DRG0009SE) H E E	RBDMS CHART

Revisions to Operator-Submitted EC Data for Sundry Notice #286379

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	ABD NOI	ABD NOI
Lease:	NMLC062486	NMLC062486
Agreement:		8910063990 (NMNM70935X)
Operator:	LEGACY RESERVES OPERATING LP PO BOX 10848 MIDLAND, TX 79702 Ph: 432-689-5200	LEGACY RESERVES OPERATING PO BOX 10848 MIDLAND, TX 79702 Ph: 432-689-5200
Admin Contact:	LAURA PINA REGULATORY TECH E-Mail: Ipina@legacylp.com	LAURA PINA REGULATORY TECH E-Mail: Ipina@legacylp.com
	Ph: 432-689-5200 Ext: 5273	Ph: 432-689-5200 Ext: 5273
Tech Contact:	LAURA PINA REGULATORY TECH E-Mail: Ipina@legacylp.com	LAURA PINA REGULATORY TECH E-Mail: Ipina@legacylp.com
	Ph: 432-689-5200 Ext: 5273	Ph: 432-689-5200 Ext: 5273
Location: State: County:	NM CHAVES	NM CHAVES
Field/Pool:	CAPROCK, QUEEN	CAPROCK-QUEEN
Well/Facility:	DRICKEY QUEEN SAND UNIT 816 Sec 4 T14S R31E NWNE 665FNL 1980FEL	DRICKEY QUEEN SAND UNIT 816 Sec 4 T14S R31E NWNE 665FNL 1980FEL



.•



BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office (RFO), prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.

2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.