Submit 1 Copy To Appropriate District Office <u>District I</u> - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	ice State of New Wex trict I - (575) 393-6161 5 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natura trict II - (575) 748-1283 S. First St., Artesia, NM 88210 OIL CONSERVATION I trict III - (505) 334-6178 0 Rio Brazos Rd., Aztec, NM 87410 1220 South St. France trict IV - (505) 476-3460			Form C-103 Revised July 18, 2013 WELL API NO. 30-025-37561 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.			
87505	ES AND REPORTS ON WELLS		VO-627		Agreement N	Jame	
	7. Lease Name or Unit Agreement Name Yarrow BHY State						
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	8. Well Number						
	as Well Other		1				
2. Name of Operator Yates Petroleum Corporation	_ JAI	N 2 6 2015	9. OGRIE				
3. Address of Operator				name or Wildo	at		
105 South Fourth Street, Artesia, NM	Brinninstool; Delaware						
4. Well Location							
Unit Letter <u>A</u> : <u>9</u>	90 feet from the North	line and	<u>990</u> fe	eet from the	East	line	
Section 32	Township 23S Rai	nge 33E	NMPM	Lea	County	/	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,672' GR							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING							
			IN .				

1	NU BOP	Rig up all, safety equipment as necessary.	
1.	NU DUP.	Rig up an, salety equipment as necessary.	

CHANGE PLANS

Plugback and perforate additional Delaware

Yates Petroleum Corporation plans to plugback and perforate additional Delaware as follows:

MULTIPLE COMPL

2. Set a CIBP at 7,248' and cap it with 35' of cement.

proposed completion or recompletion.

TEMPORARILY ABANDON

PULL OR ALTER CASING

CLOSED-LOOP SYSTEM

OTHER:

DOWNHOLE COMMINGLE

3. Perforate 4 squeeze holes at both +/- 5,400' and pump +/- 150 sacks Class "C" cement. Shut in and WOC.

4. Tag cement. If we don't tag anything down to 5,300', POOH. If we tag before that, drill out cement. Need about 75' - 100' rat hole below bottom perf (which will be 5,190') for the pump.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of

- 5. Run a CBL log, with 1500 psi on it, to confirm we have cement across the perforation interval and about +/- 200' above and below.
- 6. Perforate Delaware 5,178' 5,190' (13 holes).

CONTINUED ON NEXT PAGE:

COMMENCE DRILLING OPNS.

. ...

CASING/CEMENT JOB

OTHER:

and the second sec

П

P AND A

.....

 \Box

-	· •			· · · · · · · · · · · · · · · · · · ·		
Spud Date:			Rig Release	Date:	n an Anton ang Mga taong ang ang ang	1997年1月 1997 1000 1000 1000 1000 1000 1000 1000
		sta i jaka i ja				1 <u>-</u>
I hereby certif	y that the info	rmation above is t	rue and complete to th	e best of my knowledge and be	lief.	
SIGNATURE	form	ellett	TITLE <u>R</u>	Regulatory Reporting Technicia	<u>n DATE January</u>	<u>, 22, 2015</u>
Type or print y	name <u> 1</u>	Laura Watts	E-mail address:	laura@yatespetroleum.com	PHONE:575	-748-4272_
For State Use		May	TITLE	Petroleum Engineer	date 🖉	1/20/19
Conditions of		any):		.1	AN 2 9 2015	-

Yarrow BHY State #1 Section 32-T23S-R33E Lea County, New Mexico Page 2

Form C-103 continued:

- 7. TIH with tubing and packer, spot, break and acidize 5,178' 5,190' with 2000 gallons 7.5% NEFE acid. Over displace 5 bbls. Pump the acid at 3-4 bpm. Flush to bottom perf with 3% KCL water.
- 8. Swab test for fracable show and observe fluid entry.
- 9. If fracable show, and fluid entry is not too high, TIH with 3-1/2" frac string and frac through frac string.
- 10. Frac 5,178' 5,190' (13 holes) through 3-1/2" frac string at 20-25 bpm (treating schedule attached).
- 11. Shut the well in overnight to allow the gel to break and formation to close.
- 12. Flow the well back if it will flow. Clean out sand to 5,000' or to top of retainer at +/-5,100'.
- 13. TIH with production string as per Production Department's specification. Turn well over to production to run pump.


Schematics attached

Regulatory Reporting Technician January 22,/2015

Treating Schedule						
lbs Proppant						
Sta	ge gal					
Number		lb/gal	Stage	Cumulative	Proppant Type	
1	7500.	0.00	0.	0.	Gel Pad	
2	14000.	1 - 6	49000.	49000.	20/40 RCS	
4	+/-5,178.	0.0	0.	49000.	Flush	

Estimated Surface Treating Pressure @ 25 BPM = +/-3,550 psi.

. . **.**



 $= \frac{1}{2} + \frac{1}{2} \frac{1}{2}$

