	Submit 1 Copy To Appropriate District Office	State of New N Energy Minerals and Na	Aexico	Rey	Form C-103		
	1625 N. French Dr., Hobbs, NM 88240	Energy, whiterais and Watural Resources		WELL API NO.			
	District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5 Indicate Type of Lease			
	<u>District III</u> (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fr	ancis Dr.	STATE F	EE		
	<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, INM	87505	6. State Oil & Gas Lease N	10.		
	SUNDRY NOT	ICES AND REPORTS ON WELL	LS	7. Lease Name or Unit Ag	reement Name		
	DIFFERENT RESERVOIR. USE "APPLI PROPOSALS)	CATION FOR PERMIT" (FORM C-101)	FOR SUCI	Dragon 36 State SW	D		
	1. Type of Well: Oil Well	Gas Well 🗍 Other SWD	HOBESOCD	8. Well Number 11			
~	 Name of Operator EOG Resources, Inc. 		0 4 2015	9. OGRID Number 7377			
. /	3. Address of Operator	L TV 70700	FEB 2 4 2010	10. Pool name or Wildcat			
V	P.O. Box 2267 Midla	nd, 1X /9/02	L	SWD; Delaware			
	Unit Letter C	720feet from theNorth	RECEIVER	60feet from the	st WOST line		
	Section 36	Township 24S	Range 33E	NMPM County	Lea		
		II. Elevation (Show whether D	<i>DR, RKB</i> , <i>RT</i> , <i>GR</i> , etc.,				
	12. Check	Appropriate Box to Indicate	Nature of Notice,	Report or Other Data			
	NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT	OF:		
	PULL OR ALTER CASING		CASING/CEMEN				
	OTHER: Step	Rate Test 🛛 🗖	OTHER:				
	 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 						
	1) Make sinker bar run with slickline to verify wellbore is clear						
	2)Shut well in for 48 hours before test.						
	perform step rate test.	perform step rate test.					
	4)RIH w/gauge and set mid perfs (6100 ft). Obtain bottom hole pressure reading before pumping – the well would have been shut in for 48 hours at this point.						
	5)Monitor pressure before test and during test with surface gauge and bottom hole gauge.						
	7)Continue injecting until parting pressure is plotted or maximum rate or pressure is obtained.						
	8)Shut down pumps and n9) RDMO surveyors and p	nonitor fall off for minimum of 15 m pump company.	inutes.		-		
	,10)Notify state of results.		-				
	······································		۲	ROVIDE S.R. I	. RESULTS		
	Spud Date:	Rig Release I	Date: TO	SANTA FE FO	R APPROVAL		
	L		L				
	I hereby certify that the information	above is true and complete to the	best of my knowledg	e and belief.	<u> </u>		
	$\hat{\mathcal{O}}$						
	SIGNATURE KULLE	<u> <u>âMat</u> [TITLE Re</u>	egulatory Analyst	DATE02	/24/2015		
	Type or print name Renee' Jarr	att E-mail addr	ess:	PHONE: 4	32-686-3684		
	For State Use Only	2 7			<u> </u>		
	APPROVED BY: Walent	Drown TITLE DI	st. Super	VILLOU DATE 2,	25/2015		
	Conditions of Approval (if any):		V	1	/		

FEB 2 6 2015

Step Rate Test Sundry

1) Make sinker bar run with slickline to verify wellbore is clear

2)Shut well in for 48 hours before test.

3) Notify the State minimum of 24 hours before the step rate test. MIRU pressure monitoring company and pump company to perform step rate test.

4)RIH w/gauge and set mid perfs (6100 ft). Obtain bottom hole pressure reading before pumping – the well would have been shut in for 48 hours at this point.

5)Monitor pressure before test and during test with surface gauge and bottom hole gauge.

✓ 6)Begin step rate test. Vary/increase pump rates while measuring BHP over intervals no less than 30 minutes.

Rate	Time
0.5 BPM	30 minutes minimum
1 BPM	30 minutes minimum
1.5 BPM	30 minutes minimum
2 BPM	30 minutes minimum
3 BPM	30 minutes minimum
4 BPM	30 minutes minimum
5 BPM	30 minutes minimum
6 BPM	30 minutes minimum
8 BPM	30 minutes minimum

*Continue w/ 2 BPM or 1,000BPD steps until parting pressure is plotted or maximum rate and pressure are reached as determined by operator.

7)Continue injecting until parting pressure is plotted or maximum rate or pressure is obtained.

8)Shut down pumps and monitor fall off for minimum of 15 minutes.

9) RDMO surveyors and pump company.

10)Notify state of results.



Dragon 36 State SWD #11 WBD 2.22.15.xls