Office	State of New Mex Energy, Minerals and Natura		Form C-103 March 4, 2004
<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 . District II			WELL API NO. 30-025-28946
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION I		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Franc		STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 37505	Santa Fe, NM 875	505	6. State Oil & Gas Lease No. LG-6478
SUNDRY NOTIC	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ΓΙΟΝ FOR PERMIT" (FORM C-101) FOR	R SUCH	Abo D, 7903 JV-P
PROPOSALS.) 1. Type of Well:	HC)BBS OCD	8. Well Number
	ther		2
 Name of Operator BTA Oil Producers LLC 		R 3 @ 2015	9. OGRID Number 260297
 Address of Operator 104 S. Pecos, Midland, TX 7970 	R	ECEIVED	10. Pool name or Wildcat Double A, ABO, South 19050
4. Well Location	·		Bouble A, ABO, South 19050
Unit Letter <u>L</u> :	2310 feet from the South	line and 90	1 feet from the West line
Section 30	Township 17S F	Range 36E	NMPM Lea County
	11. Elevation (Show whether DR, 1	RKB, RT, GR, etc.)	
it or Below-grade Tank Application (For p			
Distance from nearest surface water	RngPit typeDep Below-grade Tank Location_UL	th to Groundwater SectTwp	Distance from nearest fresh water well Rng;
feet from theline and	feet from theline		·····
NOTICE OF INT E-PERMITTING <swd< th=""><th>ENTION TO:</th><th></th><th>Report or Other Data EQUENT REPORT OF:</th></swd<>	ENTION TO:		Report or Other Data EQUENT REPORT OF:
NOTICE OF INT E-PERMITTING <swd CONVERSION RETURN TO CSNG</swd 	INJECTION> INJECTION> RBDMS TA CHG LOC	SUBS	EQUENT REPORT OF:
NOTICE OF INT E-PERMITTING <swd CONVERSION RETURN TO CSNG INT TO PA P & A NK OTHER:</swd 	INJECTION> INJECTION> RBDMS TA CHG LOC TP&A R	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER:	EQUENT REPORT OF:
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NK OTHER: Describe proposed or comple of starting any proposed work or recompletion. 02/05/2015 1 MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ 1 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and sp</swd 	ENTION TO: INJECTION> RBDMS TA CHG LOC P&A R ed operations. (Clearly state all performance) SEE RULE 1103. For Multiple BOP. POH w/prod equipment sx cmt 9096'-8773' 337' 407' 527' 552'. Spot 80 sx 3612'-3280'. Ta 771' 5'	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	EQUENT REPORT OF: Image: Altering Casing Image: A
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NK OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 02/05/201\$ 1 MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ . 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and sp 10 Install Dry Hole Marker hereby certify that the information ab</swd 	ENTION_TO: INJECTION> RBDMS	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	SEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D give pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NR OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 02/05/201\$ I MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ . 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and s 10 Install Dry Hole Marker hereby certify that the information abrade tank has been/will be constructed or character 10 Car March 2000</swd 	ENTION_TO: INJECTION> RBDMS TA CHG LOC ed operations. (Clearly state all performance) SEE RULE 1103. For Multiple BOP. POH w/prod equipment sx cmt 9096'-8773' 337' 407' 527'. 552'. Spot 80 sx 3612'-3280'. Ta 771' 5'. bot 30 sx 100'-surface ove is true and complete to the beside according to NMOCD guidelines	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	SEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D give pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NK OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 02/05/201\$ 1 MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ . 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and sp 10 Install Dry Hole Marker hereby certify that the information ab</swd 	ENTION_TO: INJECTION> RBDMS TA CHG LOC ed operations. (Clearly state all performance) SEE RULE 1103. For Multiple BOP. POH w/prod equipment sx cmt 9096'-8773' 337' 407' 527'. 552'. Spot 80 sx 3612'-3280'. Ta 771' 5'. bot 30 sx 100'-surface ove is true and complete to the beside according to NMOCD guidelines	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	Comparison ALTERING CASING LING OPNS. PLUG AND ABANDONMENT ABANDONMENT D Image: Comparison of proposed completion give pertinent dates, including estimated date ach wellbore diagram of proposed completion and belief. I further certify that any pit or below-r an (attached) alternative OCD-approved plan rator DATE 03/25/2015
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NK OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 02/05/2015 1 MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ . 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and sy 10 Install Dry Hole Marker hereby certify that the information ab ade tank has been/will be constructed or cl IGNATURE</swd 	ENTION_TO: INJECTION> RBDMS	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	Comparison ALTERING CASING LING OPNS. PLUG AND ABANDONMENT ABANDONMENT D Image: Comparison of proposed completion give pertinent dates, including estimated date ach wellbore diagram of proposed completion and belief. I further certify that any pit or below-r an (attached) alternative OCD-approved plan rator DATE 03/25/2015
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NR OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 02/05/2018 1 MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and s 10 Install Dry Hole Marker hereby certify that the information abr ade tank has been/vill be constructed or ch IGNATURE MARKEN his space for State use)</swd 	ENTION_TO: INJECTION> RBDMS TA CHG LOC ed operations. (Clearly state all pector) SEE RULE 1103. For Multiple BOP. POH w/prod equipment sx cmt 9096'-8773' 37' 407' 527' 552'. Spot 80 sx 3612'-3280'. Ta 771' 5' bot 30 sx 100'-surface Ove is true and complete to the best seed according to NMOCD guidelines LAAA	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	EQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D give pertinent dates, including estimated date ach wellbore diagram of proposed completion and belief. I further certify that any pit or below- ran (attached) alternative OCD-approved plan []. rator DATE 03/25/2015 bil.com Telephone No. (432) 682-3753
NOTICE OF INT P E-PERMITTING <swd CONVERSION RETURN TO P CSNG INT TO PA P&A NK OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 02/05/2015 1 MI RU PU. ND WH, NU 2 Set CIBP @ 9026, spot 25 3 Spot 25 sx cmt @ 8590'-8 4 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 6660'-6 5 Spot 25 sx cmt @ 4880'-4 6 Cut & pull 5-1/2" csg @ 7 Spot 35 sx cmt @ 1900'-1 8 Spot 60 sx cmt @ 457'-23 9 Cut off WH and csg and sp 10 Install Dry Hole Marker hereby certify that the information ab rade tank has been/will be constructed or cl IGNATURE</swd 	ENTION_TO: INJECTION> RBDMS	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: ertinent details, and Completions: Atta	Comparison ALTERING CASING LING OPNS. PLUG AND ABANDONMENT ABANDONMENT D Image: Comparison of proposed completion give pertinent dates, including estimated date ach wellbore diagram of proposed completion and belief. I further certify that any pit or below-r an (attached) alternative OCD-approved plan rator DATE 03/25/2015