Submit I Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, witherars and reading Resources	WELL API NO.
District II	OIL CONSERVATION DIVISION	30-025-05752
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 c, 1441 07303	6. State Off & Gas Lease No.
87505		
	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1 '	ATION FOR PERMIT" (FORM C-101) FOR SUCH	North Monument G/SA Unit Blk. 10
		8. Well Number 13
1. Type of Well: Oil Well	Gas Well Injection well HOBBS OCD	
2. Name of Operator	AUG 2 5 2015	9. OGRID Number 873
Apache Corp.  3. Address of Operator	ANG X D LOVE	10. Pool name or Wildcat
P O box Drawer D Monument NM	88265	Eunice Monument G/SA
4. Well Location	RECEIVED	Dames Monament Groff
	. 220 Fact from the S. Line and	220 fact from the
	:330feet from theS line and	ieet from the
line		
Section 30	Township 19S Range 37	
	11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
10 0		D 01 D
12. Check A	appropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF IN	TENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WO	
TEMPORARILY ABANDON	<del>-</del>	PRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	<del></del>
DOWNHOLE COMMINGLE	WOETH EL COMITE GARAGEETE	
OTHER: MPT	OTHER:	
13. Describe proposed or comp	eted operations. (Clearly state all pertinent details,	
13. Describe proposed or complete of starting any proposed wo	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple C	
13. Describe proposed or complete of starting any proposed wo proposed completion or reco	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple C	
13. Describe proposed or complete of starting any proposed we proposed completion or receivers 3,761 – 3,790	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple C	
13. Describe proposed or complete of starting any proposed wo proposed completion or reco	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple C	
13. Describe proposed or complete of starting any proposed we proposed completion or receivers 3,761 – 3,790 O H 3,790 – 3,899	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	Completions: Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple C	Completions: Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed we proposed completion or receivers 3,761 – 3,790 O H 3,790 – 3,899	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	Completions: Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	Completions: Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	Completions: Attach wellbore diagram of ker & test to 500 psi
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	Completions: Attach wellbore diagram of ker & test to 500 psi  Condition of Approval: notify
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	Completions: Attach wellbore diagram of ker & test to 500 psi
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	Completions: Attach wellbore diagram of ker & test to 500 psi  Condition of Approval: notify
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or received Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours
13. Describe proposed or complete of starting any proposed we proposed completion or receivers 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours
13. Describe proposed or complete of starting any proposed we proposed completion or receivers 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours
13. Describe proposed or complot of starting any proposed wo proposed completion or recorders 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.	completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours  ior of running MIT Test & Chart
13. Describe proposed or complot of starting any proposed wo proposed completion or recorders 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.  Rig Release Date:	completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours  ior of running MIT Test & Chart
13. Describe proposed or complete of starting any proposed wo proposed completion or recorders 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer. Rig Release Date:	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours ior of running MIT Test & Chart  dge and belief.
13. Describe proposed or complot of starting any proposed wo proposed completion or recorders 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:	eted operations. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.  Rig Release Date:	completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours  ior of running MIT Test & Chart
13. Describe proposed or complete of starting any proposed we proposed completion or record Perfs 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:	rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.  Rig Release Date:  TITLEInstrument Tech	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours ior of running MIT Test & Chart  dge and belief.  DATE &-25-75
13. Describe proposed or complete of starting any proposed we proposed completion or record Perfs 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:  I hereby certify that the information of SIGNATURE	rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.  Rig Release Date:  TITLEInstrument Tech	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours ior of running MIT Test & Chart  dge and belief.
13. Describe proposed or complete of starting any proposed we proposed completion or record Perfs 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:	Propertions. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer. Rig Release Date:  Rig Release Date:  TITLEInstrument Tech  E-mail address: _JD.Ellison@.	Completions: Attach wellbore diagram of ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours ior of running MIT Test & Chart  dge and belief.  DATE 8-25-15  apacheccorp.com_PHONE: 575-441-7734
13. Describe proposed or complete of starting any proposed we proposed completion or record Perfs 3,761 – 3,790 O H 3,790 – 3,899  Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:  I hereby certify that the information of SIGNATURE	Propertions. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer. Rig Release Date:  Rig Release Date:  TITLEInstrument Tech  E-mail address: _JD.Ellison@.	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours  ior of running MIT Test & Chart  dge and belief.  DATE 8-25-15  apacheccorp.com_PHONE: 575-441-7734
13. Describe proposed or comploin of starting any proposed wo proposed completion or record Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:  I hereby certify that the information and SIGNATURE  Type or print nameJim EllisonFor State Use Only	rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer.  Rig Release Date:  TITLEInstrument Tech	Completions: Attach wellbore diagram of  ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours  ior of running MIT Test & Chart  dge and belief.  DATE 8-25-15  apacheccorp.com_PHONE: 575-441-7734
13. Describe proposed or complete of starting any proposed wo proposed completion or record Perfs 3,761 – 3,790 O H 3,790 – 3,899 Plan to move in a Lucky rig & POOI Packer set +- 3,727  Spud Date:  I hereby certify that the information is SIGNATURE  Type or print name Jim Ellison For State Use Only  APPROVED BY:	Propertions. (Clearly state all pertinent details, rk). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  H with tubing & packer. RIH with new tubing & packer. Rig Release Date:  Rig Release Date:  TITLEInstrument Tech  E-mail address: _JD.Ellison@.	Completions: Attach wellbore diagram of ker & test to 500 psi  Condition of Approval: notify  OCD Hobbs office 24 hours ior of running MIT Test & Chart  dge and belief.  DATE 8-25-15  apacheccorp.com_PHONE: 575-441-7734