Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

NMNM6136	60

Do not use thi abandoned we	is form for proposals to II. Use form 3160-3 (API	drill or to re-enter an D) for such proposals HOBI	BS OCD	6. If Indian, Allottee or T	ribe Name
	PLICATE - Other instruc	tions on reverse side.	a onic	7. If Unit or CA/Agreeme NMNM94480X	ent, Name and/or No.
Type of Well ☐ Gas Well ☐ Oth	er	√ √ √ √ √ √ √ √ √ √		8. Well Name and No. GAUCHO UNIT 20H	
Name of Operator DEVON ENERGY PRODUCT	Contact: ION CO EFMail: trina.couch	TRINA C COUCH REC	EIVED	9. API Well No. 30-025-41978-00-	X1 /
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102	2	3b. Phone No. (include area code) Ph: 405-228-7203		10. Field and Pool, or Ex OJO CHISO	ploratory
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. County or Parish, and	l State
Sec 29 T22S R34E SESW 02 32.355420 N Lat, 103.492146				LEA COUNTY, N	M
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE NATURE OF 1	NOTICE, R	EPORT, OR OTHER	DATA
TYPE OF SUBMISSION		TYPE OF	ACTION		
Notice of Intent	☐ Acidize☐ Alter Casing	☐ Deepen☐ Fracture Treat☐	CONVE	MITTING <swd ERSION</swd 	RBDMS
☐ Subsequent Report	Casing Repair	■ New Construction	RETUR		TA
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	CSNG	ENVIRO_	CHG LOC
	☐ Convert to Injection	☐ Plug Back	INTTO	PACPM P&A NE	RP&A R
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re-	give subsurface locations and measure the Bond No. on file with BLM/BIA sults in a multiple completion or reco	red and true v Required su mpletion in a	ertical depths of all pertinen absequent reports shall be fil new interval, a Form 3160-	t markers and zones. ed within 30 days 4 shall be filed once

Devon Energy Production Company, L.P. respectfully requests to plug the surface hole and skid 25' West towards the Gaucho Unit 21H and redrill the surface on the Gaucho Unit 20Y due to the high doglegs experienced.

Attached is the plugging procedure and proposed cement slurry. Verbal given by C. Walls

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


determined that the site is ready for final inspection.)

Thank you

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify the	hat the foregoing is true and correct. Electronic Submission #315750 verifie For DEVON ENERGY PRODUC Committed to AFMSS for processing by CHRIS	TION C	D LP, sent to the Hobbs	
Name (Printed/Typ	ped) TRINA C COUCH	Title	REGULATORY ANALYST	
Signature	(Electronic Submission)	Date	09/08/2015	·
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Conditions of approval certify that the applican	istopher walls if any, are attached. Approval of this notice does not warrant or tholds legal or equitable title to those rights in the subject lease applicant to conduct operations thereon.		PETROLEUM ENGINEER Hobbs	Date 09/09/2015

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



M

Gaucho Unit 20H Surface Plugging

TD - 1,688'

Hole Diameter from fluid caliper - 21.58"

	Slurry Inform	nation	
Mix Water	6.42 gps	Yield	1.35 (cu ft/sk)
Slurry Density	14.8 ppg	Mud Wt.	9.6 ppg

- 1. Run in hole with 5" open ended drill pipe to TD.
- 2. Mix and pump the first half of the balanced cement plug (425 bbls or 1770 sacks)
- 3. Trip out of hole to 844' and circulate cement out of hole.
- 4. Mix and pump the second half of the balanced cement plug (425 bbls 1770 sacks) circulating cement to surface. Be prepared to handle cement returns to surface.
- 5. If cement falls, top off with sackrete
- 6. Cut off conductor at ground level and weld on a cap as the a dry hole marker with the following information welded, stamped or otherwise permanently engraved into the marker's metal

The operator name
Lease name and well number
Location, (unit letter, section, township and range)
Date of plugged

7. Skid the rig west 25' too drill the Gaucho Unit 20Y





Company: Well Name: County: District:	Historical Data Historical Data WTX	TVD: MD: BHST: BHCT:	2000 2000 107 93	ft ft °F °F	Test Date: Requestor: Job Type: Slurry:	Luis Rodriguez Plugback Plug
Analyst:		Rig:	Other	· 1	Blend Type:	Field Blend
Mix Water	6.42		mation		Yield	1.35 (cu ft/sk)
Slurry Density	14.8				Mud Wt.	9.6 ppg

Cement Blend: Class C

Sack Weight

94 lbs/sk


2 %bwocGELGelling Agent0.4 %bwocCPT-35Dispersant0.15 %bwocCPT-20Cement Retarder

				8 hr:	1189	
				12 hr:	1652	
19	3:07	70 BC's	2646	24 hr:	2284	
				50 psi:	3:13	
				500 psi:	5:05	
	Fluid P	roperties	V. STATE SALAR		theological data (cP)	TAKES TO SEE
	od Schie	3.3		Temperature 300	200 100 60 30	6 . 3
mperature	(°F)	-				
•						

CREST PUMPING TECHNOLOGIES

BHCT: 93

Job Type: Plugback Time to 70Bc: 3:07:30



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours operator will place full tubing weight on plug when tagged.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs. The Neat cement shall be mixed according to the API water requirement. If operator requests a variance from the API water requirement, the plug(s) will be tagged and possibly pressure tested.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.