Form 3	160-5
(Augus	t 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY N	OTICES A	ND REPORTS	ON WELLS
Do not use this	form for pr	oposals to drill	or to re-enter an
handanad wall	Ilaa farm	2460 2 /A DOL 60	warrah menanasala


Lease Serial No. NMNM19859 6. If Indian, Allottee or Tribe Name

abandoned wei	ii. Use form 3160-3 (AP	D) for such proposals.			***************************************	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Oil Well	ner	HOBE	SOCY	8. Well Name and No. TRISTE DRAW 3	FEDERAL 1	
Name of Operator EOG RESOURCES, INC.	Contact: E-Mail: stan_wagi	STAN WAGNER ner@eogresources.com	2 1 2015	 API Well No. 30-025-34518 	/	
3a. Address P.O. BOX 2267 MIDLAND, TX 79702		3b. Phone No. (include area code Ph: 432-686-3689	ECEINED	10. Field and Pool, or I JOHNSON RAN	Exploratory ICH WOLFCAMP	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description			11. County or Parish, a	and State	
Sec 3 T25S R33E 1826FNL 6	60FEL /	C R	E-PERMIT!	LEA COUNTY, N	MM	
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE NAT CS	ETURN TO	ON SOND	DATA	
TYPE OF SUBMISSION		"NT	NG TO PATE	NVID RE	1/14	
Notice of Intent	☐ Acidize	☐ Deepen	L'ACTOM	P&A I	INS HONZ	
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	Reclama.	- NR CH	1G/G	
	☐ Casing Repair	1 New Construction	☐ Recomple	ete P	HG LOC BLAR	
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Temporar	rily Abandon	"W	
	☐ Convert to Injection	☐ Plug Back	☐ Water Di	sposal		
1. Dump bail 35 of Class H cc 2. Spot 30 sx Class H cement 3. Spot 30 sx Class H cement 4. Spot 30 sx Class H cement 5. Cut 5-1/2" casing at 5100' 6 6. Spot 75 sx Class C cement 7. Spot 65 sx Class C cement 8. Spot 65 sx Class C cement 9. Spot 30 sx Class C surface 10. Clean location, cut off and	ement on existing CIBP at plug at 10450' to 14750 to plug at 9200' to 9400'. It plug at 6500' to 6700'. Plug at 6500' to 5200'. It plug at 4900' to 5200'. It plug at 1600' to 1900'. It plug at 600' to 700'. Word plug. Ensure there is centered at 1900's plug. Ensure there is centered at 1900's plug.	At 12851'. SEE COA '. WOC and Tag. WOC and Tag. OC and Tag. OC and Tag.	SEE COA	ALCAMATION AS A STACKED	CHED FOR	
14. I hereby certify that the foregoing is	Electronic Submission #	319809 verified by the BLM We	ell Information	System	. The	
	Committed to AFMSS	RESOURCES, INC., sent to the for processing by LINDA JIME!	NEZ on 10/23/20	015 ()		
Name (Printed/Typed) STAN WA	GNER	Title REGUI	LATORY ANA	LYST		
Signature (Electronic S	(nhmission)	Date 10/14/2	2015			
		OR FEDERAL OR STATE		£		
			APP	ROVED		
Approved By	'	Title	PETROLE	IIM ENGINEER	Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in th			1 0 2015		
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a tatements or representations as	crime for any person knowing y and s to any matter within its jurisdiction	d with the little	III JULIIIII	agency of the United	
	OR-SUBMITTED ** O	PERATOR-SUBMITTED	** OPERATO	O FIELD OFFICE		

Additional data for EC transaction #319809 that would not fit on the form

32. Additional remarks, continued

P&A marker.



3EE 60A

Triste Draw 3 Federal 30-025-34518 EOG Resources, Inc Surface Location: Sec. 3, T. 25S, R. 33E

Conditions of Approval

Notify BLM at 575-393-3612 (Lea County) a minimum of 24 hours prior to commencing work. Some procedures are to be witnessed, which for this case shall

be the tagging of certain Cement Plugs. If there is no response, leave a voice mail with the API#, workover purpose and a call back phone number.

Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Mr. Johnny Chopp <ichopp@blm.gov or 575.234.2227>.

Work to be completed by within ninety (90) days from the approval date.

- 1. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 2. Operator to have H2S monitoring equipment on location.
- 3. Operator is approved to cap the CIBP at 12,851 (Operator Step #1). To achieve this, Operator shall pump a minimum of 25 sacks of Class H Cement. Tag is required at, or above, 12,601 feet to ensure coverage of the Production Casing Shoe.
- 4. **Before Operator Step #2**, Operator shall set a plug to cover top of Wolfcamp formation at 12,418 feet. Perforate at 12,468 and squeeze to 12,243 feet with a minimum of 25 sacks of Class H Cement. Tag is required at 12,243 feet.
- 5. Operator is approved to set a plug to cover the Production Line Stub at 10,709 feet (Operator Step #2). The plug shall cover the interval of 10,759 to 10,549 feet, 50 feet below the stub, and shall be a minimum of 25 sacks of Class H Cement. Tag is required.

- 6. Operator is approved to set a plug as proposed to cover the top of Bone Spring formation and the interval of 9400 to 9200 feet (Operator Step #3).
- 7. Operator is approved to set a plug as proposed to cover the interval of 6700 to 6500 feet (Operator Step #4).
- 8. Operator is approved to cut 5 1/2 inch casing at 5100 feet (**Operator Step #5**). As well as to set a plug as proposed in the interval of 5200 to 4900 feet (**Operator Step #6**) to cover the Production Casing Stub, the top of Delaware formation, the Intermediate Casing Shoe and the bottom of the salt. Tag is required.
- 9. Operator is approved to set a plug to cover the top of salt at 1600 feet (**Operator Step** #7). The plug shall cover the interval of 1900 to 1550 feet, 50 feet above the salt and be a minimum of 25 sacks of cement. Tag is required.
- 10. Operator is approved to set a plug to cover the Surface Casing Shoe at 643 feet (**Operator Step #8**). The plug shall cover the interval of 700 to 590 feet, at least 50 feet above the shoe and be a minimum of 25 sacks of cement. Tag is required.
- 11. Operator is approved to set surface plug, but shall set the bottom of the plug at a minimum of 60 feet. As well as ensure cement is in all annuluses and set the surface marker (Operator Steps #9 and #10).
- 12. Surface disturbance beyond the originally approved pad must have prior approval.
- 13. Closed loop system required.
- 14. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be onlocation during fracturing operations or any other crew-intensive operations.
- 15. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.
- 16. See attached for the general guidelines to permanently abandon Federal Wells and reclamation procedure.

KGR 12092015

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25

sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

9.. Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken: From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston Environmental Protection Specialist 575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Dara Glass Environmental Protection Specialist 575-234-5924

Shelly Tucker Environmental Protection Specialist 575-234-5979