Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103	
Office District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-29865	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	5. Indicate Type of Lease	
District IV - (505) 476-3460	Santa Fe, NM 87505	STATE x FEE	
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
		SWD#1572	
SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	AIRPATH AEM STATE	
PROPOSALS.)	CATION FOR FERMIT (FORM C-101) FOR SOCI	8. Well Number 1	
1. Type of Well: Oil Well	Gas Well x Other		
2. Name of Operator		9. OGRID Number	
Burns Xpress, LLC 3. Address of Operator		37/003 10. Pool name or Wildcat	
PO Box 1244 Lovington NM 88	260	Wildcat	
4. Well Location			
Unit Letter P	660 feet from the S line	and 660 feet from the	
E line			
Section 8	Township 18S Range 30	5E NMPM Lea County	
	11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)	
	3838' GR	the state of the second st	
12. Check	Appropriate Box to Indicate Nature of Notic	e, Report or Other Data	
NOTICE OF I	NTENTION TO: SU	JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK			
TEMPORARILY ABANDON	CHANGE PLANS	RILLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	ENT JOB	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM		D ×	
	pleted operations. (Clearly state all pertinent details,		
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple (Completions: Attach wellbore diagram of	
proposed completion or re	completion.		
See Attached:	Ô	\bigcirc	
Chance	of experator from L	YXY Pet. Consultants	
		-180	
t. R	word Xpress, LLC.		
Spud Date:	Rig Release Date:		
I hereby certify that the information	above is true and complete to the best of my knowle	edge and belief.	
XX			
SIGNATURE	>> TITLE Manager Mac	DATE11-20-15	
SIGNATURE OF M		DIIID_III 20 10	
Type or print nameKenyon BurnsE-mail address: kenyonburns1@gmail.com PHONE: 575-973-4850			
For State Use Only	1	· · · · / /	
APPROVED BY: TITLE Petroleum Engineer DATE 01/04/2016			
Conditions of Approval (if any):			

JAN 0 4 2016

Airpath AEM State No. 1 **Re-Entry & Completion Procedure**

API No.: 30-025-29865

Location: 660' FSL & 660' FEL Section 8, T-18S, R-36E

Lea County, New Mexico

Elevation: 3838' GL KB: +15' **TD:** 13,004'

PBTD: (P&A)

Casing & Cement:

13-3/8", 54.5#/ft., J-55, ST&C @ 425' cmt. w/425 sx. circulated

8-5/8", 32#/ft., K-55, ST&C @ 3805' cmt. w/1500 sx. circulated

Tubing:

None

Cement Plugs:

Surface, 2000'-2100', 3750'-3850', 5150'-5250', 6860'-6960', 10100'-10200', 11425'-11525', and 12744'-12844'

Procedure:

- 1. Clean off location, remove P&A marker, and dig out cellar.
- 2. Rebuild wellhead to leave a 9" x 5M casing flange looking up.
- 3. MIRU drilling rig or workover rig. NU double ram 5,000 psi working pressure BOP stack with 3000 psi rated annular preventer.
- 4. PU 7-7/8" mill tooth bit, DCs, and 3-1/2" drill pipe. Drill out plugs inside casing to 3800'. Test casing to 1500 psig and BOP stack with test plug to 5000 psig.
- 5. Drill cement plugs circulating and conditioning mud system between plugs. Mud properties to be adjusted to conform to the attached Nova Mud recommendations prior to reaching the Wolfcamp formation.
- 6. Circulate and condition hole at TD. Short trip to confirm hole condition.
- 7. POOH laying down drill pipe, DCs, and bit. PU and run 12,875' of 5-1/2", 17#/ft., N-80 casing. Land casing in full tension.
- 8. Cement w/1000 sx. per attached Baker Hughes procedure.
- 9. WOC. ND BOP stack. NU wellhead. RDMO drilling equipment.
- 10. MIRU completion unit. NU hydraulic BOP.
- 11. PU 4-3/4" bit, 6-3-1/2" DCs and 2-7/8" tubing
- 12. RU reverse unit. TIH to float collar.
- 13. Drill out float collar, cement float shoe and open hole to original TD of 13,004'.
- 14. Circulate hole with clean 2% KCL based packer fluid. POOH laying down workstring, DCs, and bit.
- 15. PU AS1X-10K nickel plated packer or equivalent with accessories as follows:

Profile nipple

6' tailpipe

Packer


Profile nipple


On/Off Tool


Plastic coated production tubing.

16. Set packer at +/- 12,800'.

- 17. ND BOP. NU wellhead.
- 18. Establish injection rate and acidize if necessary with 5000 gallons 15% HCL-NE-FE acid.
- 19. RDMO completion equipment and place well on injection







STATE OF NEW	the second s		
ENERGY AND MINERALS		SERVATION DIVISION	
	UIL CONS		Form C-103 .
DISTRIBUTION		P. O. BOX 2088	Revised 10-1-73
FILE	SANTAF	E. NEW MEXICO 87501	
V.3.0.5.			Sa. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil 6 Gas Lease No. LG 1910
	SUNDRY NOTICES AND REPO	ORTS ON WELLS	
1.	APPLICATION FOR PERMIT - " IFORM C-1	OTI FOR SUCH PROPOSALS.	7. Unit Agreement Name
	P&A		
2. Name of Operator			8. Farm or Lease Name
Yates Petr	oleum Corporation		Airpath AEM State
J. Address of Operator			9, Well No.
105 South	4th St., Artesia, NM 8821	0	1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER P	660 FEET FROM THE	South LINE AND 660 PEET FROM	Wildcat
THE LAST	LINE, SECTION TOWNSHIP		
mmmmm		Late DE PT CP as 1	01111111111111111111111
		ow whether DF, RT, GR, etc.) 3838' GR	12. County
11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1	mmmm	and the second	Lea
		dicate Nature of Notice, Report or Oth	
NOT	ICE OF INTENTION TO:	SUBSEQUENT	REPORT OF:
	7		
PERFORM REMEDIAL WORK	PLUG AND AB		ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLAN	COMMERCE DRILLING OPHS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING	CHANGE PLAN	CASING TEST AND CEMENT JON	*** **** · · · ·
		AT	
OTHER		- П	
	-	<u> </u>	0
17. Describe Proposed or (ertinent details, and give pertinent dates, including	estimated date of starting any proposed
		<u> </u>	estimated date of starting any proposed
17. Describe Proposed or (ertinent details, and give pertinent dates, including	estimated date of starting any proposed
17. Describe Proposed or (work) SEE RULE 1 for	Plugged well as follows	ertinent details, and give pertinent dates, including	
17. Describe Proposed or o work) see Rule 1703 TD 13004'. Plug #1	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87.	crtinent details, and give pertinent dates, including : Class "H" with .3% WR-2 retort	er.
17. Describe Proposed or (work) SEE RULE 1703 TD 13004'.	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks	ertinent details, and give pertinent dates, including	er.
TD 13004'. Plug #1 Plug #2	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87.	ertinent details, and give pertinent dates, including : Class "H" with .3% WR-2 retort s Class "H" with .3% WR-2 retor	er. ter.
17. Describe Proposed or o work) see Rule 1703 TD 13004'. Plug #1	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks	crtinent details, and give pertinent dates, including : Class "H" with .3% WR-2 retort	er. ter.
17. Describe Proposed of G work) see RULE 1703 TD 13004'. Plug #1 Plug #2 Plug #3	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87.	creation of the state of the st	er. ter.
TD 13004'. Plug #1 Plug #2	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CD	creation of the state of the st	er. ter.
17. Describe Proposed of G work) SEE RULE (for Plug #1 Plug #2 Plug #3 Plug #4	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87.	creation of the set of	er. ter.
17. Describe Proposed of G work) see RULE 1703 TD 13004'. Plug #1 Plug #2 Plug #3	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CD	creation of the set of	er. ter.
17. Describe Proposed of G work) SEE RULE (for Plug #1 Plug #2 Plug #3 Plug #4	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87.	entiment details, and give pertiment dates, including Class "H" with .3% WR-2 retort s Class "H" with .3% WR-2 retor Class "H" with .3% WR-2 retort lass "H" neat. lass "H" neat.	er. ter.
17. Describe Proposed of G work) see Rule 1703 TD 13004'. Plug #1 Plug #2 Plug #3 Plug #4 Plug #5	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI	entiment details, and give pertiment dates, including Class "H" with .3% WR-2 retort s Class "H" with .3% WR-2 retor Class "H" with .3% WR-2 retort lass "H" neat. lass "H" neat.	er. ter.
17. Describe Proposed of G work) see Rule 1703 TD 13004'. Plug #1 Plug #2 Plug #3 Plug #4 Plug #5	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI	entiment details, and give pertiment dates, including Class "H" with .3% WR-2 retort s Class "H" with .3% WR-2 retor Class "H" with .3% WR-2 retort lass "H" neat. lass "H" neat. lass "H" neat.	er. ter.
17. Describe Proposed of G work) see Rule ifor TD 13004'. Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87.	entiment details, and give pertiment dates, including Class "H" with .3% WR-2 retort s Class "H" with .3% WR-2 retort Class "H" with .3% WR-2 retort lass "H" neat. lass "H" neat. lass "H" neat. lass "H" neat.	er. ter.
17. Describe Proposed of G work) see Rule ifor TD 13004'. Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks	entiment details, and give pertiment dates, including Class "H" with .3% WR-2 retort s Class "H" with .3% WR-2 retort Class "H" with .3% WR-2 retort lass "H" neat. lass "H" neat. lass "H" neat. lass "H" neat.	er. ter.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87.	creation of the set of	er. ter.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. ion and install dry hole	creation of the set of	er. er.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100 and install dry hole dission given by Jerry Sex	creation of the second	er. er.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. ion and install dry hole	creation of the second	er. er.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100 and install dry hole bission given by Jerry Sex Information above is true and complete to	creation of the base of my knowledge and belief.	er. er. 4-25-87.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100 and install dry hole dission given by Jerry Sex	creation of the second	er. er.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100 and install dry hole bission given by Jerry Sex Information above is true and complete to	creation of the base of my knowledge and belief.	er. er. 4-25-87.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100 and install dry hole bission given by Jerry Sex Information above is true and complete to	creation of the base of my knowledge and belief.	er. er. 4-25-87.
17. Describe Proposed of G work) see Rule (for Plug #1 Plug #2 Plug #3 Plug #4 Plug #5 Plug #6 Plug #7 Plug #8 Clean locat Verbal perm	Plugged well as follows 12844-12744' w/40 sacks PD 9:05 AM 4-27-87. 11525-11425' w/120 sacks PD 10:32 AM 4-27-87. 10200-10100' w/40 sacks PD 11:54 AM 4-27-87. 6960-6860' w/40 sacks CI PD 2:18 PM 4-27-87. 5250-5150' w/50 sacks CI PD 4:40 PM 4-27-87. 3850-3750' w/45 sacks CI PD 5:38 PM 4-27-87. 2100-2000' w/35 sacks CI PD 6:38 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100'-surface w/30 sacks PD 7:40 PM 4-27-87. 100 and install dry hole da bo diet to add bo	creation of the base of my knowledge and belief.	er. er. 4-25-87.

Kautz, Paul, EMNRD

From:	Debbie McKelvey <debmckelvey@earthlink.net></debmckelvey@earthlink.net>
Sent:	Monday, January 04, 2016 10:01 AM
To:	Kautz, Paul, EMNRD
Cc:	Kenyon Burns
Subject:	Airpath AEM State #1 30-025-29865 - Change of Operator

Good morning Paul and Happy New Year!

I received approval from Larry Scott to transfer the referenced well from Lynx Petroleum to Burns Express. If you need anything else to approve the Change of Operator, please do not hesitate to call or email me.

Thank you.

Debbie McKelvey

McKelvey Oil Reports, LLC

&

Oil Patch Accounting, LLC

(575) 392-3575

debmckelvey@earthlink.net