Office	of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Mineral 1625 N. French Dr., Hobbs, NM 88240	Is and Natural Resources WELL AP	Revised August 1, 2011 I NO.
District II - (575) 748-1283	EVATION DIVISION 30-025-29	757 🗸
District III - (505) 334-6178 1220 Sou	th Ct Francis De 3. Indicate	Type of Lease
1000 Die Dennes Dd. Antes NIM 97410	517	il & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		14.1
SUNDRY NOTICES AND REPORTS ( (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO	EEPEN OR PLUG BACK TO A South Hob	Name or Unit Agreement Name bs (G/SA) Unit
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other: 1	Injector 8. Well N	umber: 219
2. Name of Operator		Number: 157984
Occidental Permian Ltd.		W"11 - 11 11 (O/OA)
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	RECEIVEDO. Pool n	ame or Wildcat Hobbs (G/SA)
4. Well Location		
	North line and787feet from the	West line
Section 3 Township	19S Range 38E N	MPM Lea County
	whether DR, RKB, RT, GR, etc.)	
3646' KB		
12. Check Appropriate Box to	Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☑ PLUG AND ABANDO		T REPORT OF:  ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPN	
PULL OR ALTER CASING   MULTIPLE COMPL	☐ CASING/CEMENT JOB	
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
	rly state all pertinent details, and give pertine	
of starting any proposed work). SEE RULE 19.15.	rly state all pertinent details, and give pertine	
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A	attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A  During this procedure	attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A  During this procedure top perf @ the closed-loop syste	e we plan to use m with a steel
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156')	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A  During this procedure the closed-loop syste tank and haul conten	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130'	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A  During this procedure top perf @ the closed-loop syste	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156')	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A  During this procedure the closed-loop syste tank and haul conten	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection.	The state all pertinent details, and give pertine.  7.14 NMAC. For Multiple Completions: A puring this procedure top perf @ the closed-loop systetank and haul contendisposal per ODC. Rule of the closed per ODC.	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection.	rly state all pertinent details, and give pertine. 7.14 NMAC. For Multiple Completions: A  During this procedure the closed-loop syste tank and haul conten	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi	The state all pertinent details, and give pertine.  7.14 NMAC. For Multiple Completions: A puring this procedure top perf @ the closed-loop systetank and haul contendisposal per ODC. Rule of the closed per ODC.	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. 9. 10. OCD 1	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify  Hobbs office 24 hours	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (4156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. 9. 10. Conditi	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi 9. 10. OCD I	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  top of Approval: notify  Hobbs office 24 hours  Inning MIT Test & Chart	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi 9. 10. OCD I Spud Date: Rig	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi 9. 10. OCD I	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:	we plan to use m with a steel ts to the required
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:  lete to the best of my knowledge and belief.	e we plan to use m with a steel ts to the required ale 19.15.17
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:	e we plan to use m with a steel ts to the required ale 19.15.17
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi 9. 10. OCD I Spud Date: Rig	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  on of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:  lete to the best of my knowledge and belief.	e we plan to use m with a steel ts to the required ale 19.15.17
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi 9. 10. OCD I Spud Date: Rig	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  top of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:  DATE 03/15/16  PHONE:	e we plan to use m with a steel ts to the required ale 19.15.17
of starting any proposed work). SEE RULE 19.15. proposed completion or recompletion.  1. MIRU Pulling Unit 2. POOH with injection assembly 3. Set CIBP above current open pay to shutoff injection (14156') 4. Selectively perforate interval 4106'-4130' 5. RIH with injection equipment — CHACT TEST 6. Return well to injection. 7. 8. Conditi 9. 10. OCD I  Spud Date: Rig	During this procedure top perf @ the closed-loop syste tank and haul conten disposal per ODC Ru  top of Approval: notify Hobbs office 24 hours Inning MIT Test & Chart g Release Date:  DATE 03/15/16  PHONE:	e we plan to use m with a steel ts to the required ale 19.15.17