Form 3160-5 (September 2001)

SUNDRY

UNITED STATES Hobbs

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0135 Expires: January 31, 2004

	Expires. saridar
5.	Lease Serial No.
	NM-82026

NOTICES AND REPORTS ON WELLS	14141-02020
is form for proposals to drill or to re-enter an	If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well Oil Well	Gas Well Other		1 8 2016	8. Well Nam	ne and No. / TL . 411115			
2. Name of Operator Ridgeway Ar	izona Oil Corp	RE	CEIVED	9. API Wel	INo.			
3a Address 777 N. Eldridge Pkwy #150 Ho	uston, TX 77079	3b. Phone No. (include 832-485-8500	e area code)	10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., 660 FSL & 1980 FEL Section 24, T-07S, R-33E	T., R., M., or Survey Description)		11. County or	r Parish, State It County, NM			
12. CHECK AF	PROPRIATE BOX(ES) T	O INDICATE NATUR	RE OF NOTICE, R	EPORT, OR	OTHER DATA			
TYPE OF SUBMISSION		TYI	PE OF ACTION		D.A /			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily At Water Disposal		INT TO PA WVV P&A NR P&A R			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Proposed plugging procedure is attached

Federal A3 was plugged. Junday needs to be submitted for Federal A3 (30-041-20154) with P-BA dates. with notes on why it was late.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

								1			
I hereby certify that the foregoing is true and correct Name (Printed/Typed)	l			1	/			//		/	-//
Jamie L Hogue	Title	VP Regulatory Affai	irs	R	gent in			1-			//
Signature and hogo	Date		02	/09/2	016	111	1	<u>LU</u>	/	1	
THIS SPACE FOR FEDERAL	OR :	STATE OFFICI	EL	JS	140			/		1/2	_ //
Approved by		Title			AH	Date	18	016/	W	// 1	VV
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject least which would entitle the applicant to conduct operations thereon.	Office	VR.	AU	OF LSB/	LAND AD FIE	V	HA THE OFFICE	NT			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person within	knowingly and willfull its jurisdiction.	ly to	mak	e to	any de _l	partm	ent or agen	cy of th	Unite	d

(Instructions on page 2)

MW/OCD 03/21/2016

ON



Remediate Location

HOBBS OCD

MAR 1 8 2016

RECEIVED

Plugging Procedure Federal "A" #6 API No. – 30-041-20107

1.	Prepare location and test anchors
2.	MIRU plugging rig
3.	Notify OCD/BLM 24 hours prior to commencement of P & A procedure.
4.	NDWH/NU BOP 4122 toy
5.	Prepare location and test anchors MIRU plugging rig Notify OCD/BLM 24 hours prior to commencement of P & A procedure. NDWH/NU BOP RIH w-4 ½ CIBP on 2 3/8 WS @ 4100′ (+/-) – within 100′ of top perf – 4100′ a. Spot 35′ of cement on CIBP b. WOC – bump plug @ 4065′ (+/-) Load well with a minimum of P lb. mud and conduct MIT to 500 pci. test for lock off
	a. Spot 35' of cement on CIBP
	b. WOC - bump plug @ 4065' (+/-)
6.	Load well with a minimum of 9 lb. mud and conduct MIT to 500 psi., test for leak off.
	a. Bleed pressure off after MIT.
7.	MIRU WL and RIH w/perf gun to 3065'
	a. perforate @ 2 JSPF
	b. POOH w/WL
	c. RDWL 3100
8.	TIH w/WS - Squeeze 40 SX cement plug @-3065' to 2965' (+/- a. Wait on cement b. Tag plug @ 2965' or above. Plus must be a minimum of 130' (Plus must be a minimum of 130' (
	a. Wait on cement Dlug must be a minimum of 100 (
	b. Tag plug @ 2965' or above.
9.	MIRITWI and RIH w/nerf gun to 2065'
	a. perforate @ 2 JSPF
	a. perforate @ 2 JSPF b. POOH W/WL c. RDWL 2360 (to seal Yates Firmation)
	c. RDWL 2340
10.	TIH w/WS – Squeeze 40 SX cement plug @ 2065' to 1965'
	a. Wait on cement
	b. Tag plug @ 1965' or above
11.	MIRU WL and RIH w/perf gun to 1925'
	a. perforate @ 2 JSPF
	b. POOH w/WL
	c. RDWL
12.	TIH w/WS – Squeeze 60 SX cement plug @ 1025' to 925'
	a. Wait on cement
	b. Tag plug @ 925' or above
13.	MIRU WL and RIH w/perf gun to 400'
	a. perforate @ 2 JSPF
	b. 85/8 Surface Casing Shoe @ 366', TAG Minimum 5 312.
	c. POOH W/WL 412-312
	d. Squeeze 60 SX cement from 400" to 300" (+/-)
14.	a. perforate @ 2 JSPF b. 8 5/8 Surface Casing Shoe @ 366' c. POOH w/WL d. Squeeze 60 SX cement from 400" to 300" (+/-) MIRU WL and RIH w/perf gun to 60' a. perforate @ 2 JSPF b. 85/8 Surface Casing Shoe @ 366' TAG Mirimum of 312. The state of t
	a. perforate @ 2 JSPF
	b. POOH w/WL
	c. RDWL
15.	TIH w/WS – Circulate cement plug from 60' to surface
	a. Wait on cement
	b. Cut off well head
16.	RDMO Plugging Rig
	a. Install P & A marker plate
	b. Cut off dead men

Co. Rep	NM-82026	
Well Name	Federal A	Well No. 2
Field	Chaveroo	
County	Roosevelt	
State	NM	
Date	2/9/2016	
Date Comp		
KB	0.00	

Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	8 5/8	0	24	362	250	Surface
Inter Csg	0	0	0	0	0	0
Prod Csg	4 1/2	0	9 1/2	4422	150	Unknow
Liner O.D.	0	0	0	0	0	0

Comp	0.00			Liner O.D.	0	0	0	0	0	0			
			Lease NM- Well Test Data Unit Name & Size Perforations TBG Data	BOPD	Well#	% Fi	eld CF	Cha	veroo		Perf @ 60' Sqz to Surface		
			Strokes Per. Min. Tension	Rods String od Grade SON FOR FAILU	Actual RES & MEA	Load	Seat Nipp Tap	er 2 er 4	⊺ SAID		366' Perf @ 400' Sqz 60 SX	2'-3 2'	
											Perf @ 1025' Sqz 40 SX		
			LIST ANY RECOM	MENDATIONS TO	O PREVENT	FUTURE LL CONTR	FAILURES	OR ANY	r ES.		2340 Perf @ 200 5' Sqz 40 SX	,	
		Perí	forations								Perf @ 3065'		
			0-4378' 1 SPF FD @ 4378' 4 4410	3 <u>8</u> 5 ETD	@	0				4	35' Cmt. Plug Cibp @ 4400		4065'

HOBBS OCD

Federal A 1 30-041-20107 Ridgeway Arizona Oil Corp March 02, 2016 Conditions of Approval

MAR 1 8 2016

RECEIVED

- 1. Operator shall place CIBP at 4,072' (50'-100' above top most perf) and place 35' of Class C cement on top as proposed. WOC and TAG.
- 2. Operator shall place a balanced Class C cement plug from 3,100'-2,965' as proposed. WOC and TAG.
- 3. Operator shall place a balanced Class C cement plug from 5,950'-5,800'. WOC and TAG.
- 4. Operator shall place a balanced Class C cement plug from 2,360'-1,965'to seal the Yates formation. WOC and TAG required.
- 5. Operator shall place a balanced Class C cement plug from 1,025'-925' as proposed. WOC and TAG.
- 6. Operator shall place a balanced Class C plug from 412'-312' to seal the 13-3/8'' shoe. WOC and TAG.
- 7. Operator shall place a balanced Class C cement plug from 60'- surface as proposed
- 8. See Attached for general plugging stipulations.

JAM 030216

HOBBS OCD

BUREAU OF LAND MANAGEMENT
Roswell Field Office
2909 West Second Street

MAR 1 8 2016
RECEIVED

Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office (RFO), prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. Monument: Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. Timing Limitation Lease Stipulation / Condition of Approval For Lesser Prairie-Chicken: Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1 through June 15 annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, geophysical exploration other than 3-D seismic operations, and pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.
- 8. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.