State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

David Catanach, Director
Oil Conservation Division

Brett F. Woods, Ph.D.

Deputy Cabinet Secretary



Response Required - Deadline Enclosed

Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"

26-Apr-16

BURGUNDY OIL & GAS OF N M INC

401 W TEXAS STE 1003 MIDLAND TX 79701-

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

Test Date:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

SKAGGS GRAYBURG UNIT No.001

30-025-06067-00-00

Active Injection - (All Types)
4/26/2016 Permitted Injection PSI: Actual PSI:

Test Reason: Annual IMIT Test Result: F Repair Due: 7/30/2016

Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:

Comments on MIT: Failure, water is coming out of surface valve at a steady / continuous stream. Pumper shut in well. Rule

19.15.26.11

EUNICE MONUMENT UNIT No.030 30-025-06167-00-00

Active Injection - (All Types)

O-19-20S-37E

K-12-20S-37E

Test Date: 4/25/2016 Permitted Injection PSI: Actual PSI:

Test Reason: 5-year Test Test Result: F Repair Due: 7/29/2016

Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:

Comments on MIT: Failure, attempted to pressure up backside when fluid started spewing out of surface valve. Well was shut in

by pumper upon failure. Rule 19.15.26.11

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.



Burgundy O & G of NM, Inc. 401 W. Texas, Ste 1003 Midland, TX 79701

- 18