Submit 1 Copy To Appropriate District Office District I – (575) 393-6161	K AMENDED State of New Mexico Energy, Minerals and Natural Resources	Form C-102 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	009	WELL API NO. 30- 025-27796
$\frac{District II - (575) 748-1283}{811 \text{ S. First St., Artesia, NM 88210}} OIL CONSERVATION DIVISION$ $\frac{District III - (505) 334-6178}{122016} 01 2016 1220 \text{ South St. Francis Dr.}$		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NMEE 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATIO PROPOSALS.)	TO DRILL OR TO DEEPEN OR PLUG BACK TO A ON FOR PERMIT" (FORM C-101) FOR SUCH	J. SPEIGHT
1. Type of Well: Oil Well Gas	Well Other	8. Well Number 1
2. Name of Operator	incis Oil Company	9. OGRID Number 012361
3. Address of Operator P.O. Box 21468, Tulsa, OK 74121-1468		10. Pool name or Wildcat House Yates Seven Rivers
4 Well Location	60 feet from the South line and	660 feet from the East line
Section 31	Township 19S Range 39E	NMPM Lea County
11	. Elevation (Show whether DR, RKB, RT, GR, et 3587' GR	
	5567 GI	
OTHER: 13. Describe proposed or completed	operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated da
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>D(LCIPD and THL w(tubin)</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>P(LCIPP and THL w(tubin)</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>D(LCIPD and THL w(tubin)</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>D(LCIPD and THL w(tubin)</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>P/LCIPD and THL w(tubin)</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG ng. Set CIBP @ 2970'. Spot 25 sxs Class "C" o brine-based plugging mud w/ 25 sx gel/100 770'-1650'. WOC and tag. 50'-surface.	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark I</li> <li>Remediate location. WBD a</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recompl Kaiser-Francis Oil Company reques</li> <li>MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark I</li> <li>Remediate location. WBD a</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG ag. Set CIBP @ 2970'. Spot 25 sxs Class "C" o brine-based plugging mud w/ 25 sx gel/100 770'-1650'. WOC and tag. 50'-surface. location w/ 4' marker as per NM requirement attached.	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recomplexaiser-Francis Oil Company request. MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark 1</li> <li>Remediate location. WBD a</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG ag. Set CIBP @ 2970'. Spot 25 sxs Class "C" o brine-based plugging mud w/ 25 sx gel/100 770'-1650'. WOC and tag. 50'-surface. location w/ 4' marker as per NM requirement attached. Rig Release Date:	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce cmt on top of plug @ 2970'. bbls. Test csg to 500#. Well will & Approved Mell & Approved Mell will & Approved Mell & Approv
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recomplexaiser-Francis Oil Company request. MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark 1</li> <li>Remediate location. WBD a</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG ag. Set CIBP @ 2970'. Spot 25 sxs Class "C" o brine-based plugging mud w/ 25 sx gel/100 770'-1650'. WOC and tag. 50'-surface. location w/ 4' marker as per NM requirement attached. Rig Release Date:	Completions: Attach wellbore diagram of GF-SUN #1 according to the following proce cmt on top of plug @ 2970'. bbls. Test csg to 500#. Well & 10 & 2016. Well & 10 & 2016. Mell & 20
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recomplexaiser-Francis Oil Company requests</li> <li>MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark 1</li> <li>Remediate location. WBD a</li> <li>Spud Date:</li> </ol>	I operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple Cletion.         Ists permisstion to plug and abandon the MG         ing. Set CIBP @ 2970'. Spot 25 sxs Class "C" of brine-based plugging mud w/ 25 sx gel/100         770'-1650'. WOC and tag.         50'-surface.         location w/ 4' marker as per NM requirement         attached.         Rig Release Date:         re is true and complete to the best of my knowled         TITLE         Regulatory Compli	Completions: Attach wellbore diagram of GF-SUN #1 according to the following process cmt on top of plug @ 2970'. bbls. Test csg to 500#. Well will 32 Approved Mell 32 Approv
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recomplexaiser-Francis Oil Company request. MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark 1</li> <li>Remediate location. WBD a</li> </ol>	l operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple C letion. sts permisstion to plug and abandon the MG ag. Set CIBP @ 2970'. Spot 25 sxs Class "C" o brine-based plugging mud w/ 25 sx gel/100 770'-1650'. WOC and tag. 50'-surface. location w/ 4' marker as per NM requirement attached. Rig Release Date:	Completions: Attach wellbore diagram of GF-SUN #1 according to the following process cmt on top of plug @ 2970'. bbls. Test csg to 500#. Well will 32 Approved Mell 32 Approv
<ol> <li>Describe proposed or completed of starting any proposed work). proposed completion or recomplexaiser-Francis Oil Company requests</li> <li>MIRU WOR.</li> <li>P/U CIBP and TIH w/tubin</li> <li>Circ hole w/ approved 9.5#</li> <li>Spot 25 sx cmt plug from 17</li> <li>Mix and pump cmt plug from</li> <li>Cut off wellhead and mark 17</li> <li>Remediate location. WBD a</li> <li>Spud Date:</li> </ol>	I operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple Cleation.         Stee RULE 19.15.7.14 NMAC. For Multiple Cleation.         Ists permisstion to plug and abandon the MG         ag. Set CIBP @ 2970'. Spot 25 sxs Class "C" of brine-based plugging mud w/ 25 sx gel/100         770'-1650'. WOC and tag.         50'-surface.         location w/ 4' marker as per NM requirement attached.         Rig Release Date:         re is true and complete to the best of my knowled to the best of my knowl	Completions: Attach wellbore diagram of GF-SUN #1 according to the following process cmt on top of plug @ 2970'. bbls. Test csg to 500#. Well & 100 approved the provide of the provide the provide of the provide of the provide the provide of the p