

30-025-40459



Internal Incident Report – Spill/Release

HOBBS OCD

JUN 14 2012

RECEIVED

Location: Hawk Federal A-5 #9

Production Area: Eunice North

District: New Mexico

Date: 06/13/12

Time: 1:52pm

One Line Summary: Valve malfunction on suction tank.

Full summary: While pumping a sweep the hand misaligned a valve on the suction tank and overfilled the suction tank. 5bbls of brine was released with recovering 3bbls. The initial assessment will be completed when the drilling rig moves off of this location.

Root cause of incident: Contractor error

Corrective Actions:

- 1. Make sure that valve are aligned and installed properly before starting work.**
- 2. Check valves continually during the work day.**

Reported by: Natalie Gladden



HOBBS OCD

JUN 14 2012

RECEIVED