Submit 1 Copies To Appropriate District State of New Me	Exico Form C-103
Office Energy, Minerals and Natu	ral Resources Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 S OCD	WELL API NO. 30-025-33576
	5 Indicate True of Lease
1000 Rio Brazos Rd., Aztec, NML87440 0 2010 Sonto Fe NIM 97	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 001
2. Name of Operator	9. OGRID Number 256073
JR Oil. Ltd. Co.	
3. Address of Operator P.O. Box 2975, Hobbs, NM 88241	10, Pool name or Wildcat Reeves, Queen, West (Gas)
4. Well Location	
Unit Letter <u>N</u> :660 feet from the <u>South</u> line and <u>19</u>	80 feet from the <u>West</u> line
	Range 35E NMPM Lea, County
11. Elevation (Show whether DR, 3946 [*]	
12. Check Appropriate Box to Indicate Natu	re of Notice, Report or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL	SUBSEQUENT RI REMEDIAL WORK COMMENCE DRILLING OPNS. CASING/CEMENT JOB BAR
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all p	Table 6 V 2 mar 2 (2)
of starting any proposed work). SEE RULE 19.15.714 NMAC proposed completion or recompletion.	
SEE ATTACHED PLUG AND ABANDON PROCEDURE AND SC	HEMATIC.
NOTIFY OCD 24 HOU PLUGGING OPERAT	IRS PRIOR TO BEGINNING
I hereby certify that the information above is true and complete to the be	st of my knowledge and belief.
SIGNATURE Diblie MKilvey_TITLE_	AGENT DATE <u>9/22/16</u>
	nckelvey@earthlin.net Telephone No. 505-392-3575
For State Use Only	Dur en alada
APPROVED BY: Man Title Te Conditions of Approval (if any):	Holeum Engr. Specialist DATE 9/27/2016

JR Oil Ltd OGRID # 256073

Plugging procedure on SV 17 State #1

1: MIRU Lay down prod equip, pk up work string, TIH w/ bit and scraper to 4400'

2: TOH, GIH w/ WL CIBP set at 4350' dump 35' cmt, GIH w/ WL CIBP set at 3350'

3: TIH w/ WS load csg w/ 9# mud , spot 50 sxs cmt on CIBP to bring TOC to +- 2850

4: Pull up and spot 25 sxs cmt at 1880', to bring TOC to +- 1630'

5: Pull up and spot 30 sxs cmt at 300' to bring cmt to surface. Cut off WH and set DH marker.

JR Oil Ltd- OGRID#256073

SV 17 State #1 API 30-025-33576

UL-N, S-17, T18S, R35E Proposed PA Schematic

Proposed P&A

