Submit I Copy To Appropriate District Oppose State of New Mexico	Form C-103
Office Energy Minerals and Natural Resources	Revised August 1, 2011
District [ - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283	30-025-28268
District II - (575) 748-1283 811 S. First St., Artesia, NM 88240 District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE S FEE
District IV - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	North Hobbs (G/SA) Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Injector (WAG)	8. Well Number 422
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd. 3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	TO. TOOT Marke OF WINCAR THOODS (CHOR)
4. Well Location	
Unit Letter H: 2181 feet from the North line and 498	_feet from theEastline
Section 33 Township 18S Range 381	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3647.5 (KB)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
	IT JOB
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>1. MIRU PU. ND tree. NU BOP</li> </ul>	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>1. MIRU PU. ND tree. NU BOP</li> <li>2. Test backside – POOH w/ inj. equipment</li> <li>3. RIH w/ bit and drill out to TD @4476' Condi</li> </ul>	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.</li> <li>1. MIRU PU. ND tree. NU BOP</li> <li>2. Test backside – POOH w/ inj. equipment</li> <li>3. RIH w/ bit and drill out to TD @4476'</li> <li>4. Perf 4144-4429' (4 spf) gross interval per prog</li> </ul>	tion of Approval: notify
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog OCD	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog OCD	tion of Approval: notify
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH Anstall inj. equip and return well to inj	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH Anstall inj. equip and return well to inj	tion of Approval: notify Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.         1. MIRU PU. ND tree. NU BOP         2. Test backside – POOH w/ inj. equipment         3. RIH w/ bit and drill out to TD @4476'         4. Perf 4144-4429' (4 spf) gross interval per prog         5. Acidize with 7000 gal 15% PAD +4800 # RS per prog         6. Upgrade WH         7. Install inj. equip and return well to inj         Rig Release Date:	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. ND tree. NU BOP Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476' Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH Anstall inj. equip and return well to inj	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.         1. MIRU PU. ND tree. NU BOP         2. Test backside – POOH w/ inj. equipment         3. RIH w/ bit and drill out to TD @4476'         4. Perf 4144-4429' (4 spf) gross interval per prog         5. Acidize with 7000 gal 15% PAD +4800 # RS per prog         6. Upgrade WH         7. Install inj. equip and return well to inj         Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled,	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.         1. MIRU PU. ND tree. NU BOP         2. Test backside – POOH w/ inj. equipment         3. RIH w/ bit and drill out to TD @4476'         4. Perf 4144-4429' (4 spf) gross interval per prog         5. Acidize with 7000 gal 15% PAD +4800 # RS per prog         6. Upgrade WH         7. Install inj. equip and return well to inj         Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled,	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.  1. MIRU PU. ND tree. NU BOP 2. Test backside – POOH w/ inj. equipment 3. RIH w/ bit and drill out to TD @4476' 4. Perf 4144-4429' (4 spl) gross interval per prog 5. Acidize with 7000 gal 15% PAD +4800 # RS per prog 6. Upgrade WH 7. Install inj. equip and return well to inj  Spud Date:  I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE  Sign	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.         1. MIRU PU. ND tree. NU BOP         2. Test backside – POOH w/ inj. equipment         3. RIH w/ bit and drill out to TD @4476'         4. Perf 4144-4429' (4 spf) gross interval per prog         5. Acidize with 7000 gal 15% PAD +4800 # RS per prog         6. Upgrade WH         7. Install inj. equip and return well to inj         Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled.	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  I. MIRU PU. ND tree. NU BOP  Test backside – POOH w/ inj. equipment RIH w/ bit and drill out to TD @4476'  A Perf 4144-4429' (4 spf) gross interval per prog Acidize with 7000 gal 15% PAD +4800 # RS per prog Upgrade WH Test Install inj. equip and return well to inj  Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE TTTLE Production Engineer Type or print name Conor McGinnis E-mail address conor mcginnis@oxy. For State Use Only	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief. 
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.  1. MIRU PU. ND tree. NU BOP 2. Test backside – POOH w/ inj. equipment 3. RIH w/ bit and drill out to TD @4476' 4. Perf 4144-4429' (4 spf) gross interval per prog 5. Acidize with 7000 gal 15% PAD +4800 # RS per prog 6. Upgrade WH 7. Install inj. equip and return well to inj  Spud Date:  I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURETTTLE Production EngineerType or print nameConor McGinnis E-mail address conor mcginnis@oxy.	tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart ge and belief.

P