
Form 3160-5 (August 2007)		UNITED STATES	5) Hobbs	FORM APPROVED	
	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS			and the	OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM77063 6. If Indian, Allottee or Tribe Name	
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter appendence abandoned well. Use form 3160-3 (APD) for such proposals.		6. If			
	SUBMIT IN TRI	PLICATE - Other instruc	tions on reverse side OV	7. If	Unit or CA/Agreement, Name and/or	
 Type of Well Oil Well 	Gas Well Oth	er	REC		ell Name and No. ONTINENTAL APJ FEDERAL 3	
2. Name of Operat EOG Y RES	tor OURCES, INC.	Contact: E-Mail: tinah@yate	TINA HUERTA	9. AI	PI Well No. D-025-36049	
3a. Address 105 SOUTH FOURTH STREET ARTESIA, NM 88210			3b. Phone No. (include area code) Ph: 575-748-4168 Fx: 575-748-4585		Field and Pool, or Exploratory	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description			on)		11. County or Parish, and State	
Sec 28 T23S	8 R32E NWNW 66	SOFNL 660FWL	LE		EA COUNTY, NM	
1:	2. CHECK APPF	ROPRIATE BOX(ES) TO	DINDICATE NATURE OF	NOTICE, REPOR	T, OR OTHER DATA	
TYPE OF SU	UBMISSION	TYPE OF ACTION				
Notice of I	ntent	Acidize	Deepen	Production (S	INT TO PA 🐜 🖌	
Notice of In		□ Alter Casing	Fracture Treat	Reclamation	INT TO PA 🍌 🗴	
Subsequent	t Report	Casing Repair	New Construction	Recomplete	P&A R	
Final Abar	donment Notice	Change Plans	Plug and Abandon	Temporarily		
		Convert to Injection	Plug Back	□ Water Dispos		
1. TIH with o plugging mut 2. Set packe Class C cem 3. Tag TOC. C cement plu Bell Canyon, 4. Spot a cor section. 5. Spot a 25	pen ended tubing d. Spot 25 sx Cla r at 5500 ft. Estal ent. Release pac Perforate 5-1/2 i ug from 4850 ft - 4 , 8-5/8 inch casing ntinuous 335 sx C sx Class C cements y that the foregoing is	ss C cement on top of Cl blish rate into casing hole ker. WOC. nch casing at 4850 ft. Se 600 ft inside and outside shoe and DV tool. Rele lass C cement plug from nt plug from 910 ft - 810 ft true and correct. Electronic Submission # For EOG Y Committed to AFMSS for	BP at 6912 ft. Load hole with BP. WOC and tag. es then squeeze with a minim et packer at 4600 ft then spot 5-1/2 inch casing, this will co ase packer. WOC and tag. 4600 ft - 1250 ft, this will cov t. WOC and tag. 357969 verified by the BLM We RESOURCES INC., sent to th processing by DEBORAH MCK	um of 200 sx of a 60 sx Class over top of er entire satt Provention Hobbs INNEY on 11/15/201		
Name (Printed/	Typed) TINA HUE	RTA	Title REG R	EPORTING SUPE	BAD FIELD OFFICE	
Signature	(Electronic S		Date 11/14/2	2016		
KUR3	1	THIS SPACE FO	DR FEDERAL OR STATE	OFFICE USE		
Approved By	Taul	& Swark	Title Tec	hnical P	ET Date ///	
Conditions of approv certify that the applic		d. Approval of this notice does itable title to those rights in the	not warrant or	FO		
			crime for any person knowingly and to any matter within its jurisdiction		ny department or agency of the Unite	
			PERATOR-SUBMITTED		SUBMITTED **	
	OFERAT			OF LINATOR S		
		FUR REC	0RD ONLY			


Additional data for EC transaction #357969 that would not fit on the form

32. Additional remarks, continued

6. Spot a 10 sx Class C cement plug from 100 ft up to surface.7. Cut off wellhead, install dry hole marker and clean location.

Wellbore schematics attached





Conditions of Approval

Yates Petroleum Corporation Continental APJ - 03, API 3002536049 T23S-R32E, Sec 28, 660FNL & 660FWL November 15, 2016

- 1. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location during this workover operation.
- 2. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. <u>Notify 575-393-3612 Lea Co as work begins</u>. <u>Plugging procedures are to be witnessed</u>. If there is no response leave a voice mail with the API#, workover purpose, and a call back phone number.
- 5. Surface disturbance beyond the existing pad must have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H_2S monitoring equipment shall be on location.
- 8. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow, Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during any other crew-intensive operations.
- 10. The BLM PET witness is to run tbg tally and agree to cement volumes and placement. Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.
- 11. Cementing procedure is subject to the next three numbered paragraphs.
- 12. Mix cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft to the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ½" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- 13. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.

- 14. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 15. Tag the csg leak squeeze <5560-823> (Step 2 of Yate's procedure) with tubing and pressure test the squeeze plug to 300psig surface pressure.
- 16. Step 3 of procedure: Perf at 4940' or below (50' below Bell Canyon top of 4880).
- 17. After displacement of the 4940 perf sqz, leave the pkr set and close a valve on the tubing at the wellhead. WOC Hold the cement sqz in place with the displacement fluid until cement has set.
- 18. Release packer. Tag the plug at 4830' or above with tubing.
- 19. File subsequent sundry Form 3160-5 within 30 days of workover procedures. Submit the (BLM Form 3160-5 subsequent report (daily reports) via BLM's Well Information System; https://www.blm.gov/wispermits/wis/SP (email pswartz@blm.gov for operator setup instructions). Include (dated daily) descriptions of the well work, ie. procedure descriptions and setting depths of each plug in the subsequent sundry.
- 20. Wellbore plugging is to be accomplished within 90 days of approval.

Reclamation Objectives and Procedures

In Reply Refer To: 1310

Reclamation Objective: At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as needed. This will apply to well pads, facilities, and access roads. Barricade all access road(s) at the starting point. If reserve pits have not been adequately reclaimed due to salts or other contaminants, propose a plan for BLM approval to provide restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations should have included adequate measures for stabilization and reclamation of

disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.

- 2. For locations and/or access roads not having an approved plan, or an inadequate plan for surface reclamation the operator must submit a proposal describing the procedures for reclamation. The appropriate time for submittal would be when filing the Notice of Intent, or with the Subsequent Sundry Report of Abandonment on Form 3160-5. The final reclamation goal is to be completed within 6 months of wellbore abandonment.
- 3. With an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It may be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives.
- 4. Upon reclamation conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a BLM specialist to inspect the location to verify work was completed as per approved plans.
- 5. The BLM approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been tentatively reestablished. If the objectives have not been met BLM will be notify the operator of the required corrective actions.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time the full BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the full BLM objectives have been met, submit a Final Abandonment Notice (FAN) Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time a BLM specialist will again inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability for the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Trishia Bad Bear Natural Resource Specialist Robertson, Jeffery Natural Resource Specialist 575-234-2230, 575-706-1920 (Cell)

Vance Wolf Natural Resource Specialist 575-393-3612, 575-390-2258 (Cell)

Jesse Bassett Natural Resource Specialist 575-234-5913, 575-499-5114 (Cell)

Paul Murphy Natural Resource Specialist 757-234-5975, 575-885-9264 (Cell)

Henryetta Price Environmental Protection Specialist 575-234-5951, 575-706-2780 (Cell) 575-234-5979

Brooke Wilson Natural Resource Specialist 575-234-6237

Arthur Arias Environmental Protection Specialist 575-234-6230, 575-499-3378 (Cell)

Shelly Tucker Environmental Protection Specialist 575-234-5905, 575-361-0084 (Cell)

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.