



	UNITED STATES EPARTMENT OF THE II UREAU OF LAND MANA	NMOCD Hobbs		FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WE Do not use this form for proposals to drill or to re abandoned well. Use form 3160-3 (APD) for such p			ELLS -enter an proposals.		NMNM111970	
abandoned we	proposals.	No.	6. If Indian, Allottee of	r Tribe Name		
SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2	2015	If Unit or CA/Agre	ement, Name and/or No.
<ol> <li>Type of Well</li> <li>☑ Oil Well □ Gas Well □ Other</li> </ol>			EN EL		8. Well Name and No. PERRO LOCO 22 B3PA FEDERAL 1H	
2. Name of Operator Contact: JACKIE L MEWBOURNE OIL COMPANY - E-Mail: jlathan@mewbourne.c			THAN 🗸		9. API Well No. 30-025-43393-00-X1	
3a. Address	3b. Phone No Ph: 575-39	. (include area code)	)	10. Field and Pool or Exploratory Area OJO CHISO		
HOBBS, NM 88241						
4. Location of Well <i>(Footage, Sec., T., R., M., or Survey Description)</i>				,	11. County or Parish, State	
Sec 27 T22S R34E NENE 20				LEA COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	Acidize	Dee	pen	Product	ion (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing		Iraulic Fracturing	□ Reclam		U Well Integrity
	Casing Repair		v Construction	C Recomp		☑ Other Well Spud
☐ Final Abandonment Notice			g and Abandon		arity Abandon	
determined that the site is ready for 1 01/14/17 Spud 17 1/2" hole. T Cemented with 1300 sks Clas CaCl2. Mixed @ 14.8 #/g w/1 Tested BOPE to 5000# & Am FIT test to 10.5 PPG EMW. At 8:30 AM 01/17/17, tested E Chart & Schematic Attached. Bond on file: NM1693 nationv	D hole @ 1840'. Ran 184 sc Wadditives. Mixed @ .34 yd. Plug down @ 3:00 hular to 2500#. BOPE & csg to 1500# for 3	13.5 #/g w/1 AM 01/16/1	.74 yd. Tail w/20 7. Circ 245 sks o	0 sks Class f cmt to the		
	Electronic Submission #3	JRNE OIL CO	<b>IPANY</b> , sent to t	he Hobbs on 01/24/2017	-	
Signature (Electronic	Submission)		Date 01/19/2	017		
	THIS SPACE FO	R FEDERA			SE	
MUCEPTED FOI	E CLAS					
Approved By inditions of approval, if any, are attached. Approval of this notice does not wa tify that the applicant holds legal or equitable title to those rights in the subject ich would entitle the applicant to conduct operations thereon.			Title     Date       Office     Date			
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictilious of traudment	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter w	erson knowingly and ithin its jurisdiction.	willfully to m	ake to any department or	agency of the United
Instructions on page 2) <b>** BLM REV</b>	ISED ** BLM REVISED	) ** BLM RI	EVISED ** BLN		) ** BLM REVISE	D** KZ









MAN WELDING SERVICES, INC.						
Company Mew Bourne Date 1-17-16						
Lease PerroLoco 22 Fed. 1H County Lea N.M.						
Drilling Contractor Atterson Plug & Drill Pipe Size 12"C22 XT 39						
Accumulator Pressure: 3000 Manifold Pressure: 1500 Annular Pressure: 800						
Accumulator Function Test - OO&GO#2						
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)						
<ul> <li>Make sure all rams and annular are open and if applicable HCR is closed.</li> <li>Ensure accumulator is pumped up to working pressure! (Shut off all pumps)</li> <li>1. Open HCR Valve. (If applicable)</li> </ul>						
<ol> <li>Close annular.</li> <li>Close all pipe rams.</li> <li>Open one set of the pipe rams to simulate closing the blind ram.</li> <li>For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).</li> <li>Record remaining pressure // COO psi. Test Fails if pressure is lower than required.         <ul> <li>a. {950 psi for a 1500 psi system}</li> <li>b. {1200 psi for a 2000 &amp; 3000 psi system}</li> </ul> </li> <li>If annular is closed, open it at this time and close HCR.</li> </ol>						
To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)						
<ul> <li>Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:</li> <li>a. (800 psi for a 1500 psi system)</li> <li>b. {1100 psi for 2000 and 3000 psi system}</li> </ul>						
<ol> <li>Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)</li> <li>Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.</li> <li>Record pressure drop <u>looo</u> psi. Test fails if pressure drops below minimum.</li> <li>Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 &amp; 3000 psi system}</li> </ol>						

## To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Ð Open the bleed off valve to the tank, [manifold psi should go to 0 psi] close bleed valve.
  - 1. Open the HCR valve, (if applicable)
  - 2. Close annular
  - 3. With pumps only, time how long it takes to regain the required manifold pressure.

  - 4. Record elapsed time <u>/:38</u>. Test fails if it takes over 2 minutes.
    a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system)