Submit 3 Copies To Appropriate District	State of New Me	exico		Fc	orm C-103		
Office District I	Energy, Minerals and Natu	June 19, 2008					
1625 N. French Dr., Hobbs, NM 87240 District II		WELL API NO. 30-025-20521					
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATIO 1220 South St. Fra	5. Indicate Type of Lease					
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8	STATE X FEE					
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.					
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	7. Lease Name or Unit Agreement Name: Langlie Lynn Queen Unit						
1. Type of Well: Oil Well X Gas Well	Other	8. Well Numbe	er 11	1			
2. Name of Operator				9. OGRID Number			
Energen Resources Corporation							
3. Address of Operator 3510 N. "A" St., Bldgs A	& R Midland TV 70705		10. Pool name or Wildcat Langlie Mattix 7 RVRS/Queen/GB				
4. Well Location			Langine Matt	1X / KVKS/Quee	n/ GB		
Unit Letter <u>A</u> :	660 feet from the Nor	rth line and	660 feet	from the Eas	stline		
Section 27	Township 23S	Range 36E	NMPM	County	Lea		
	11. Elevation (Show whether		c.)				
	33/	76 GL					
12. Check A	ppropriate Box to Indicate	Nature of Notice, 1	Report, or Oth	er Data			
NOTICE OF INT	ENTION TO:	SOB	SEQUENTE	REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS.	P AND A			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB							
DOWNHOLE COMMINGLE							
OTHER:		OTHER:					
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>							
SEE ATTACHED PROPOSED TEM	PORARY ABANDON PROCEDURE.			h - Afer			
Condition of Approval: notify							
NO PRODUCTION REPORTED IN OCD Hobbs office 24 hours							
NO PRODUCTION REPORTED IN -2.4MONTHS OCD Hobbs office 24 hours prior of running MIT Test & Chart							
Spud Date:	Rig Relea	ase Date:					
I hereby certify that the information	above is true and complete to the	best of my knowledg	e and belief.				
the of the	Li						
SIGNATURE Menan Manual TITLE Regulatory Analyst DATE 03/07/2017 brenda.rathjen@energen.com							
Type or print name Brenda F. Rathjen E-mail address: PHONE 432-688-3323							
For State Use Only Manuel Manuel Adam Adam State							
APPROVED BY TOUR TITLE NO DATE 797207 Conditions of Approval (if any):							

## **ENERGEN RESOURCES CORPORATION** Langlie Lynn Queen Unit #11, API # 30-025-20521

600' FNL, 600' FEL Sec. 27, T-23-S, R-36-E Lea County, NM

The LLQU #11 was completed in 7/16/63 as a 7Rivers-Queen producer. The well is not currently economic to produce, and needs to be TA'd.

For scope changes during work, stop and discuss with engineering before proceeding


API:	30-025-20521	KB:	3386'	PBTD:
Spud Date:	23201	GLE:	3376'	TD: 3730'

**Temporary Abandon Procedure** 

## SAFETY CONSIDERATIONS

Observe all Energen Guidelines for PPE and H2S Safety Observe perforation and contractor safety guidelines Wireline and explosives on location while perforating Workstring should be in good condition and tested to 5000 psi. BOP should be in good working condition and tested Rig anchors will need to be tested prior to MIRU Keep a TIW valve open and on the rig floor at all times Notify FAA five days prior to starting P&A operations Notify the NM OCD 24 hours prior to starting TA operations Notify the BLM prior to starting TA operations Meet with engineer, superintendents, and consultant prior to beginning the job, to assure that everyone is agreement with the procedure.

- 1 MIRU Well Service Unit.
- 2 Bleed well down.
- 3 NDWH
- 4 Unset pump. POOH w/ rods and pump.
- 5 NU adapter flange and BOP for 4-1/2" csg and 2-1/16" tubing. Test to 500 psi above working pressure.
- 6 POOH and LD production string. Use production tubing as workstring or:
- 7 Unload and rack 3600' 2-3/8" workstring. Maintain kill truck w/10 ppg brine on location.
- 8 RIH, set CIBP @3482', and dump bail 35' cmt or 25 sx cmt through tubing.
- 9 RIH w/ workstring and circulate packer fluid.
- 10 Notify OCD and BLM 24 hours prior to running MIT test and chart
- 11 POOH. RIH w/ 3 joints tubing as kill string.
- 12 ND BOP. NUWH
- 13 Perform bradenhead test.
- 14 RD and clean location.



## ENERGEN RESOURCES, INC.

Langlie Lynn Unit #11

Lea County, NM

1 10

