Office State of New Mexico	Form C-103
District I = (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-31310
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St/Araticis Dr7	STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460  Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Onit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	LOVINGTON PADDICK UNIT
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other	8. Well Number: 103
2. Name of Operator	9. OGRID Number
CHEVRON MIDCONTINENT, L.P.	241333
3. Address of Operator	10. Pool name or Wildcat
6301 DEAUVILLE BLVD, MIDLAND, TX 79706 RM.N3002	LOVINGTON; PADDOCK
4. Well Location	
Unit Letter A: 16 feet from the NORTH line and	feet from the <u>EAST</u> line
Section 36 Township 16S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3841' GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO	OFOLIENT F
	SEQUENT
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOFT TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR	
TEMPORARILY ABANDON	
FULL ON ALTER CASING IT WILLTIFLE COWIFE IT TOASING/CEWIEN	L GAINI
	P&A R
DOWNHOLE COMMINGLE	P&A R
OTHER:  OTHER:  OTHER:	
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:	ad give pertinent dates, including estimated date
OTHER:	ad give pertinent dates, including estimated date
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:	ad give pertinent dates, including estimated date
OTHER:  OTHER:	ad give pertinent dates, including estimated date
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.	ad give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin. 2. MIRU. NDWH. NU BOPE.	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin. 2. MIRU. NDWH. NU BOPE.	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of
OTHER:  I OTHER:  OTHE	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of the 25sx of cmt. on top. Pressure test
OTHER:  Is Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  Call and notify NMOCD 24 hrs. before operations begin.  MIRU. NDWH. NU BOPE.  RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Tagental states.	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of t 25sx of cmt. on top. Pressure test g. (B.Salt)
OTHER:  I OTHER:  OTHER:  OTHER:  OTHER:  I OTHER:  OTHER:  OTHER:  I OTHER:  OTHER:  OTHER:  I OTHER:  OTHER:  OTHER:  OTHER:  I OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  I OTHER:  OT	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt)
OTHER:  Is details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  Call and notify NMOCD 24 hrs. before operations begin.  MIRU. NDWH. NU BOPE.  RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Tagestandard Spotasing.  Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Tagestandard Spotasing.  Spot 40sx of Class "C" cement from 350' to surface. (FW/surface.)	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace)
OTHER:  I OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  I OTHER:  OT	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace)
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Tagonian Spot Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Tagonian Spot Spot 40sx of Class "C" cement from 350' to surface. (FW/surface) (FW/surfacee	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace)
OTHER:  I OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  I OTHER:  OT	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace)
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Tagonian Spot Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Tagonian Spot Spot 40sx of Class "C" cement from 350' to surface. (FW/surface) (FW/surfacee	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace)
OTHER:  OTHER:	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta  5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta  6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surface.)  7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on CD 24 HOURS PRIOR TO
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta  5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta  6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surface.)  7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.	t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta, 5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta, 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surface)	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of  t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on  CD 24 HOURS PRIOR TO G PLUGGING OPERATIONS
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta  5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta  6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surface.)  7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on CD 24 HOURS PRIOR TO
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921',circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta, 5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta, 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surf. 7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.  I hereby certify that the information above is true and complete to the bes    NOTIFY OC   BEGINNING  SIGNATURE	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of  t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) anchors 3' below grade. Weld on  CD 24 HOURS PRIOR TO G PLUGGING OPERATIONS  DATE 03/06/17
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921', circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta  5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta  6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surf.)  7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.  I hereby certify that the information above is true and complete to the bes.  NOTIFY OC BEGINNING.  SIGNATURE  M. Lee Roark  E-mail address: LRoark@Chevr.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of  t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on  CD 24 HOURS PRIOR TO G PLUGGING OPERATIONS
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921', circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta  5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta  6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surf;  7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.  I hereby certify that the information above is true and complete to the bes  NOTIFY OC BEGINNING.  SIGNATURE	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of  t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) unchors 3' below grade. Weld on  CD 24 HOURS PRIOR TO G PLUGGING OPERATIONS  DATE 03/06/17  on.com PHONE: (432)-687-7279
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. Call and notify NMOCD 24 hrs. before operations begin.  2. MIRU. NDWH. NU BOPE.  3. RIH and tag BP@5,921', circulate well w/9.5 ppg mud and spocasing.  4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC&Ta  5. Spot 30sx of Class "C" cement from 2,095'-1,845', WOC&Ta  6. Spot 40sx of Class "C" cement from 350' to surface. (FW/surf;  7. Verify cement to surface on all casings. Cut off wellhead and a dryhole marker and clean location.  Closed loop above ground tank system will be used for fluids.  I hereby certify that the information above is true and complete to the bes  NOTIFY OC BEGINNING.  SIGNATURE	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of  t 25sx of cmt. on top. Pressure test g. (B.Salt) g. (Shoe/T.Salt) ace) anchors 3' below grade. Weld on  CD 24 HOURS PRIOR TO G PLUGGING OPERATIONS  DATE 03/06/17

## CURRENT

Well:

Lovington Paddock Unit 103

Field: Lovington Reservoir:

Paddock

API: St.:

Loc:

30-025-31310-00

**New Mexico** 

Sec:

36

Tws: **16S** 

16' FNL and 1078' FEL

Rng: 36E

Spud Date: 9/11/1991 TD Date: 9/20/1991 Comp Date:

> 8-5/8" 24# @ 2045' (48 jts) CMT: 825sx CI "C"

TOC: Surface (circ)

HOLE: 12-1/4"

5-1/2" 15.5# @ 6500' (150 jts)

CMT: 1625sx CI "C"

TOC: Surface (circ)

HOLE: 7-7/8"

RBP @ 5921' (3/31/2008)

**Perforations** 6058-63791

COTD: PBTD:

TD:

6500'

=

= =

=

=

=

=

=

## PROPOSED WELLBORE DIAGRAM

Lease: Location:	LOVINGTOR	1078' FEL			: <u>103</u> 36-T16S-R36E	_	Field: _		INGTON; PADDOCK
County:	Lea	St:	NM_I	Refno:		API:	30-025-31	310	Cost Center:
Surface Csg Size: Wt.: Set @: Sxs cmt: Circ: TOC: Hole Size:	8-5/8" 24# 2045' 825 Yes Surf 12-1/4"	-			MLF		(FW/surfa	ce)	ass "C" Cement from 350'-surface.
Production	Csg.		2	4			Spot 30s) WOC&TA		ass "C" Cement from 2095'-1845'. Salt/Shoe)
Size: Wt.: Set @: Sxs Cmt: Circ: Hole Size: PBTD: TD:	5-1/2" 15.5# 6500' 1625 Yes 7-7/8" 6458' 6500'				MLF				
							Spot 25sx WOC&TA		ass "C" Cement from 3109'-2900'. Salt)
					MLF				
		BP@5921'					Tag BP@	5921' a	and spot 25sx on top thru tubing.
			0.070	=					
Remarks:		6058	3'-6379'	= =					
			U		by: LRQS te: 03/06/17		Prepa	ared by Date	/: