

30-025- 27/80BBS OCD

APR 1 4 2017

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office Attention: William Sonnamaker RECEIVED

Regarding: Raya Energy Corp. Jennings B Federal 2 Bradenhead Test Chart

Mr.. Sonnamaker,

We failed the first bradenhead test due to a hole in the tubing. This is the successful chart after pulling the well and repairing the tubing. I believe my Field Supervisor Karl Harris, coordinated with an OCD representative during this test and provided the paperwork, but forgot to give him the chart, which he just mailed to me. Please let me know if you need any additional information from us.

Best regards,

Phillip H. Roberson

President,

FieldPoint Petroleum Corp. and Raya Energy Corp.

## OENIED

· NO RECORD OF NOTICE FOR MIT CHECKED OCD, BLM

· NO C-103 INTENT.

· NEED C-103 SURSEQUENT FOR WELL WORK TO REPAIR WELL WITH CURRENT WELL BORE DIAGRAM.

PRIOR TO RE-TESTING WITH A WITNESS

609 Castle Ridge Road • Austin, Texas 78746 • 512-579-3560

4/24/2017