Submit 1 Copy To Appropriate District Office	State of New Me		Form C-103			
District 1 – (575) 393-6161 HOBBS (Spergy, Minerals and Natural Resources			Turni Abiato	Revised Aug	ust 1, 2011	
1025 W. Franch Dr., Hobbs, NM 88240			WELL API NO. 30-025-35961			
BILS. First St., Artesia, NM 88210 AY 03 200 CONSERVATION DIVISION			5. Indicate Type of L	ease		
1000 Rin Rmans Rd. Azine NM 87410			STATE 🛛	FEE [		
District IV - (505) 476-3460 RECEIVED Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas L	ease No.		
87505			*			
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name Conoco State			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				o State		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other:			8. Well Number:	a. Well Number:		
2. Name of Operator			9. OGRID Number: 16696			
OXY USA INC.						
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)			
P.O. Box 4294, Houston TX, 77210-4294			Hobbs: Drinkard/ Ho	bbs: Tubb (C	ias)	
4. Well Location						
Unit LetterJ_:2110feet from theSouth line and2055feet from theEast line  Section 33 Township 18S Range 38E NMPM Lea County						
Section 33	Township 18S Elevation (Show whether DR,	Range 38E		.ea (	County	
	2' (KB)	AND, NI, ON, ER.,				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				TERING CAS	SING 🗆	
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DR			The second secon	AND A		
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT			I JOB			
DOWNHOLE COMMINGLE						
OTHER:	П	OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or recompletion.						
1. MIRU PU. ND Wellhead. NU BOP.		Province this	procedure we plan	to use		
2. POOH with production tubing During this			procedure we plan to use loop system with a steel			
3. RIH with bit and tag PBTD (6950') the closed-			aul contents to the	required		
4. RIH w/ RBP and packer and test casing for leaks 5. If no leaks, TA wellbore per plan 35' - TAG disposal no			CONCENTS TO THE	17		
6. Set CIBP at 661 I' and cap w/ 30' cement (Drinkard perfs)						
7. Circulate packer fluid between perfs 35'						
8. Set 2 <sup>rd</sup> CIBP at 6356' and cap w/ 30' cement (Tubb perfs)  9. Circulate packer fluid to surface.			ition of Approval:	: notify	d d	
10. Perform MIT			D Hobbs office 24	hours	and a second	
11. ND BOP. NU TA wellhead. RD PU		prior of	running MIT Tes	t & Chart	1	
prior of running MIT Test & Chart						
Spud Date: Rig Release Date:						
				1		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE DATE						
Type or print name Jacob S. Cox E-mail address: Jacob Cox ©oxy.com PHONE: 713-497-2053						
For State Use Only						
APPROVED BY: Y VAILUX DIOWTELLE NO /IL DATE 5/3/2017						
Conditions of Approval (if any)						



