
Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT						FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.							, Allottee or Tr	ibe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well MAY 3 0 2017						7. If Unit or CA/Agreement, Name and/or No.			
Oil Well Gas Well Other						Well Name and No. WH RHODES B FEDERAL NCT-1 23			
PPC OPERATING COMPANY LLC E-Mail: GREG.BRYANT@BASICENERGYSERVICES.COM						9. API Well No. 30-025-32097-00-S1			
3a. Address3b. Phone No. (include Ph: 432-563-33541500 INDUSTRIAL BLVD SUITE 304 ABILENE, TX 79602Ph: 432-563-3354				area code)		10. Field and Pool or Exploratory Area RHODES			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 26 T26S R37E SWNW 2583FNL 55FWL						11. County or Parish, State LEA COUNTY, NM			
Sec 20 1205 R3/E SWINW 2563FINE SSFWL									
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent	Acidize Deepen Produ Alter Casing Hydraulic Fracturing Reclaim					tion (Start/I nation INT TO PA PM:X			
□ Subsequent Report					Recom	plete P&A NR			
☐ Final Abandonment Notice	□ Change Plans ☑ Plug and Abandon □ Temper □ Convert to Injection □ Plug Back □ Water				rarily Aban	P&A R			
 following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1) MIRU. ND WH, NU BOP. POOH w/ Prod equipment (if necessary) 2) RIH Tbg - Tag existing CIBP @ 3128'. Circ hole w/ MLF 3) Spot 50sx cmt @ 3128'-2684'. WOC-Tag 7 2 6 2 6 84 or less above. Base Salf. 4) PUH to 1400' - Spot 40sx cmt to 1040'. WOC-Tag 7 salf 1330 5) POOH Tbg. ND BOP. Pump 15sx cmt @ 100' to surface 6) POOH. Top off well. RDMO. Cut off WH & anchors. Install P&A marker. SEE ATTACHED FOR									
CONDITIONS OF APPROVAL									
and the second									
14. I hereby certify that the foregoing is true and correct. Electronic Submission #369165 verified by the BLM Well Information System For PPC OPERATING COMPANY LLC, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 03/09/2017 (17PP0351SE)									
Name(Printed/Typed) GREG BF	RYANT	1	litle	AGENT			× *		
Signature (Electronic	Submission)	п	Date	03/08/20			D	1	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By			Title		MAY	15 901	2	Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu	uitable title to those rights in the su	ubject lease	Office		fff	varte	F		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowing and willsuff to make to any department of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction CARI SBAD FIFLD OFFICE									
(Instructions on page 2)	ISED ** BLM REVISED		/ISEI) ** BLM	REVISE		REVISED *	J	


Copy of W H Rhodes B Federal NCT 1 #23 Wellbore Diagram_rev TR.xlsx



2/22/2017

HJW

Copy of W H Rhodes B Federal NCT 1 #23 Wellbore Diagram_rev TR.xisx



2/22/2017

HJW

Conditions of Approval

PPC Operating Company LLC WH Rhodes B NCT-1 #23, API 3002532097 T26S-R37E, Sec 28, 2583FNL & 55FWL May 15, 2017

1. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location during this workover operation.

- 2. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. <u>Notify 575-393-3612 Lea Co as work begins</u>. <u>Plugging procedures are to be witnessed</u>. If there is no response leave a voice mail with the API#, workover purpose, and a call back phone number.
- 5. Surface disturbance beyond the existing pad must have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H_2S monitoring equipment shall be on location.
- 8. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during any other crew-intensive operations.
- The BLM PET witness is to run tbg tally and agree to cement volumes and placement. Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.
- **11.** Cementing procedure is subject to the next three numbered paragraphs.
- 12. Mix cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft to the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ½" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 14. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.

15. File subsequent sundry Form 3160-5 within 30 days of workover procedures.16. Wellbore plugging is to be accomplished within 90 days of approval.

Reclamation Objectives and Procedures

In Reply Refer To: 1310

Reclamation Objective: At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as needed. This will apply to well pads, facilities, and access roads. Barricade all access road(s) at the starting point. If reserve pits have not been adequately reclaimed due to salts or other contaminants, propose a plan for BLM approval to provide restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations should have included adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For locations and/or access roads not having an approved plan, or an inadequate plan for surface reclamation the operator must submit a proposal describing the procedures for reclamation. The appropriate time for submittal would be when filing the Notice of Intent, or with the Subsequent Sundry Report of Abandonment on Form 3160-5. The final reclamation goal is to be completed within 6 months of wellbore abandonment.
- 3. With an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It may be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives.
- 4. Upon reclamation conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a BLM specialist to inspect the location to verify work was completed as per approved plans.

- 5. The BLM approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been tentatively reestablished. If the objectives have not been met BLM will be notify the operator of the required corrective actions.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time the full BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the full BLM objectives have been met, submit a Final Abandonment Notice (FAN) Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time a BLM specialist will again inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability for the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Trishia Bad Bear Natural Resource Specialist 575-393-3612, 575-390-2258 (Cell)

Jesse Bassett Natural Resource Specialist 575-234-5913, 575-499-5114 (Cell)

Paul Murphy Natural Resource Specialist 757-234-5975, 575-885-9264 (Cell)

Henryetta Price Environmental Protection Specialist 575-234-5951, 575-706-2780 (Cell) Robertson, Jeffery Natural Resource Specialist 575-234-2230, 575-706-1920 (Cell)

Vance Wolf Natural Resource Specialist 575-234-5979

Brooke Wilson Natural Resource Specialist 575-234-6237

Arthur Arias Environmental Protection Specialist 575-234-6230, 575-499-3378 (Cell)

Shelly Tucker Environmental Protection Specialist 575-234-5905, 575-361-0084 (Cell)