Office Office	State of New Me		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-38318	
District II - (575) 748-1283 811 S. First St., Artesia, NM 88240 District III - (575) 344-1283 CONSERVATION DIVISION District III - (505) 344-148 1220 South St. Francis Dr.		5. Indicate Type of Lease	
District III – (505) 334 of 18 Dr. 1220 South St. Francis Dr.		STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Ft. NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH MONUMENT G/SA UNIT [302708]
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well: Oil Well Gas Well Other		8. Well Number #364	
2. Name of Operator		9. OGRID Number	
Apache Corporation			873 10. Pool name or Wildcat
Address of Operator Soa Veterans Airpark Lane, Suite 1000 Midland, TX 79705		23000] EUNICE MONUMENT; GRAYBURG-S	
4. Well Location	Wildiana, 177 70700		20000 EONIGE MONOMENT, ONAT BONG-C
Unit Letter N : 10	feet from the SOUTH	line and 1420	feet from the FWL line
Section 19 Township 19S Range 37E NMPM County lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3675 gl			
	_		
12. Check Ap	propriate Box to Indicate N	ature of Notice, I	Report or Other Data
NOTICE OF INT	ENTION TO	OLIDO	SECUENT DEPORT OF
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORL TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			
DOWNHOLE COMMINGLE	MOETIFEE COMFE	CASING/CEWENT	308
CLOSED-LOOP SYSTEM			
OTHER: NOI- Add pay 8	k acidize	OTHER:	
	ted operations. (Clearly state all p		give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Apache would like to complete the following work:			
Work Objective: Add pay in and acidize upper interval in the Grayburg.			
voik Objective. Add pay in and acidize	upper interval in the Grayburg.		
3636' – 56'			
3660' – 76'			
3680' – 88'			
See attached WBD & Procedures			
Spud Data:	Rig Release Da	to:	
Spud Date: 06/01/2007	Kig Kelease Da	ite.	The state of the s
I hereby certify that the information at	eeve is true and complete to the bo	est of my knowledge	and belief
Thereby colliny and the interpretation) of a state and complete to the oc	ist of my knowledge	, and other.
	1. 1/0.		(2017
SIGNATURE	Hullis TITLE Reg An	alyst	DATE 08/14/2014 2017
Tyme on much and Firming Pollice	E!!	Emily.follis@apache	
Type or print name Emily Pollis For State Use Only	E-mail address		FIUNE: (402) 010-1001
Mal MKARLA ARITH			
APPROVED BY: 1 OLUM CTITLE TO DATE 8/21/2017			
Conditions of Approval (if ary):		1	1 1
U			

NMGSAU #364 (30-025-38318)

AFE: 11-17-1429

Work Objective: Add pay in and acidize upper interval in the Grayburg.

Day 1: RU SU. POOH w/pump and rods.

NU BOP. POOH w/tubing. Note scale and paraffin deposits as well as location of deposits on report. Notify Midland engineering of type and amount of scale

encountered as soon as tubing is pulled.

Day 2: RIH w/bit and scraper. RIH to ±4043' and tag for fill. POOH.

MIRU WL Unit. Perforate as follows w/2 SPF and 180 degree phasing:

3636' - 56'

3660' - 76'

3680' - 88'

RIH w/RBP. **Set RBP @ ±3751'. Set packer @ ±3600'.** Acidize Upper Grayburg w/4000 gals 15% HCl acid (Grayburg Blend) and ball sealers. Record ISIP, 5 min, 10 min, and 15 min shut-in pressures.

Release packer and RBP. POOH w/packer and RBP.

Day 4/5: Finish POOH w/tubing and lay down packer. Test in hole w/2-7/8" tubing. RIH w/pump

and rods. POP.

Apache Corporation – NMGSAU #364

Wellbore Diagram - Proposed Status

API: 30-025-38318

Date: 8/1/2017

J. Bower



GL=3674'

KB=3686'

Hole Size

Hole Size =7-7/8"

Spud: 6/1/07



Surface Location

10' FSL & 1420' FWL, Sec 19, T19S, R37E, Lea County, NM

Surface Casing 8-5/8" 24# J-55 @ 395' w/ 282 sx to surface

TAC @ ????' SN @ 3907'

TBD: Perf Grayburg @ 3636' - 56', 3660' - 76', 3680' - 88' w/ 2 jspf (94 holes) Acidize w/4000 gal 15% NEFE acid

12/11: Perf Grayburg @ 3801-08; 3814-34; 3838-46; 3850-58 w/ 2 jspf (86 holes). Acidized w/ 3000 gal 15% NEFE acid

6/07: Perf Grayburg @ 3888-3902 w/ 2 jspf (40 holes). Acidized w/ $1000~{\rm gal}~15\%$ NEFE acid.

3/14: Treat perfs fr/ 3801-3858' & 3888-3902' w/ blue spark tools. Return to production.

PBTD = 4043' TD =4120' Production Casing 5-1/2" 17# J-55 @ 4120' w/ 1231 sxs

Apache Corporation – NMGSAU #364

Wellbore Diagram – Current Status

API: 30-025-38318

Date: 7/7/2016 K. Grisham

Surface Location

10' FSL & 1420' FWL, Sec 19, T19S, R37E, Lea County, NM

Surface Casing 8-5/8" 24# J-55 @ 395' w/ 282 sx to surface

TAC @ 3715' SN @ 3907'

12/11: Perf Grayburg @ 3801-08; 3814-34; 3838-46; 3850-58 w/ 2 jspf (86 holes). Acidized w/ 3000 gal 15% NEFE acid

6/07: Perf Grayburg @ 3888-3902 w/ 2 jspf (40 holes). Acidized w/ 1000 gal 15% NEFE acid.

3/14: Treat perfs fr/ 3801-3858' & 3888-3902' w/ blue spark tools. Return to production.

PBTD = 4043'TD =4120'

GL=3674'

KB=3686'

Hole Size =11"

Hole Size =7-7/8"

Spud: 6/1/07

Production Casing 5-1/2" 17# J-55 @ 4120' w/ 1231 sxs