Submit 1 Copy To Appropriate Distric Office		State of N Minerals and		exico ral Resources 🚕		Form Revised July	C-103	
District I 1625 N. French Dr., Hobbs, NM 88240				000	WELL API NO.	0251 0-025-102-51	18, 2013	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATIO			ATIO	N DIVISION	5. Indicate Type			
District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM				ncis Dr. 2011	STATE D			
District IV 1220 S. St. Francis Dr., Santa Fe, NM		Bailta I C,		0CT 2 3 2017	6. State Oil & Ga			
87505	OTICES AND F				7 Loss North			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)				OR PLUG BACK TO A	NG PENROSE	Unit Agreement N	ame:	
						8. Well Number		
2. Name of Operator	Gas well					9. OGRID Number		
XTO Energy, Inc.		,				005380		
3. Address of Operator 500 W. Illinois, Ste 100 Midland TX 79701					10. Pool name or Wildcat BLINERY OIL AND GAS (OIL)			
4. Well Location					1			
Unit Letter H	: <b>1980</b> f	feet from the	NORT	H line and	<b>660</b> feet fro	om the EAST	line	
Section 13		wnship 22S		0	NMPM	County LEA		
	11. Eleva	tion (Show w	whether	DR, RKB, RT, GR, et	<i>c.)</i>			
10.01	1	D . I	1			<b>D</b> :		
12. Chec	K Appropriate	Box to Inc	licate	Nature of Notice,	Report, or Other	Data		
NOTICE OF I	INTENTION	τo		SUB	SEQUENT RE	PORT OF		
				COMMENCE DRILL		P AND A		
PULL OR ALTER CASING	_	E COMPL		CASING/CEMENT J				
DOWNHOLE COMMINGLE				CAGING/CEMENT 5				
CLOSED-LOOP SYSTEM								
OTHER:				OTHER: TEMPOR	ARILY ABANDON		X	
13. Describe proposed or comp	pleted operations	. (Clearly stat	te all pe	rtinent details, and giv	ve pertinent dates, in	ncluding estimated of	late	
of starting any proposed w	ork). SEE RULE						late	
	ork). SEE RULE	E 19.15.7.14 N					late	
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS	ork). SEE RULE completion. F REFERENCEL & PMP ND WH.	E 19.15.7.14 N D WELL: RELEASE TA	JMAC	For Multiple Comple	etions: Attach wellb	ore diagram of		
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP.	B 19.15.7.14 N D WELL: RELEASE TA	MAC	For Multiple Comple	etions: Attach wellb	ore diagram of		
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP.	B 19.15.7.14 N D WELL: RELEASE TA	MAC	For Multiple Comple BOP LD PROD TUBI TEST TO 600PSI. W	tions: Attach wellb NG SWI& SDON. R	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.		
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP.	B 19.15.7.14 N D WELL: RELEASE TA	MAC	For Multiple Comple BOP LD PROD TUBI TEST TO 600PSI. W	tions: Attach wellb NG SWI& SDON. R TNESSED BY NMC	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.		
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP.	B 19.15.7.14 N D WELL: RELEASE TA	MAC	For Multiple Comple BOP LD PROD TUBI TEST TO 600PSI. W	tions: Attach wellb NG SWI& SDON. R TNESSED BY NMC	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.		
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP.	B 19.15.7.14 N D WELL: RELEASE TA	MAC	For Multiple Comple BOP LD PROD TUBI TEST TO 600PSI. W	tions: Attach wellb NG SWI& SDON. R TNESSED BY NMC	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.		
of starting any proposed w proposed completion or rea XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP.	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	IMAĈ	For Multiple Comple BOP LD PROD TUBI TEST TO 600PSI. W	tions: Attach wellb NG SWI& SDON. R TNESSED BY NMC	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.		
of starting any proposed w proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 S2 09/18-09/20: TAG CMT@5375	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	IMAC	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon National States	etions: Attach wellb NG SWI& SDON. R TNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.		
of starting any proposed w proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 S) 09/18-09/20: TAG CMT@5375	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	AC NU I CLEAN	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon use Date:	etions: Attach wellbook NG SWI& SDON. R ITNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGETO DCD. WB TA. $P$	0 5415 2	
of starting any proposed w proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 S2 09/18-09/20: TAG CMT@5375	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	AC NU I CLEAN	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon National States	etions: Attach wellbook NG SWI& SDON. R ITNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGET DCD. WB TA.	0 5415 2	
of starting any proposed w proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 S2 09/18-09/20: TAG CMT@5375	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	AC NU I CLEAN The to the TIT E-m	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon Abandon use Date:	ettions: Attach wellb NG SWI& SDON. R TNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGETO DCD. WB TA. 9/19/201 	0 5415 2   7	
of starting any proposed we proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX 09/18-09/20: TAG CMT@5375 Spud Date:	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	AC NU I CLEAN The to the TIT E-m	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon Abandon use Date:	ettions: Attach wellb NG SWI& SDON. R TNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGETO DCD. WB TA. 9/19/201 	0 5415 2   7	
of starting any proposed we proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 SX 09/18-09/20: TAG CMT@5375 Spud Date: I hereby certify that the information SIGNATURE Type or print name PATRICIA I For State Use Only APPROVED BY	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	AC NU I CLEAN The to the TIT E-m	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon Abandon Le Date:	ettions: Attach wellb NG SWI& SDON. R TNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGETO DCD. WB TA. 9/19/201 	0 5415 2   7	
of starting any proposed we proposed completion or rec XTO NOTIFICATION OF TA O 09/14-09/16/17 MIRU LD RDS RIH CIBP SET @5410 RIH 4 S2 09/18-09/20: TAG CMT@5375 Spud Date: I hereby certify that the information SIGNATURE Type or print name PATRICIA I For State Use Only	ork). SEE RULE completion. F REFERENCEL & PMP ND WH. X CMT ON CIBP. RU PMPT TRK	B 19.15.7.14 N D WELL: RELEASE TA CIRC WELL C	AC NU I CLEAN The to the TIT E-m	For Multiple Complete BOP LD PROD TUBIL TEST TO 600PSI. W This Appro Abandon Abandon Le Date:	ettions: Attach wellb NG SWI& SDON. R TNESSED BY NMC val of Tempora ent Expires	ore diagram of RIH W 4.5 GAUGET DCD. WB TA. P DATE 10/19/201 PHONE 432-571	0 5415 2   7	

×

π

RBDMS - CHART-V

