

Submit I Copy To Appropriate District State of New	Mexico	Form C-103
Office Energy Minorals and		Revised August 1, 2011
District I – (575) 393-6161 Energy, Minerals and 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVA		30-025-05485
District III = (505) 334-6178 1220 South St.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8/410 Sonto Eq. N	AD TRACE	STATE FEE 6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON W (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-	REIVED	o, State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON W	RECE	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN (OR PLUG BACK TO A	South Hobbs (G/SA) Unit -
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Forth NORTH
1. Type of Well: Oil Well 🛛 Gas Well 🗋 Other: TA		8. Well Number: 24-141
2. Name of Operator Occidental Permian Ltd.	/	9. OGRID Number: 157984
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		
4. Well Location		
Unit LetterM_:1315feet from theSouthline and1315feet from theWestline		
Section 24 Township	18S Range 38E	37E NMPM Lea County
11. Elevation (Show whether	r DR, RKB, RT, GR, etc.)	
3622' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
		DOAND
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT J	P&A R
OTHER:	OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed workpation. 4.1. 		
proposed completion of recompletion K EFE ATTACHED CUMPITIONIS of APPONIA		
proposed completion or recompletion K SEE ATTACHED CONDITIONS of APPROVAL		
2. PU to 4060° and spot 25sxs (shoe). WOC and tag (no deeper than 4010°). During this procedure we plan to use		
a, TO to 2017 and shot 20 and 1 great		
4. PU to 300° and perf x squeeze with 200sxs. Cement to surface. Top off well as necessary. tank and haul contents to the required		
5. Cut off wellhead and install dry hole marker with labeling.		
 Cut off wellhead and install dry hole marker with labeling. RD x MO. Clean up location and remove anchors. disposal per ODC Rule 19.15.17 		
Spud Date: Rig Relea	se Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
$\Delta u = u = u$		
SIGNATURE_AU UCTITLE_Production EngineerDATE10/25/17		
Type or print nameAlison Cramer E-mail address_alison_cramer@oxy.com PHONE: 713-840-3024		
For State Use Only		
APPROVED BY Manheutituhn TITLE Petroleum Engr. Specialist DATE 10/26/2017		
Conditions of Approval (if any):		
NOTIFY OCD 24 HOURS PRIOR TO		

BEGINNING PLUGGING OPERATIONS

CURRENT WELLBORE



PROPOSED P&A WELLBORE



OCCICENTAL PERMIAN LTD.

NORTH HOBBS G/SA UNIT NO. 141

Conditions of Approval:

- 1) Tag top of cement on CIBP.
- 2) Circulate mud laden fluid and pressure test casing.
- 3) Spot 30 sx Class C cement at 4080'. WOC & Tag. (7" shoe & Top of 5" liner) Tag at 3900' or better.
- 4) Spot 25 sx Class C cement at 2817'. (Base of salt)
- 5) Perforate at 1700' and attempt to squeeze 60 sx Class C cement. WOC & Tag. (Top of Salt) Tag at 1600' or better.
- 6) Perforate at 300'. Circulate Class C cement to surface inside/outside 7" casing.
- 7) Cut off wellhead 3' below ground level. Confirm cement to surface all strings. Install P&A marker.