

HOBBS OCD
NOV 02 2017
RECEIVED

WELL INFORMATION

Rebel Federal 20 #6

30-025-42995

When drilling the conductor for the Rebel 20 Fed 6H original SHL, the auger unit drilling the mouse hole collided with the conductor putting a 20" hole in the conductor which more than likely parted the conductor. Ready Drill, the conductor/mouse hole company, plugged the entire conductor and mouse hole along with the cellar with cement programed in the above table.

Well was skid and repermitted under API

30-25-43449

Rebel 20 Federal #6Y