Office	State of New Mexico	Form C-103
B 1012121	nergy, Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		20.025.24142
off B. Pitst BL, Attesta, 1414 GOLTO	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE 🛛
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO	FOR PERMIT" (FORM HO FOR SUCHOCI	FRED TURNER JR A TURNER A
PROPOSALS.)		/
1. Type of Well: Soil Well Gas W	ell Other	√ 15
2. Name of Operator OXY USA WTP LP	DEC 0 7 2017	9. OGRID Number 192463
3. Address of Operator	RECEIVED	10. Pool name or Wildcat
PO BOX 4294; HOUSTON, TX 77210	KECEIAED	SKAGGS GRAYBURG DRINKARD
4. Well Location		
Unit Letter 1: 2160 feet from	the SOUTH line and 990 feet from the EA	<u>ST</u> line
Section 18 Township 20S		
11. E	Elevation (Show whether DR, RKB, RT, GR 3555' GL	c, etc.)
12. Check Appropriate Box to Indic		er Data
NOTICE OF INTEN		SUBSEQUENT REPORT OF:
	G AND ABANDON REMEDIAL NOTE: REMEDIAL NOTE: COMMENCE	WORK ☐ ALTERING CASING ☐ ' E DRILLING OPNS.☐ P AND A ☐
_	TIPLE COMPL CASING/CE	
	_	_
OTHER:		n is ready for OCD inspection after P&A
Rat hole and cellar have been filled an	liance with OCD rules and the terms of the d leveled. Cathodic protection holes have	Operator's pit permit and closure plan.
Rat hole and cellar have been filled an	flance with OCD rules and the terms of the d leveled. Cathodic protection holes have and at least 4' above ground level has been	been properly abandoned.
 □ Rat hole and cellar have been filled an □ A steel marker at least 4" in diameter at 	d leveled. Cathodic protection holes have and at least 4' above ground level has been	been properly abandoned. set in concrete. It shows the
 ✓ Rat hole and cellar have been filled an ✓ A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N 	d leveled. Cathodic protection holes have and at least 4' above ground level has been AME, WELL NUMBER, API NUMBER	been properly abandoned. set in concrete. It shows the R, QUARTER/QUARTER LOCATION OR
 ✓ Rat hole and cellar have been filled an ✓ A steel marker at least 4" in diameter at OPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO 	d leveled. Cathodic protection holes have and at least 4' above ground level has been AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM	been properly abandoned. set in concrete. It shows the R, QUARTER/QUARTER LOCATION OR
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at leas	d leveled. Cathodic protection holes have and at least 4' above ground level has been AME, WELL NUMBER, API NUMBER WISHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE.	set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at OPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED C ✓ The location has been leveled as nearly 	d leveled. Cathodic protection holes have and at least 4' above ground level has been AME, WELL NUMBER, API NUMBER WISHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE.	been properly abandoned. set in concrete. It shows the R, QUARTER/QUARTER LOCATION OR
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at OPERATOR NAME, LEASE N UNIT LETTER, SECTION, TO PERMANENTLY STAMPED C ✓ The location has been leveled as nearly other production equipment. 	d leveled. Cathodic protection holes have and at least 4' above ground level has been AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE. y as possible to original ground contour and	been properly abandoned. set in concrete. It shows the R, QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at leas	d leveled. Cathodic protection holes have and at least 4' above ground level has been ame. Well number, API number with an armount of the marker's surface. If a possible to original ground contour and the state of the state o	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level.
 ☑ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at least 1". ☑ OPERATOR NAME, LEASE NUMITY LETTER, SECTION, TO PERMANENTLY STAMPED C ☑ The location has been leveled as nearly other production equipment. ☑ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's 	d leveled. Cathodic protection holes have and at least 4' above ground level has been ambiguity. AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE. If as possible to original ground contour and the state of the state o	been properly abandoned. set in concrete. It shows the R, QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at Personal Andrews and Personal Anchors, dead men, tied owns and rise of this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. 	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and an amount and a property and part least two feet belowing well on lease, the battery and pit locat pit permit and closure plan. All flow lines,	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with, production equipment and junk have been removed
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at least 1. The location has been leveled as nearly other production equipment. ✓ Anchors, dead men, tie downs and rise of this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ✓ All metal bolts and other materials have 	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and an amount and a property and part least two feet belowing well on lease, the battery and pit locat pit permit and closure plan. All flow lines,	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Personal A steel marker at least 4" in diameter at OPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED C ✓ The location has been leveled as nearly other production equipment. ✓ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ✓ All metal bolts and other materials have to be removed.) ✓ All other environmental concerns have 	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been as possible to original ground contour and as possible to or	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with, production equipment and junk have been removed removed. (Poured onsite concrete bases do not have
 ✓ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Department of the production has been leveled as nearly other production equipment. ✓ Anchors, dead men, tie downs and rise of the interproduction of the operator's from lease and well location. ✓ All metal bolts and other materials have to be removed.) ✓ All other environmental concerns have pipelines and flow lines have been abar 	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been as possible to original ground contour and as possible to or	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with, production equipment and junk have been removed
 ☑ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at OPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED C ☑ The location has been leveled as nearly other production equipment. ☑ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ☑ All metal bolts and other materials have to be removed.) ☑ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. 	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and an amount and a second a second and a second and a second and a second and a second a sec	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have
 ☑ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at DPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED C ☑ The location has been leveled as nearly other production equipment. ☑ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ☑ All metal bolts and other materials have to be removed.) ☑ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. ☑ If this is a one-well lease or last remain 	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and a least two feet below as possible to original ground contour and are have been cut off at least two feet belowing well on lease, the battery and pit locat pit permit and closure plan. All flow lines are been removed. Portable bases have been addressed as per OCD rules. Indoned in accordance with 19.15.35.10 Nilming well on lease: all electrical service political service polit	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with, production equipment and junk have been removed removed. (Poured onsite concrete bases do not have
 ☑ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Department of the Department of the production equipment. ☑ Anchors, dead men, tie downs and rise of the Operator's from lease and well location. ☑ All metal bolts and other materials have to be removed.) ☑ All other environmental concerns have pipelines and flow lines have been abaretrieved flow lines and pipelines. ☑ If this is a one-well lease or last remailed to be removed.) ☑ All other environmental concerns have pipelines and flow lines have been abaretrieved flow lines and pipelines. ☑ If this is a one-well lease or last remailed location, except for utility's distribution information. 	AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE. The shave been cut off at least two feet belowing well on lease, the battery and pit locate pit permit and closure plan. All flow lines, the been addressed as per OCD rules. The been addressed as per OCD rules. The change well on lease: all electrical service potrastructure.	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well
 ☑ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at DPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED OF The location has been leveled as nearly other production equipment. ☑ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ☑ All metal bolts and other materials have to be removed.) ☑ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. ☑ If this is a one-well lease or last remain location, except for utility's distribution information. 	AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE. The shave been cut off at least two feet belowing well on lease, the battery and pit locate pit permit and closure plan. All flow lines, the been addressed as per OCD rules. The been addressed as per OCD rules. The change well on lease: all electrical service potrastructure.	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well
 ☑ Rat hole and cellar have been filled an ☑ A steel marker at least 4" in diameter at ☐ OPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED OF ☑ The location has been leveled as nearly other production equipment. ☑ Anchors, dead men, tie downs and rise ☑ If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ☑ All metal bolts and other materials have to be removed.) ☑ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. ☑ If this is a one-well lease or last remain 	AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE. The same been cut off at least two feet belowing well on lease, the battery and pit locate pit permit and closure plan. All flow lines are been removed. Portable bases have been addressed as per OCD rules. Indoned in accordance with 19.15.35.10 Number with the same well on lease: all electrical service polaristructure.	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with, production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well to schedule an inspection.
 ☑ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Department of the Department of the production has been leveled as nearly other production equipment. ☑ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. ☑ All metal bolts and other materials have to be removed.) ☑ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. ☑ If this is a one-well lease or last remain location, except for utility's distribution information. 	AME, WELL NUMBER, API NUMBER WNSHIP, AND RANGE. All INFORM ON THE MARKER'S SURFACE. The same been cut off at least two feet belowing well on lease, the battery and pit locate pit permit and closure plan. All flow lines are been removed. Portable bases have been addressed as per OCD rules. Indoned in accordance with 19.15.35.10 Number with the same well on lease: all electrical service polaristructure.	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well
□ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at DPERATOR NAME, LEASE NUNIT LETTER, SECTION, TO PERMANENTLY STAMPED C. □ The location has been leveled as nearly other production equipment. □ Anchors, dead men, tie downs and rise If this is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. □ All metal bolts and other materials have to be removed.) □ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. □ If this is a one-well lease or last remain location, except for utility's distribution information when all work has been completed, return SIGNATURE SIGNATURE SIGNAT	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and a possible to original ground contour and a possi	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well to schedule an inspection.
□ X steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at 10 DPERMANENTLY STAMPED CO PERMANENTLY STAMPED CO The location and seem to downs and rise and the terms of the Operator's from lease and well location. □ All metal bolts and other materials have to be removed.) □ All other environmental concerns have Pipelines and flow lines have been abaretrieved flow lines and pipelines. □ If this is a one-well lease or last remain location, except for utility's distribution information and when all work has been completed, return SIGNATURE □ A STATE	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and a possible to original ground contour and a possi	been properly abandoned. set in concrete. It shows the R. OUARTER/OUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well to schedule an inspection. ENTAL SPECIALIST_DATE
□ X steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker at least 4" in diameter at A steel marker SECTION, TO PERMANENTLY STAMPED COMMENTALY STAMPED COMMEN	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and a possible to original ground contour and a possi	been properly abandoned. set in concrete. It shows the R. OUARTER/OUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well to schedule an inspection. ENTAL SPECIALIST_DATE
□ Rat hole and cellar have been filled an A steel marker at least 4" in diameter at Department of the Permanent of the production equipment. □ The location has been leveled as nearly other production equipment. □ Anchors, dead men, tie downs and rise of the It is a one-well lease or last remain OCD rules and the terms of the Operator's from lease and well location. □ All metal bolts and other materials have to be removed.) □ All other environmental concerns have pipelines and flow lines have been abarretrieved flow lines and pipelines. □ If this is a one-well lease or last remain location, except for utility's distribution information of the It is a completed, return the It is a completed, return the It is a completed, return the It is a completed. TYPE OR PRINT NAME _WADE DITTERMEDITE.	d leveled. Cathodic protection holes have and at least 4' above ground level has been amount at least 4' above ground level has been amount at least 4' above ground level has been amount and a possible to original ground contour and a possi	been properly abandoned. set in concrete. It shows the R. QUARTER/QUARTER LOCATION OR ATION HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and ground level. ion(s) have been remediated in compliance with production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- les and lines have been removed from lease and well to schedule an inspection.