Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resour	ces Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-38637
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Artes 13, 27410	1220 South St. Francis Dr.	STATE S FEE
District IV – (505) 47(-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 201 87505	(	
SUNDRY NOTIC	ESAND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPINE OF PROPOSALS.)	TO DRILL OR TO DEEPEN OR PLUG BACK TO ATION FOR PERMIT" (FORM C-101) FOR SUCH	
	Gas Well  Other INJECTOR	8. Well Number 455
2. Name of Operator		9. OGRID Number
CHEVRON USA INC	/	1323
3. Address of Operator 1616 W. BENDER BLVD HOBBS	S, NM 88240	10. Pool name or Wildcat VACUUM; GRAYBURG SAN ANDRES
4. Well Location		
Unit Letter <u>D</u> : <u>131</u>	ofeet from theNORTH line and _	660 feet from theWEST line
Section 36	Township 17S Range 34E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT,	GR, etc.)
12. Check Ap	ppropriate Box to Indicate Nature of N	lotice, Report or Other Data
NOTICE OF INT	ENTION TO:	CLIPSEOLIENT DEDORT OF:
NOTICE OF INT PERFORM REMEDIAL WORK □	PLUG AND ABANDON ☐ REMEDIA	SUBSEQUENT REPORT OF:
TEMPORARILY ABANDON	The state of the s	CE DRILLING OPNS. P AND A
PULL OR ALTER CASING		CEMENT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	Workver
OTHER:  13. Describe proposed or complete	ted operations. (Clearly state all pertinent de	tails, and give pertinent dates, including estimated date
OTHER:  13. Describe proposed or complete	tted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult	
OTHER:  13. Describe proposed or comple of starting any proposed work proposed completion or recomplete.	tted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of
OTHER:  13. Describe proposed or completion of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult mpletion.  S REPAIRED THE ABOVE WELL AS FOLI	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of LOWS:
OTHER:  13. Describe proposed or completion of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS 12/08/2017 MIRU WRO, Kill	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult impletion.  S REPAIRED THE ABOVE WELL AS FOLI illed well, ND Inj tree, NUBOP, Tested BOP &	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of LOWS:
OTHER:  13. Describe proposed or complete of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS:  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line of On/off tool.	ted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult mpletion.  SREPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  SDON clean water, POOH with tubing laying it down and
OTHER:  13. Describe proposed or complet of starting any proposed work proposed completion or record CHEVRON USA INC. HAS 12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line On/off tool. 12/12/2017 Check pressure,	ted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult mpletion.  SREPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  2 SDON clean water, POOH with tubing laying it down and 0 PSI, Move out fiberlined tubing and move in work
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or recompleted in the starting any proposed work proposed completion or recompleted in the starting and proposed work proposed completion or recompleted in the starting and proposed work proposed work proposed work proposed with the starting and proposed work proposed wore	ted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult mpletion.  SREPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  SDON clean water, POOH with tubing laying it down and
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS:  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole a	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS:  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.	ted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult mpletion.  SREPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS:  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole a	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or reconstruction.  CHEVRON USA INC. HAS:  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole a	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and
OTHER:  13. Describe proposed or complete of starting any proposed work proposed completion or reconsistance.  CHEVRON USA INC. HAS  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.  ORIGINAL MIT CITAL COMPLET COMPLETE	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult impletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTIN	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and
OTHER:  13. Describe proposed or complete of starting any proposed work proposed completion or reconsistance.  CHEVRON USA INC. HAS  12/08/2017 MIRU WRO, Kill 12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.  ORIGINAL MIT CITAL COMPLET COMPLETE	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult impletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTIN	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or recompleted to the proposed completed to the proposed completed to the proposed	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Mult impletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTIN	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON  clean water, POOH with tubing laying it down and  O PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and  UED ON NEXT PAGE
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or recompleted in the starting any proposed work proposed completion or recompleted in the starting and proposed work proposed completion or recompleted in the starting and proposed work pr	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4" perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTIN Rig Release Date:	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of LOWS:  ESDON clean water, POOH with tubing laying it down and 0 PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and UED ON NEXT PAGE
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or recompleted in the starting any proposed work proposed completion or recompleted in the starting and proposed work proposed completion or recompleted in the starting and proposed work pr	sted operations. (Clearly state all pertinent de k). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  S REPAIRED THE ABOVE WELL AS FOLI lled well, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4" perforated sub latch on circulate hole a HART AND COPY ATTACHED, CONTIN Rig Release Date:	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of LOWS:  ESDON clean water, POOH with tubing laying it down and 0 PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and UED ON NEXT PAGE
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or recompleted to the proposed completed to the proposed completed to the proposed completed to the proposed to the	sted operations. (Clearly state all pertinent deck). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  SREPAIRED THE ABOVE WELL AS FOLIABLE WELL, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTINE Rig Release Date:  Bove is true and complete to the best of my known is true and complete to the best of my known in the permitting specific permitting specif	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of LOWS:  ESDON clean water, POOH with tubing laying it down and 0 PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and UED ON NEXT PAGE
OTHER:  13. Describe proposed or complete of starting any proposed work proposed completion or recomplete.  CHEVRON USA INC. HAS   12/08/2017 MIRU WRO, Kill  12/11/2017 Rig up wire line on/off tool.  12/12/2017 Check pressure, String. RIH with on/off tool, Plug to 4315'.  ORIGINAL MIT Complete Spud Date:	sted operations. (Clearly state all pertinent deck). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  SREPAIRED THE ABOVE WELL AS FOLIABLE WELL, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTINE Rig Release Date:  Bove is true and complete to the best of my known is true and complete to the best of my known in the permitting specific permitting specif	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON  clean water, POOH with tubing laying it down and  0 PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and  UED ON NEXT PAGE  dowledge and belief.  DATE 12/20/2017
OTHER:  13. Describe proposed or completed of starting any proposed work proposed completion or recompleted to the proposed completed to the proposed completed to the proposed completed to the proposed to the	sted operations. (Clearly state all pertinent deck). SEE RULE 19.15.7.14 NMAC. For Multimpletion.  SREPAIRED THE ABOVE WELL AS FOLIABLE WELL, ND Inj tree, NUBOP, Tested BOP & to set 1.43 plug in packer, Circulate hole with Tubing N/A, 7" 0 PSI, 9 5/8 1300 PSI 13 3/8 and 4' perforated sub latch on circulate hole at HART AND COPY ATTACHED, CONTINE Rig Release Date:  Bove is true and complete to the best of my known is true and complete to the best of my known in the permitting specific permitting specif	tails, and give pertinent dates, including estimated date iple Completions: Attach wellbore diagram of  LOWS:  ESDON  clean water, POOH with tubing laying it down and  0 PSI, Move out fiberlined tubing and move in work and release packer POOH. RIH with 7" packer and  UED ON NEXT PAGE  dowledge and belief.  IALIST  DATE 12/20/2017

RBDMS-CHART-

## **Repair Work Continued**

**12/13/2017** Rig up wireline and pull 1.43 profile plug. Pump down tubing to see if there is any migration up the 9 5/8. Keeping pressure in 7" to 500 PSI Maximum. RIH with injection packer and set and test it to 500 PSI (held). Get off on/off tool and pull 1 joint shut down.

**12/14/2017** Check pressure, pull out laying down work string, RIH with TK 99 and on/off tool. Circulate packer fluid.

**12/15/2017** Check PSI and hanger, nipple down BOP< nipple up wellhead. Chart test casing for 30 minutes with George Bower/ NMOCD witnessing test. Rig down move off location.



