Submit I Copy To Appropriate District Office	State of New Mexico)	Form C-1	
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2	011
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	183		WELL API NO. 30-025-27001	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	_
District III - (505) 334-6178	1220 South St. Francis Dr.		STATE FEE FEE	ed
1000 Rio Brazos Rd , Aztec, NM 87410 District IV - (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				
87505	SEC AND REPORTS ON WELLS		7 I am Name on Heit A manuart Name	_
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Lease Name or Unit Agreement Nam North Hobbs (G/SA) Unit	6	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Section 30		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Injector		8. Well Number: 442		
2. Name of Operator		9. OGRID Number: 157984	-	
Occidental Permian Ltd.		9, OGRID Nulliber, 137984		
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA	0	
HCR I Box 90 Denver City, TX 793	323			´
4. Well Location				
	00 feet from the South line and	d 1050	feet from the East line	
Section 30		lange 38E	NMPM Lea County	
	11. Elevation (Show whether DR, RK)	the state of the s	The state of the s	198
	3657' KB			
12. Check A	ppropriate Box to Indicate Natur	e of Notice,	Report or Other Data	
NOTICE OF IN	EENTION TO:	CLID	SEQUENT DEPORT OF	
NOTICE OF IN	The state of the s		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING [-
TEMPORARILY ABANDON				
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	SING/CEMEN	30B	
DOWNHOLE COMMINGLE				
OTHER:		HER:		
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of 				
		or Multiple Con	npletions: Attach wellbore diagram of	
proposed completion or reco	mpletion.			
1. MIRU Pulling Unit			to use	
2. POOH with injection equipment		During this	procedure we plan to use	
3 Selectively add new perforations in Zone 2C between 4085'-4130' the closed-			loop system with a steel	
4. Acidize all perforations. tank and h			aul contents to the required	
5. RIH with injection equipment disposal po			r ODC Rule 19.15.17	
6. Turn well to injection.		disposal pe	. 000	
7.	and the second second			
8. Condition of Ap	proval: notify			
OCD Hobbs of	lice 24 nours			
prior of running M	IT Test & Chart			
Spud Date:	Rig Release Date:			
, A				
I have have a sife of the shade in formation of	h	6 1 1 d	and hallof	
I hereby certify that the information a	bove is true and complete to the best of	i my knowledge	e and benef.	
1.0.1	, , , , , , , , , , , , , , , , , , , ,			
SIGNATURE / lub / luc	·			
	·	DATE /	2/27/17	
	TITLE Prod Es,			
	·			
For State Use Only	TITLE 12vd E, E-mail address rick ree			
For State Use Only	TITLE 12vd E, E-mail address rick ree		PHONE: 713-215-7653	Q
For State Use Only	TITLE Prod Es,			8