Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103 Revised July 18, 2013
District I – (575) 393-6161 Energy 1625 N. French Dr., Hobbs, NM 88240	, Minerals and Natural Resources	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL C	CONSERVATION DIVISION	30-025-44013 5. Indicate Type of Lease
District III - (505) 334-6178 1 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE X FEE
$\frac{\text{District IV}}{1220 \text{ S. St. Francis Dr., Santa Fe, NM}}$	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Florence State 23 23 34 AR
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other		8. Well Number 202H
As a second		9. OGRID Number 228937
3. Address of Operator		10. Pool name or Wildcat
5400 LBJ Freeway, Ste. 1500, Dallas, TX 75240		WC-025 G-06S233423N;WOLFCAMP
4. Well Location		
	eet from the <u>S</u> line and	1767feet from the line
	ownship 23S Range 34E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3403' GR		
12. Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION	I TO: SUE	SEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE		
CLOSED-LOOP SYSTEM		_
OTHER: 13 Describe proposed or completed operation	X OTHER:	d give partinent dates including estimated date
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU</li> </ol>	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D.</li> </ol>	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co g, operator did not witness a wiper plu . 330' toe-hardline is at 16,053' M.D. F	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached.
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.</li> <li>While cementing the production casing Current casing shoe is at 16,139' M.D.</li> <li>The production casing will be pressure</li> </ol>	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co g, operator did not witness a wiper plu . 330' toe-hardline is at 16,053' M.D. F	uppletions: Attach wellbore diagram of uppletions.
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.</li> <li>While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> </ol>	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co g, operator did not witness a wiper plu . 330' toe-hardline is at 16,053' M.D. F tested. If casing integrity pressure te	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr.</li> </ol>	Display the second seco	impletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing.
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p</li> </ol>	processing integrity test to 6,000 processing integrity test test test processing integrity test test processing integrity test test processing integrity test processing integrit	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test,
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation and the protection and the protection.</li> </ol>	processing the second s	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing</li> </ul>	ns. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co g, operator did not witness a wiper plu . 330' toe-hardline is at 16,053' M.D. F tested. If casing integrity pressure test nd wet shoe is indicated, plan to set a perform casing integrity test to 6,000 p ion and stimulation procedures of orig g isolation from shoe to remainder of v	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the wellbore.
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing</li> </ul>	provide the state all pertinent details, and JLE 19.15.7.14 NMAC. For Multiple Co g, operator did not witness a wiper plut. 330' toe-hardline is at 16,053' M.D. For tested. If casing integrity pressure test Paul Kautz, are to first pressure test and wet shoe is indicated, plan to set a perform casing integrity test to 6,000 p ion and stimulation procedures of origing isolation from shoe to remainder of vequipment for this operation starting 1	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, inal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing Operator plans to move in and rig up experiment.</li> </ul>	provide the state all pertinent details, and JLE 19.15.7.14 NMAC. For Multiple Co g, operator did not witness a wiper plut. 330' toe-hardline is at 16,053' M.D. For tested. If casing integrity pressure test Paul Kautz, are to first pressure test and wet shoe is indicated, plan to set a perform casing integrity test to 6,000 p ion and stimulation procedures of origing isolation from shoe to remainder of vequipment for this operation starting 1	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, inal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> </ul>	Paul Kautz, are to first pressure test on and stimulation procedures of orig isolation from shoe to remainder of v equipment for this operation starting 1 20/2018. Operator will send successful	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the vellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz.
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing Operator plans to move in and rig up experiment.</li> </ul>	Paul Kautz, are to first pressure test of wet shoe is indicated, plan to set a procedure of oregoin and stimulation procedures of orig g solution from shoe to remainder of v equipment for this operation starting 1 0/2018. Operator will send successful	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, inal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> </ul>	Paul Kautz, are to first pressure test on and stimulation procedures of orig isolation from shoe to remainder of v equipment for this operation starting 1 20/2018. Operator will send successful	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the vellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz.
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforatic casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> </ul>	Paul Kautz, are to first pressure test         Ind wet shoe is indicated, plan to set a         perform casing integrity test to 6,000 p         isolation from shoe to remainder of v         equipment for this operation starting 1         0/2018. Operator will send successful         Rig Release Date:	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz.
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> <li>Spud Date:</li> </ul>	Paul Kautz, are to first pressure test         Ind wet shoe is indicated, plan to set a         perform casing integrity test to 6,000 p         isolation from shoe to remainder of v         equipment for this operation starting 1         0/2018. Operator will send successful         Rig Release Date:	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz.
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforation casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> <li>Spud Date:</li> </ul>	Paul Kautz, are to first pressure test         Ind wet shoe is indicated, plan to set a         perform casing integrity test to 6,000 p         isolation from shoe to remainder of v         equipment for this operation starting 1         0/2018. Operator will send successful         Rig Release Date:	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz.
<ul> <li>13. Describe proposed or completed operatio of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforatic casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> <li>Spud Date: 11/09/2017</li> </ul>	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co         g, operator did not witness a wiper plu. 330' toe-hardline is at 16,053' M.D. For tested. If casing integrity pressure test ind wet shoe is indicated, plan to set a berform casing integrity test to 6,000 p ion and stimulation procedures of origing isolation from shoe to remainder of variable and complete to the best of my knowledge         Rig Release Date:       12/0         TITLE_Completions Engineer       12/0	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a usi for 30 minutes. After a successful casing test, jinal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz. 05/2017 ge and belief. 
<ul> <li>13. Describe proposed or completed operatio of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforatic casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> <li>Spud Date: 11/09/2017</li> </ul>	and complete to the best of my knowledge         TITLE Completions Engineer	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, inal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz. 05/2017 ge and belief. 
<ul> <li>13. Describe proposed or completed operatio of starting any proposed work). SEE RU proposed completion or recompletion. While cementing the production casing Current casing shoe is at 16,139' M.D. The production casing will be pressure procedure will be followed:</li> <li>Operator plans, as discussed with Mr. If casing integrity pressure test fails ar depth of 16,006' M.D. and then then p we will continue with planned perforatic casing for the life of the well, providing Operator plans to move in and rig up e casing integrity test completed by 1/10</li> <li>Spud Date: 11/09/2017</li> <li>I hereby certify that the information above is true SIGNATURE Waylon Wolf</li> </ul>	ons. (Clearly state all pertinent details, an JLE 19.15.7.14 NMAC. For Multiple Co         g, operator did not witness a wiper plu. 330' toe-hardline is at 16,053' M.D. For tested. If casing integrity pressure test ind wet shoe is indicated, plan to set a berform casing integrity test to 6,000 p ion and stimulation procedures of origing isolation from shoe to remainder of variable and complete to the best of my knowledge         Rig Release Date:       12/0         TITLE_Completions Engineer       12/0	mpletions: Attach wellbore diagram of ug bump. Pre-frac plat attached. st fails and wet shoe is indicated, the following the production casing. composite bridge plug rated to 10,000 psi at a si for 30 minutes. After a successful casing test, inal design. The bridge plug will remain in the wellbore. /6/2018 and plans to have the new successful results to Mr. Paul Kautz. 05/2017 ge and belief. 