

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.  
NMNM62667

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
EUMONT 33 FED 019. API Well No.  
30-025-33171-00-S110. Field and Pool or Exploratory Area  
EUMONT11. County or Parish, State  
LEA COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator  
MEWBOURNE OIL COMPANYContact: JACKIE LATHAN  
E-Mail: jlathan@mewbourne.com3a. Address  
P O BOX 5270  
HOBBS, NM 882413b. Phone No. (include area code)  
Ph: 575-393-5905

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 33 T20S R37E SESE 660FSL 660FEL

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

## TYPE OF SUBMISSION

## TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other  
Change to Original A  
PD

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Please review the attached plugging procedure for the above captioned well.

**Carlsbad Field Office**  
**OCD Hobbs****SEE ATTACHED FOR  
CONDITIONS OF APPROVAL***See Attach Revised P&A Procedure*

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #401207 verified by the BLM Well Information System  
For MEWBOURNE OIL COMPANY, sent to the Hobbs  
Committed to AFMSS for processing by PRISCILLA PEREZ on 01/25/2018 (18PP0462SE)**

Name (Printed/Typed) JACKIE LATHAN

Title AUTHORIZED REPRESENTATIVE

Signature (Electronic Submission)

Date 01/17/2018

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By ZOTA STEVENS

Title PETROLEUM ENGINEER

Date 02/23/2017

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

**COMPLETION PROCEDURE**

Submitted By: C.Walker

**Wellname:** Eumont 33 Federal #1

**Location:** 660' FSL & 660' FEL  
Sec 33, T20S, R37E  
Lea Co, NM

**Date:** 1/16/2018

**Csg Set:** 3850.05'

**Packer Type:** N/A

**Csg Size:** 4 1/2" 11.6# K-55

**Packer Depth:** N/A

**Liner Size:** N/A

**Tbg:** 2 3/8" 4.7# J-55

**Liner Top:** N/A

**Tbg Set:** 3571'

**Ports:** N/A

**Total Rods:** 3530'

**Procedure:**

1. MIRU BCM. ND wellhead & NU BOP. Release pkr & POOH w/tbg.
2. RIH w/CIBP & working string.
3. Set CIBP @ 3550' (perfs @ 3576'-3600').
4. Test csg to 500#. Locate any csg leak.
5. POOH w/tbg and LD setting tool.
6. RIH w/tbg & spot 25 sks Class "H" cmt on top of CIBP. WOC & tag.
7. Spot 120' plug from 2850'-2970'(Yates). WOC & tag. *130' plug spot from 2970'-2840'*
8. Spot 120' plug from 2400'-2520'(Base of Salt). WOC & tag.
9. Spot 120' plug from 1500'-1620'(Top of Salt). WOC & tag.
10. Spot 120' plug from 370'-490'(Shoe). WOC & tag.
11. Perf @ 60'. Circulate cement to surface and verify csg and annulus cmt'd to surface.
12. RDMO BCM.
13. Cut off WH & install dry hole marker @ ground level.
14. Perform reclamation of location in accordance to BLM regulations.

Eumont 33 Federal #1

# Eumont 33 Federal #1 - Wellbore Diagram After P&A

Last Updated: 1/15/2018

By: Connor Walker

Spud Date: 1/27/1996

12 1/4"x8 5/8" 24 & 32#  
400'

60' to surface  
Class C cement

120' plug @ 370' - 490' (Shoe)

120' plug @ 1500' - 1620' (Top of Salt)

120' plug @ 2400' - 2520' (Base of Salt)


120' plug @ 2850' - 2970' (Yates)

25 sx Class "H" cmt plug

CIBP @ 3550'

Perfs:  
3576' - 3600'  
96 holes

11.6' #  
7 7/8"x4 1/2" 15.5# & 17#  
3850'



# Eumont 33 Federal #1 - Wellbore Diagram Before P&A

Last Updated: 1/15/2018

By: Connor Walker

Spud Date: 1/27/1996

12 1/4"x8 5/8" 24 & 32#

400'

Perfs:  
3576' - 3600'  
96 holes

11-6-7#  
7 7/8"x4 1/2" 15.5# & 47#  
3850'

EOT @ 3571.76

*Yates 2697*  
*Seven Rivers 292940*  
*Queen 3436*  
*Denrose 343543*  
*Grayburg 3727*

## Current Tbg Detail

1 2 3/4" J55 jt w/ BP	32.04
1 2 3/4" perf sub	4.10
1 2 3/4" SN	1.10
110 2 3/4" 4.7# J55 tbg	3524.52
Total tbg	3561.76
KB Corr	10.00
EOT @	3571.76
1 2" x 1 1/2" x 12' RHBC Pump (M-529) w/8' G/8'	
1 3/4" Guided Pony Rod	2'
1 HF O/O tool	1'
140 3/4" Grade D Rods	3500'
1 1 1/4" x 16' PR w/1 1/2" x 8' PRL	16'
Total Rods	3531'



## REVISED P&A PROCEDURES.

1. MIRU BCM, ND wellhead & NU BOP. Release pkr & POOH w/tbg.
2. RIH w/CIBP & working string.
3. Set CIBP @ 3550' (perfs @ 3576'-3600).
4. Test csg to 500#. Locate any csg leak.
- 5.--POOH w/tbg and LD setting tool.
6. RIH w/tbg & Spot 25 sks "H" cmt on top of CIBP WOC & tag.
7. Spot 130ft plug from 2840-2970' (Yates). WOC & tag.
8. Spot 125 ft plug from 2395'-2520(Base of Salt). WOC & tag.
9. Spot 120' plug from 1500'-16201(Top of Salt). WOC & tag.
10. Spot 120' plug from 370'-490'(Shoe). WOC & tag
11. Perf at 60'. Circulate cement to surface and verify csg and annulus cmt'd to surface.
12. RDMO BCM.
13. Cut off WI-I & install dry hole marker @ ground level.
14. Perform reclamation of location in accordance to BLM regulations.

**BUREAU OF LAND MANAGEMENT  
Carlsbad Field Office  
620 East Greene Street  
Carlsbad, New Mexico 88220  
575-234-5972**

**Permanent Abandonment of Federal Wells  
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon.

**If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.**

**The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.**

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.**

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.