Submit 1 Copy To Appropriate District	State of New Me	Form C-103				
Office District I – (575) 393-6161	Energy, Minerals and Natu	Revised July 18, 2013				
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.				
<u>District II</u> – (575) 748-1283	OIL CONSERVATION	30-041-20819				
811 S. First St., Artesia, NM 88210		5. Indicate Type of Lease				
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE 🖂			
istrict IV – (505) 476-3460	Santa Fe, NM	3 05	6. State Oil & Gas Lease No.			
220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM	E 5010				
87505	Santa Fe, NM STATE STATE STATE STATE STATE OF THE STATE OF THE STATE STA	010				
SUNDRY NOT	TICES AND REPORTS ON WEL	AN	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR PLU	UG BACK TO A	SPEIGHT			
DIFFERENT RESERVOIR. USE "APPL	ICATION FOR PERMIT" (FORM C-101) FO	OR SUCH				
I ROI OSALS.)		Ken	8. Well Number 001			
	1. Type of Well: Oil Well Gas Well Other					
2. Name of Operator			9. OGRID Number			
SOVEREIGN EAGLE LLC			263940			
3. Address of Operator			10. Pool name or Wildcat			
PO BOX 968, ROSWELL NM 88	202-0968		TULE MONTOYA;PENN			
4. Well Location						
	6 . 6 1 . 6 1 . 1 . 1 . 1 . 1 .	0.001	C.T. I'			
	feet from the <u>South</u> line and <u>1280</u>					
Section 22 Township	<u>2S</u> Range <u>29E</u> NMPM	County Roose	evelt Unit			
	11. Elevation (Show whether DR,	PKR PT CP ata				
	4388'	, KKD, K1, OK, etc.)				
	4300					
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data			
			•			
NOTICE OF II	NTENTION TO:	SUBS	SEQUENT			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK				
TEMPORARILY ABANDON		COMMENCE DRII				
		CASING/CEMENT				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMENT				
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM	MULTIPLE COMPL		P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER:	MULTIPLE COMPL	OTHER:	P&A NR P&A R			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM THER: 13. Describe proposed or com	MULTIPLE COMPL	OTHER:	P&A NR P&A R If give pertinent dates, including estimated date			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w	MULTIPLE COMPL pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC	OTHER:	P&A NR P&A R			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	OTHER:	P&A NR P&A R If give pertinent dates, including estimated date			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	OTHER:	P&A NR P&A R If give pertinent dates, including estimated date			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	OTHER: pertinent details, and C. For Multiple Con	P&A NR P&A R If give pertinent dates, including estimated date			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU	pleted operations. (Clearly state all prork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA F	OTHER: pertinent details, and C. For Multiple Con	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM THER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892	pleted operations. (Clearly state all prork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA F	OTHER: pertinent details, and C. For Multiple Con	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM THER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids.	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½ d and leave 100' of cement inside ca	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG.	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside cad 4. 8 5/8" casing shoe at 2180'. Per	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Starting and leave 100' of cement inside cat 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. 2130 &	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx or BETTER.	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee t under a packer into	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Perf casing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and squeeze holes with cement until the squeeze holes with a squeeze	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into	P&A NR P&A R digive pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. 0'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Perf casing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and squeeze holes with cement until the squeeze holes with a squeeze	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Perf casing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and squeeze holes with cement until the squeeze holes with a squeeze	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into	P&A NR P&A R digive pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. 0'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Perf casing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and squeeze holes with cement until the squeeze holes with a squeeze	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into	P&A NR P&A R digive pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. 0'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Starting and leave 100' of cement inside cate 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. DON: GAT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx and squeeze holes with cement until level, verify cement to surface, INS	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates GTALL DRY HOLE	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Starting and leave 100' of cement inside cate 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and squeeze holes with cement until the squeeze holes with a squeeze	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates GTALL DRY HOLE	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Starting and leave 100' of cement inside cate 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. DON: GAT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx or SETTER. f 370's squeeze holes with cement until level, verify cement to surface, INS	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates GTALL DRY HOLE	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892. Seluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside cat 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 of 5. 13 3/8" casing shoe at 320'. Perform 6. Cut off wellhead 3' below grounds.	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. DON: GAT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx or SETTER. f 370's squeeze holes with cement until level, verify cement to surface, INS	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates GTALL DRY HOLE	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Starting and leave 100' of cement inside cate 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 & 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. DON: GAT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx or SETTER. f 370's squeeze holes with cement until level, verify cement to surface, INS	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates GTALL DRY HOLE	P&A NR P&A R If give pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. O'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 of 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground I hereby certify that the information	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. 12230' and squeeze holes with 35 sx and leave to case the state of the state of the state of the state of the squeeze holes with 35 sx and leave to case the state of the s	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates STALL DRY HOLE est of my knowledge	P&A NR P&A R digive pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. 0'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION. Each of the packer into squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM THER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Starting structures fluids. 3.TOP OF CEMENT behind 5 ½" and leave 100' of cement inside cat 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. 2130 & 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground structures for the structure of the structure	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. DON: GAT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze hole sing. WOC & TAG. f 2230' and squeeze holes with 35 sx or SETTER. f 370's squeeze holes with cement until level, verify cement to surface, INS	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates STALL DRY HOLE est of my knowledge	P&A NR P&A R digive pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. 0'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION. Each of the packer into squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Percasing. WOC & TAG. @ 2130 of 5. 13 3/8" casing shoe at 320'. Perf 6.Cut off wellhead 3' below ground I hereby certify that the information	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes with 35 sx and leave to casing. WOC & TAG. If 2230' and squeeze holes with cement until level, verify cement to surface, INSTANCE INSTA	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates TALL DRY HOLE est of my knowledge ATIONS MANAGI	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Stationary fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside cate 4. 8 5/8" casing shoe at 2180'. Performing. WOC & TAG. 2130 & 5. 13 3/8" casing shoe at 320'. Performing for the state of the stat	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes with 35 sx and leave to casing. WOC & TAG. If 2230' and squeeze holes with cement until level, verify cement to surface, INSTANCE INSTA	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates TALL DRY HOLE est of my knowledge ATIONS MANAGI	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . S fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside ca 4. 8 5/8" casing shoe at 2180'. Performing and the second of t	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes with 35 sx and leave to casing. WOC & TAG. If 2230' and squeeze holes with cement until level, verify cement to surface, INSTANCE INSTA	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates TALL DRY HOLE est of my knowledge ATIONS MANAGI	P&A NR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE LOSED-LOOP SYSTEM OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or re PROPOSE TO PLUG AND ABAN 1.SET CAST IRON BRIDGE PLU 2. CANYON PERFS 6780-6892 . Stationary fluids. 3.TOP OF CEMENT behind 5 ½" of and leave 100' of cement inside cate 4. 8 5/8" casing shoe at 2180'. Performing. WOC & TAG. 2130 & 5. 13 3/8" casing shoe at 320'. Performing for the state of the stat	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion. IDON: G AT 7005' ABOVE MONTOYA For Squeeze perfs with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes sing. WOC & TAG. If 2230' and squeeze holes with 35 sx and leave to casing is 6280'. Perf 4 squeeze holes with 35 sx and leave to casing. WOC & TAG. If 2230' and squeeze holes with cement until level, verify cement to surface, INSTANCE INSTA	OTHER: pertinent details, and C. For Multiple Con PERFS 7065-7098' A op of cement at 6686 es at 4500' and squee a under a packer into il cement circulates TALL DRY HOLE est of my knowledge ATIONS MANAGI	P&A NR P&A R digive pertinent dates, including estimated date impletions: Attach wellbore diagram of AND DUMP 35' OF CEMENT ON IT. 0'. WOC & TAG Load hole with mud laden eze 35 sacks under a packer into squeeze perfs of squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION. Each of the packer into squeeze perfs and leave 100' of cement inside leaving casing full of cement. MARKER AND CLEAN LOCATION.			

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS

C103 INTENT TO P&A EXPIRES 03-20-2019

COMPANY		LEASE TYPE				API NO.		SPUD DATE
SOVEREIGN EAGLE, LLC		STATE X FEE FEDERAL		#30-041-20819		10/14/87		
WELL NAME	SECTION	TWP.		RA	NGE	COUNT	Y / STATE	COMP. DATE
SPEIGHT #1	22	2-S		29-E		ROOSEVELT / NM		01/29/88
FOOTAGE 1400' FSL & 1280' FEL	ELEVATION = 4388'	KELLY BUSHING = STATUS 4398' GAS			TOTAL DEPTH = 7200'		<u>P.B.T.D.</u> /122'	
FIELD/POOL/AREA		Size	Sks. Cmt.	TOC	Weight	Grade	Thread	Depth
TULE	SURF. CASING	13 3/8"	300	CIRC.	68#			320'
LOCATION DESCRIPTION	INT. CASING	8 5/8""	800	CIRC.	24#			2,180'
40.44.044.05.51.045.414	CASING	5 1/2"	250	6270'	17#			7,199'
19 MI SW OF FLOYD,NM Depth ft.	Description					O.D.	Length	Depth
300	13 3/8" CSG. 68# @3	13 3/8" CSG. 68# @320' w/300 sacks						320'
1000				-				
2000								
	8 5/8" CSG. 24# SET	8 5/8" CSG. 24# SET @ 2180' w/800 sacks						2180'
3000								
4000								
5000								
6000	2 7/8" tbg in place							
	TAC @ 6585							
	SEAT NIPPLE @ 706	6						
	MUD JOINT @ 7102							
	T.O.C. = 6280' by CBL 10/02/03							TOC=6280'
6500		41						
	10/12/10- Set PKR @							
	01/19/88 CANYON O	RTED						
	02/13/09 Basal Canyo							
	01/18/88 PENN "C" s		ACIDIZE w/200	0 gal. 15% MCA				
	02/42/00 Peen HAH 60	O Ed! Acidina w/		T SQUEEZED	9/2003			
	02/12/09 Penn "A" 6939-51'. Acidize w/ 900 gal 7 1/2 % NeFe 02/10/09 Penn "C" ss 6985-92'. Acidize w/ 1000 gal 7 1/2% NeFe							
	CEMENT SQUEEZED 9/2003							
7000	01/20/88 SET OTIS WA PACKER @ 7048' (DRILLED OUT 9/2003)							
	01/15/88 MONTOYA: PERF. 7084'-98' ACIDIZE w/2000 gal. 15% MCA (10/06/03 MONTOYA ADD. PERF: 7065'-75 ' & 7109'-19' A/w 5000 gal. 15% NEFE)							7199'
	(1.000.00 MORTO TRADE.T ENT. 1000-10 & 1100-10 PVW 0000 gai. 1070 NEFE)							
	5 1/2" CSG. 17# SET @ 7199' w/ 250 sacks					SOVEREIGN EAGLE, LLC		
8000	TD = 7200'	PBTD	= 7122'		Van Dack		P.O. BOX	
COMMENTS:	=Existing Packer =Tubing Anchor					ROSWELL, NEW MEXICO		
MONTOYA TOP = 7058'				=Perf	s-Open		88202	
PRECAMBRIAN TOP = 7133' WATER ANALYSIS: SCALING				=Perfs	-Squeezed		Revised 07/11/20	14