Office		exico	Form C-10	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ıral Resources	Revised July 18, 201	13
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-025-31807	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra	eis Du	STATE STEE	
District IV – (505) 476-3460	Santa Fenna 8	7505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	""	7505 N 07 2018		
	CES AND REPORTS ON WELLS	MED	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN OR PL	UG BACKING A	,	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG PAGENTE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) POSALS.)		CENTRAL VACUUM UNIT		
1. Type of Well: Oil Well	Gas Well Other		8. Well Number #212	
2. Name of Operator			9. OGRID Number	
CHEVRON USA INC			4323 10. Pool name or Wildcat	
3. Address of Operator 1616 W. BENDER BLVD HOBBS, NM 88240		VACUUM;GRAYBURG-SAN ANDRES		
4. Well Location	· · · · · · · · · · · · · · · · · · ·		, <u> </u>	
Unit Letter H: 15	41 feet from the <u>NORTH</u> li	ne and <u>181</u> feet	from the EAST line	-
Section 25	Township 17S Range	34E NMPM	1 County LEA	
	11. Elevation (Show whether DR	, RKB, RT, GR, etc.)		
	3994' GL			
12. Check A	Appropriate Box to Indicate N	lature of Notice, I	Report or Other Data	
		•	•	
NOTICE OF IN			SEQUENT REPORT OF:	,
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		j 1
TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRIL		J
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MOLTIPLE COMPL	CASING/CEMENT	10B	
CLOSED-LOOP SYSTEM				
OTHER:	П	OTHER:	П	
			——————————————————————————————————————	
	leted operations. (Clearly state all	pertinent details, and	give pertinent dates, including estimated da	— ate
13. Describe proposed or comp			give pertinent dates, including estimated dan pletions: Attach wellbore diagram of	 ate
13. Describe proposed or comp	ork). SEE RULE 19.15.7.14 NMA		give pertinent dates, including estimated dan pletions: Attach wellbore diagram of	ate
13. Describe proposed or comp of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 NMA ompletion.	C. For Multiple Con	npletions: Attach wellbore diagram of	ate
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I	ork). SEE RULE 19.15.7.14 NMA	C. For Multiple Con	npletions: Attach wellbore diagram of	ate
13. Describe proposed or comp of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 NMA ompletion.	C. For Multiple Con	npletions: Attach wellbore diagram of	ate
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP a	C. For Multiple Con THE ABOVE SUB.	npletions: Attach wellbore diagram of	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test w	THE ABOVE SUB. and dump cement, cirith NMOCD.	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, or the control of the circulate packer fluid.	THE ABOVE SUB: and dump cement, cir ith NMOCD. confirm MIT test wit	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, of the mith tubing and witnessed by North tubing and witnessed by	THE ABOVE SUB: and dump cement, cir ith NMOCD. confirm MIT test wit	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, or the control of the circulate packer fluid.	THE ABOVE SUB: and dump cement, cir ith NMOCD. confirm MIT test wit	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, of the mith tubing and witnessed by North tubing and witnessed by	THE ABOVE SUB: and dump cement, cir ith NMOCD. confirm MIT test wit	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N NDBOP, NUWH, confirm	ork). SEE RULE 19.15.7.14 NMAGOMPHETION. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test word with tubing and L/D. NDBOP, of the control	THE ABOVE SUB. THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with IMOCD RD WSU ar ig unit,	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N	ork). SEE RULE 19.15.7.14 NMAGO ompletion. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, of the mith tubing and witnessed by North tubing and witnessed by	THE ABOVE SUB. THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with IMOCD RD WSU ar ig unit,	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N NDBOP, NUWH, confirm	ork). SEE RULE 19.15.7.14 NMAGOMPHETION. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test word with tubing and L/D. NDBOP, of the control	THE ABOVE SUB. THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with IMOCD RD WSU ar ig unit,	npletions: Attach wellbore diagram of JECT WELL. TA PROCEDURE rculate packer fluid. MIT test with NMOCD th NMOCD. R/D.	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 M NDBOP, NUWH, confirm Spud Date:	ork). SEE RULE 19.15.7.14 NMAGOMPHETION. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test word with tubing and L/D. NDBOP, of the MIT test and witnessed by NMIT test with NMOCD, R/D puling Rig Release Date.	THE ABOVE SUB. THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with IMOCD RD WSU are g unit, ate:	IPCT WELL. TA PROCEDURE reculate packer fluid. MIT test with NMOCD th NMOCD. R/D. and Move off well	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N NDBOP, NUWH, confirm	ork). SEE RULE 19.15.7.14 NMAGOMPHETION. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at t, circulate packer fluid. MIT test word with tubing and L/D. NDBOP, of the MIT test and witnessed by NMIT test with NMOCD, R/D puling Rig Release Date.	THE ABOVE SUB. THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with IMOCD RD WSU are g unit, ate:	IPCT WELL. TA PROCEDURE reculate packer fluid. MIT test with NMOCD th NMOCD. R/D. and Move off well	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N NDBOP, NUWH, confirm Spud Date:	ork). SEE RULE 19.15.7.14 NMAGOMPHETION. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at a circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, of the mith tubing and the with test with NMOCD, R/D puling the mith test with test with NMOCD, R/D puling the mith test with R/D puling the mith test with test with R/D puling the mith t	THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with MOCD RD WSU ar g unit, ate:	propose the procedure of the procedure o	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N NDBOP, NUWH, confirm Spud Date:	ork). SEE RULE 19.15.7.14 NMAGOMPHETION. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at a circulate packer fluid. MIT test work of the with tubing and L/D. NDBOP, of the mith tubing and the with test with NMOCD, R/D puling the mith test with test with NMOCD, R/D puling the mith test with R/D puling the mith test with test with R/D puling the mith t	THE ABOVE SUB. and dump cement, cir ith NMOCD. confirm MIT test with MOCD RD WSU ar g unit, ate:	propose the procedure of the procedure o	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 N NDBOP, NUWH, confirm Spud Date: I hereby certify that the information	ork). SEE RULE 19.15.7.14 NMAGOMPLETON. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at a circulate packer fluid. MIT test with tubing and L/D. NDBOP, of the mith tubing and L/D. NDBOP, of the mith tubing and witnessed by NMIT test with NMOCD, R/D puling Rig Release Date of the beautiful above is true and complete to the beautiful above.	THE ABOVE SUB- and dump cement, cir ith NMOCD. confirm MIT test wit MOCD RD WSU ar g unit, ate: ERMITTING SPECI	IPPLET WELL. TA PROCEDURE TO THE PROCEDURE TO	
13. Describe proposed or comp of starting any proposed we proposed completion or rec CHEVRON USA INC. IS I AS FOLLOWS: POOH and L/D rods, NUB- Set CIBP and dump cement Circulate packer fluid, POO NDBOP NUWH. Run 30 M NDBOP, NUWH, confirm Spud Date: I hereby certify that the information SIGNATURE Type or print name CINDY HERRE	ork). SEE RULE 19.15.7.14 NMAGOMPLETON. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at a circulate packer fluid. MIT test with tubing and L/D. NDBOP, of the mith tubing and L/D. NDBOP, of the mith tubing and witnessed by NMIT test with NMOCD, R/D puling Rig Release Date of the beautiful above is true and complete to the beautiful above.	THE ABOVE SUB- and dump cement, cir ith NMOCD. confirm MIT test wit MOCD RD WSU ar g unit, ate: ERMITTING SPECI	propose the procedure of the procedure o	
13. Describe proposed or compof starting any proposed we proposed completion or recomproposed completion or recomp	ork). SEE RULE 19.15.7.14 NMAGOMPHETON. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at a circulate packer fluid. MIT test with tubing and L/D. NDBOP, of the mith tubing and L/D. NDBOP, of the mith tubing and witnessed by NMIT test with NMOCD, R/D puling Rig Release Date of the mith tubing and complete to the boundary of the mith tubing and L/D. TITLE PERAL-MURILLO E-mail address:	THE ABOVE SUB- and dump cement, cir ith NMOCD. confirm MIT test wit MOCD RD WSU ar g unit, ate: ERMITTING SPECI	propositions: Attach wellbore diagram of superioristic procedure. JECT WELL. TA PROCEDURE reculate packer fluid. MIT test with NMOCD th NMOCD. R/D. and Move off well e and belief. ALIST DATE 05/21/2018 chevron.com PHONE: 575-263-0431	
13. Describe proposed or compof starting any proposed we proposed completion or recomproposed completion or recomp	ork). SEE RULE 19.15.7.14 NMAGOMPLETON. REQUESTING A 5 YEAR TA ON OP, POOH with tubing. Set CIBP at a circulate packer fluid. MIT test with tubing and L/D. NDBOP, of the mith tubing and L/D. NDBOP, of the mith tubing and witnessed by NMIT test with NMOCD, R/D puling Rig Release Date of the beautiful above is true and complete to the beautiful above.	THE ABOVE SUB- and dump cement, cir ith NMOCD. confirm MIT test wit MOCD RD WSU ar g unit, ate: ERMITTING SPECI	IPPLET WELL. TA PROCEDURE TO THE PROCEDURE TO	