

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-00036 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> ✓
2. Name of Operator JAY MANAGEMENT COMPANY, LLC		6. State Oil & Gas Lease No. K-2654
3. Address of Operator 1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027		7. Lease Name or Unit Agreement Name NEW MEXICO "B" STATE ✓
4. Well Location Unit Letter A : 323 feet from the NORTH line and 1007' feet from the EAST line Section 27 Township 10S Range 32E NMPM County LEA ✓		8. Well Number 2 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4265' GR		9. OGRID Number 247692 ✓
		10. Pool name or Wildcat MESCALERO PERMO PENN ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			

OTHER: ☐ OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completion: Attach wellbore diagram of proposed completion or recompletion.

- 1. PERF (DEEP PENETRATING SHOTS)
- 2. CUT OFF WEEHEAD. VERIFY CEN
- 3. INSTALL UPRIGHT P&A MARK

SURFACE.

HOBBS OCD ✓

JUL 11 2018 ✓

RECEIVED

SEE ATTACHED
CONDITIONS OF APPROVAL

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Clayton Griffin

TITLE District Manager

DATE 07/10/2018

Type or print name Clay Griffin

E-mail address: cgriffin@ajmgt.com

PHONE: 574-707-5691

For State Use Only

APPROVED BY:

Walter Ritzman

TITLE Petroleum Engr. Spec.

DATE 07/12/2018

Conditions of Approval (if any):



LSE #: K-2654
FIELD: Mescalero Permò Penn
LOCATION: 330 FNL & 990 FEL
FORMATION: Permò Penn
ELEVATION:

O.D.	WT./FT.	GRADE	THD	TOP	BTM	NO. JTS.	BIT SZ.	SX CMT.	TOP CMT.
10-3/4"	32.75#				445'			450	Surf.
7-5/8"	24# & 26.40#				4480'			1928	976'

[illegible]

O.D.	WT./FT.	GRADE	THD	TOP	BTM	NO. JTS.

[illegible][illegible]

T. ANHY 1533

CONDITIONS OF APPROVAL:

New Mexico "B" No. 2

30-025-00036

UL -A, Section 27, T10S, R32E

- 1) Tag CIBP at 4310'. Circulate MLF from 4310' to 1575'.
- 2) Spot 25 sx cement on CIBP. WOC & Tag.
- 3) POOH to 1575'. Spot 30 sx cement. WOC & Tag. (Top Salt)
- 4) POOH to 816'. Spot 40 sx cement. WOC & Tag at 647' or better. (Bad csg)
- 5) Perf 7 5/8" casing at 495'. Circulate cement to surface inside/outside 7 5/8" casing.
- 6) Cut off wellhead 3' below ground level.
- 7) Verify cement to surface all strings.
- 8) Install upright P&A marker.