<u>District I</u> – (575) 393-6161		f New Mexico	Form C-103
1625 N. French Dr., Hobbs, NM 88240	Energy, Mineral	ls and Natural Resources	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	OIL CONSER	VATION DIVISION	30-025-44083
811 S. First St., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III - (505) 334-61781220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460		Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		,	0. State Off & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Thistle Unit
1. Type of wen: On wen k Gas wen D Other			102
2. Name of Operator Devon Energy Production Co. LP			9. OGRID Number 6137
3. Address of Operator 333 W. Sheridan Ave OKC, OK 73102			10. Pool name or Wildcat
4. Well Location	Sheridan Ave OKC, C	JK /5102	Triple X; Bone Spring (59900)
Unit Letter B	: <u>335</u> feet from th		1780 feet from the East line
Section 22	Township 2	23S Range 33E whether DR, RKB, RT, GR, et	NMPM Lea County
	371	-	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	INTENTION TO:		BSEQUE
PERFORM REMEDIAL WORK			DV A
TEMPORARILY ABANDON	CHANGE PLANS		
PULL OR ALTER CASING [MULTIPLE COMPL		
_			P&A R
] uctor P&A	I OTHER:	
13. Describe proposed or cor	npleted operations. (Clear	rly state all pertinent details, a	nd give pertinent dates, including estimated date
	work) SEE PLILE 10.15	7.14 NMAC For Multiple C	ompletions: Attach wellbore diagram of
proposed completion or r Devon Energy respectfully	recompletion. requests the following proce	edure to plug and abandon set co	nductor: HOBBS OCD
proposed completion or r Devon Energy respectfully	ecompletion. requests the following proce mpletely fill conductor with c	edure to plug and abandon set co	AVD-
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas	ecompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th	edure to plug and abandon set co cement e following information:	HOBBS OCD JUL 3 1 2018
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" belov 3. Weld plate to cutoff cas a. Company name, Well N	ecompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num	edure to plug and abandon set co cement e following information:	JUL 3 1 2018
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" belov 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har	ecompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to	edure to plug and abandon set co cement e following information:	JUL 312018
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" belov 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo	recompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to ordinate and plate	edure to plug and abandon set co cement e following information: .ber, & Legal Description	JUL 3 1 2018
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st	recompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to ordinate and plate tored in well file for this well	edure to plug and abandon set co cement e following information: .ber, & Legal Description o be certified or done by a survey	ing company) RECEIVED
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri	recompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location nd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to	edure to plug and abandon set co cement e following information: .ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p	ing company) RECEIVED
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri 6. Fill cellar with caliche	recompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location nd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory	edure to plug and abandon set co cement e following information: .ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p	ing company) JUL 3 1 2018 RECEIVED
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri	recompletion. y requests the following proce mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location nd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory	edure to plug and abandon set co cement e following information: .ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p	ing company) JUL 3 1 2018 RECEIVED
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate inform a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Vame and Number, API Num t of plate location nd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor	edure to plug and abandon set co cement e following information: aber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in	JUL 3 1 2018 RECEIVED lug and abandon report) spect location, bond on well will be released
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri 6. Fill cellar with caliche	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Vame and Number, API Num t of plate location nd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor	edure to plug and abandon set co cement e following information: aber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H	JUL 3 1 2018 RECEIVED lug and abandon report) spect location, bond on well will be released
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate inform a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Vame and Number, API Num t of plate location nd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor	edure to plug and abandon set co cement e following information: aber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H	JUL 3 1 2018 RECEIVED lug and abandon report) spect location, bond on well will be released
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep Spud Date: 12/01/	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor 17 Ri	edure to plug and abandon set co cement e following information: ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H BEGINNING PLUG	JUL 3 1 2018 RECEIVED lug and abandon report) spect location, bond on well will be released OURS PRIOR TO GING OPERATIONS
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate inform a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor 17 Ri	edure to plug and abandon set co cement e following information: ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H BEGINNING PLUG	JUL 3 1 2018 RECEIVED lug and abandon report) spect location, bond on well will be released OURS PRIOR TO GING OPERATIONS
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep Spud Date: 12/01/	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor 17 Rit on above is true and completed on above is true and completed attack in the second second second on above is true and completed on above is true and on above is true and completed on above is true and on above is	edure to plug and abandon set co cement e following information: ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H BEGINNING PLUG	JUL 3 1 2018 RECEIVED lug and abandon report) spect location, bond on well will be released OURS PRIOR TO GING OPERATIONS
roposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS coo i. Send to engineer to be st 5. GPS coordinate informa a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep Spud Date: 12/01/	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include the Jame and Number, API Num- t of plate location hd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to alling / completion, regulatory port from cement vendor 17 Rif on above is true and completion DULL TI'	edure to plug and abandon set co cement e following information: ber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H BEGINNING PLUG lete to the best of my knowled	JUL 3 1 2018 RECEIVED RECEIVED lug and abandon report) spect location, bond on well will be released OURS PRIOR TO GING OPERATIONS lge and belief.
proposed completion or r Devon Energy respectfully 1. Pump cement job to con 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS con i. Send to engineer to be st 5. GPS coordinate inform a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep Spud Date: 12/01/ I hereby certify that the information SIGNATURE <u>Rebuctua</u>	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include the Jame and Number, API Num- t of plate location hd-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to alling / completion, regulatory port from cement vendor 17 Rif on above is true and completion DULL TI'	edure to plug and abandon set co cement e following information: aber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H BEGINNING PLUG lete to the best of my knowled TLE <u>Regulatory Analyst</u>	JUL 3 1 2018 RECEIVED RECEIVED lug and abandon report) spect location, bond on well will be released OURS PRIOR TO GING OPERATIONS lge and belief. DATE 7/31/2018 @dvn.com PHONE: 405-228-8429
proposed completion or r Devon Energy respectfully 1. Pump cement job to completion of r 2. Cut off casing 55" below 3. Weld plate to cutoff cas a. Company name, Well N 4. Take GPS measurement a. Can be taken with a har b. Take picture of GPS cood i. Send to engineer to be st 5. GPS coordinate information a. Upon completion of dri 6. Fill cellar with caliche 7. Get post job cement rep Spud Date: 12/01/ I hereby certify that the information SIGNATURE Type or print name Rebecca Determinitian	recompletion. y requests the following proce- mpletely fill conductor with c v GL ing. Plate needs to include th Jame and Number, API Num t of plate location id-help GPS (does not need to ordinate and plate tored in well file for this well ation / picture will be given to lling / completion, regulatory port from cement vendor 17 Ri 17 Ri 17 Ri 17 Eal E-1	edure to plug and abandon set co cement e following information: aber, & Legal Description o be certified or done by a survey o regulatory to file with C-103 (p y will file C-103, NMOCD will in NOTIFY OCD 24 H BEGINNING PLUG lete to the best of my knowled TLE <u>Regulatory Analyst</u>	JUL 3 1 2018 RECEIVED RECEIVED lug and abandon report) spect location, bond on well will be released OURS PRIOR TO GING OPERATIONS lge and belief.

C103 INTENT TO P&A EXPIRES 1 YEAR FROM DATE OF APPROVAL

MW