	State of New Mexico	Form C-103
Office <u>District I</u> (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-44673
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE 🔀 FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	o. State on a das Bease No.
87505	NOTE AND DEPORTS ON WELLS	
COO NOT HEE THE CODY COD BROW	TICES AND REPORTS ON WELLS  DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLI	ICATION FOR PERMIT" (FORM C-100BBS OCD	CONDOR 32 STATE COM
		8. Well Number 712C
1. Type of Well: Oil Well	Gas Well Other	1120
	RESOURCES INC AUG 272018	9. OGRID Number 7377
3. Address of Operator	DX 2267 MIDLAND, TX 797 RECEIVED	10. Pool name or Wildcat
	DA 2267 MIDLAND, IX 7970E-C-14-C-	BOBCAT DRAW; UPPER WOLFCAMP
4. Well Location	204	NECT VALECT
Unit Letter N :	291 feet from the SOUTH line and	
Section 32	Township 25S Range 34E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR, et	c.)
	3340' GR	
12. Check	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF IN	NTENTION TO:   SU	BSEQUENT
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		RILLING OPNS IN I TO PAIM
PULL OR ALTER CASING		DOANID
DOWNHOLE COMMINGLE	<del></del>	P&A R
CLOSED-LOOP SYSTEM		<del></del> _
OTHER:	OTHER:	J
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details,	
13. Describe proposed or com of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAC. For Multiple C	
13. Describe proposed or com	ork). SEE RULE 19.15.7.14 NMAC. For Multiple C	
13. Describe proposed or com of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC. For Multiple C	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. sees to P&A this wellbore ASAP using the follow	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or research EOG proposed 1- CAP CIB	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  sees to P&A this wellbore ASAP using the follow  BP @4055" w/100' Cmt  ' cmt plug 955-1055', WOC and Tag	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  sees to P&A this wellbore ASAP using the follow  BP @4055" w/100' Cmt  or cmt plug 955-1055', WOC and Tag  or cmt plug 100'-surface	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt  Comt plug 955-1055', WOC and Tag  Comt plug 100'-surface	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt  Comt plug 955-1055', WOC and Tag  Comt plug 100'-surface	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt  Comt plug 955-1055', WOC and Tag  Comt plug 100'-surface	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt  Comt plug 955-1055', WOC and Tag  Comt plug 100'-surface	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  P @4055" w/100' Cmt  Comt plug 955-1055', WOC and Tag  Comt plug 100'-surface	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100 3- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  BP @4055" w/100' Cmt  O' cmt plug 955-1055', WOC and Tag  O' cmt plug 100'-surface  NOTIFY OCD 26  BEGINNING PL	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS
13. Describe proposed or composed of starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  sees to P&A this wellbore ASAP using the followard for the followard form of the followard form	ompletions: Attach wellbore diagram of ving procedure:
13. Describe proposed or composed starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100 3- Spot 100	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  BP @4055" w/100' Cmt  O' cmt plug 955-1055', WOC and Tag  O' cmt plug 100'-surface  NOTIFY OCD 26  BEGINNING PL	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS
13. Describe proposed or composed starting any proposed was proposed completion or responsed completio	Nork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this well as the sees to P&A thi	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS
13. Describe proposed or composed starting any proposed was proposed completion or responsed completio	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the follow  BP @4055" w/100' Cmt  O' cmt plug 955-1055', WOC and Tag  O' cmt plug 100'-surface  NOTIFY OCD 26  BEGINNING PL	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS
13. Describe proposed or composed starting any proposed was proposed completion or responsed completio	North). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the plug 4055" w/100" Cmt  O' cmt plug 955-1055", WOC and Tag  O' cmt plug 100"-surface  NOTIFY OCD 2"  BEGINNING PL  Rig Release Date:	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS  1/20/2018
13. Describe proposed or composed starting any proposed was proposed completion or responsed completio	Nork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this wellbore ASAP using the followard of the sees to P&A this well as the sees to P&A thi	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS  1/20/2018
13. Describe proposed or compost starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100 3- Spot 100  Spud Date: 5/2/201  I hereby certify that the information	North). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the property	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS  J20/2018  dge and belief.  DATE 08/20/2018
13. Describe proposed or composed starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100 3- Spot 100  Spud Date: 5/2/201  I hereby certify that the information  SIGNATURE  Type or print name Kay Madde	North). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the property	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS  1/20/2018
13. Describe proposed or compost starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100 3- Spot 100  Spud Date: 5/2/201  I hereby certify that the information	North). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the property	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS  J20/2018  DATE 08/20/2018  eogresources.com PHONE: 432-686-3658
13. Describe proposed or composed starting any proposed we proposed completion or re  EOG propo  1- CAP CIB 2- Spot 100 3- Spot 100  Spud Date: 5/2/201  I hereby certify that the information  SIGNATURE  Type or print name Kay Madde	North). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  Sees to P&A this wellbore ASAP using the followard of the property	ompletions: Attach wellbore diagram of ving procedure:  HOURS PRIOR TO UGGING OPERATIONS  J20/2018  dge and belief.  DATE 08/20/2018

## EOG Resources Condor 32 State Com 712H Bobcat Draw (Wolfcamp) Field

30-025-44673 292' FSL & 2597' FWL Section 32 T25S R34E Lea County, New Mexico

# **Existing WBD** 8/17/2018

Formation Top	TVD
Rustler	814
Top of Salt	1585
Base of Salt	5010
Lamar	5264
Bell Canyon	5288
Cherry Canyon	6305
Brushy Canyon	7945
Bone Spring Lime	9412
Leonard A	9445
First BS Sand	10399
Second BS Shale	10610
Second BS Sand	10958
Third BS Carb	11438
Wolfcamp	12475

8.4 ppg WBM + CI & Biocide

Surface Casing @ 1005' MD/TVD

13-3/8" 40.5# J55 STC

Lead Cement: 680 sx (13.5 ppg / 1.76 yld) Tail Cement: 200 sx (14.8 ppg / 1.36 yld)

Circulated 332 sx CTS

CIBP @ 4055'

CIBP @ 4543', WS3 Baker @ 4,521'. Mill window @ 4538'. Attempt to sidetrack, no success. Drlg alongside casing to 4732', unable to work past.

Two whipstocks in hole. WS1 SLB @ 4890'. WS2 Baker @ 4780'

CIBP @ 4894"

1" Intermediate Casing @ 5095'

9-5/8" 40# J55 LTC (0' - 3694') 9-5/8" 40# HCK55 LTC (3694' - 5095') Lead Cement: 1025 sx (12.7 ppg / 2.32 yld) Tail Cement: 475 sx (14.8 ppg / 1.42 yld) Circulated 121 sx CTS 30 min Casing test to 2300 psi

9.0 ppg Cut Brine

Water

Tight Spot in casing @ 4,918'

Drilled well to 7-5/8" casing point. TOH. PU and RIH with 7-5/8" casing to 4918'. Unable to work casing past tite spot in casing @ 4918'. Pulled 7-5/8" casing out of hole. RIH with DP and mill(s). Unable to get past tite spot.

### EOG Resources Condor 32 State Com 712H Bobcat Draw (Wolfcamp) Field

30-025-44673 292' FSL & 2597' FWL Section 32 T25S R34E Lea County, New Mexico

9.5 ppg WBM

9.5 ppg WBM

# Note:

This procedure was approved by Maxey Brown with the NMOCD at 9:36 AM CST on 8/20/2018 (via email).

For cement contact Russel Roberts with Nine Energy Services at 830.480.0659

Cut-off casing(s) 4' below ground level and install top steel plate. Weld the following on plate: Operator Name, Lease Name and Well No., API Number, Surface Location, Section, Township and Range.

# **Existing WBD** 8/17/2018

Formation Top	TVD
Rustler	814
Top of Salt	1585
Base of Salt	5010
Lamar	5264
Bell Canyon	5288
Cherry Canyon	6305
Brushy Canyon	7945
Bone Spring Lime	9412
Leonard A	9445
First BS Sand	10399
Second BS Shale	10610
Second BS Sand	10958
Third BS Carb	11438
Wolfcamp	12475

Cmt Plug #3 - 100' (4' - 104')(50 sx)

#### Surface Casing @ 1005' MD/TVD

13-3/8" 40.5# J55 STC

Lead Cement: 680 sx (13.5 ppg / 1.76 yld) Tail Cement: 200 sx (14.8 ppg / 1.36 yld)

Circulated 332 sx CTS

Cmt Plug #2 - 100' (955' - 1055')(50 sx)(Tag required - Must tag @ 955' or less)

Cmt Plug #1 - 100' (3955' - 4055')(50 sx)(No tag required)

CIBP @ 4055'

Tight Spot in casing @ 4,918

CIBP @ 4543', WS3 Baker @ 4,521'. Mill window @ 4538'. Attempt to sidetrack, no success. Drlg alongside casing to 4732', unable to work past.

Two whipstocks in hole. WS1 SLB @ 4890'. WS2 Baker @ 4780'

CIBP @ 4894'

---- (-) ----

### 1st Intermediate Casing @ 5095'

9-5/8" 40# J55 LTC (0" - 3694")
9-5/8" 40# HCK55 LTC (3694" - 5095")
Lead Cement: 1025 sx (12.7 ppg / 2.32 yld)
Tail Cement: 475 sx (14.8 ppg / 1.42 yld)
Circulated 121 sx CTS
30 min Casing test to 2300 psi

9.0 ppg Cut Brine Water

Drilled well to 7-5/8" casing point. TOH. PU and RIH with 7-5/8" casing to 4918'. Unable to work casing past tite spot in casing @ 4918'. Pulled 7-5/8" casing out of hole. RIH with DP and mill(s). Unable to get past tite spot.