252570925Submit 1 Copy To Appropriate District Office	State of New Mexi	co		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natura	l Resources		vised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION D	IVISION	30-025-25709	
<u>District III</u> – (505) 334-6178	1220 South St. Franc		5. Indicate Type of Lease STATE ☐ F	EE 🗆
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe NM 90	DK D	6. State Oil & Gas Lease N	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 865	8100	o. State Off & Gas Lease I	NO.
87505	Ho	9 4 10's		
District IV – (505) 4/6-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS? (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACKETAL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SIGNATURE.			7. Lease Name or Unit Ag	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			CENTRAL VACUUM UN	NIT -
PROPOSALS.)				
SUNDRY NOTICES AND REPORTS ON WELLS? (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SICK PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other WAG INJECTOR		8. Well Number 85		
2. Name of Operator		9. OGRID Number 4323		
CHEVRON USA INC				
3. Address of Operator			10. Pool name or Wildcat	
6301 DEAUVILLE BLVD, MIDLAND, TEXAS 79706		VACUUM GRAYBURG SAN ANDRES		
4. Well Location		•		
Unit Letter L: 133	36 feet from the SOUTH line a	nd 1201	feet from the WEST	line
Section 31 Township 17S Range 35E			- -	nty LEA
	11. Elevation (Show whether DR, R	<u> </u>		
The state of the second second	3982' KB	ND, K1, OK, CIC.)		design of
	, , , , , , , , , , , , , , , , , , , ,		TO SECTION OF THE SEC	J. Komer (d. 18 Sallaho Star Doll Collection on Million and Association of the Collection of the Colle
12 Chack A	Appropriate Box to Indicate Nat	ure of Notice I	Panort or Other Data	
12. Check A	appropriate box to indicate Nat	uic of Notice, i	report of Other Data	
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPORT	OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK		NG CASING
TEMPORARILY ABANDON	CHANGE PLANS ☐ (COMMENCE DRIL	LING OPNS.□ P AND A	A 🔲
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🔲	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
OTHER: 13. Describe proposed or comp	leted operations. (Clearly state all per	tinent details, and		
OTHER: 13. Describe proposed or complete of starting any proposed wo	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC.	tinent details, and		
OTHER: 13. Describe proposed or comp	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC.	tinent details, and		
OTHER: 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion.	tinent details, and For Multiple Con	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. THE SUBJECT WELL FAILED ITS	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC.	tinent details, and For Multiple Con	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion.	tinent details, and For Multiple Con	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION.	leted operations. (Clearly state all per ork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK	tinent details, and For Multiple Con	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION.	leted operations. (Clearly state all per ork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK	tinent details, and For Multiple Con	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK	tinent details, and For Multiple Con	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT	tinent details, and For Multiple Con COVER TO REST	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN	tinent details, and For Multiple Con COVER TO REST	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT	tinent details, and For Multiple Com COVER TO REST IG AND CHART	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN	tinent details, and For Multiple Com COVER TO REST IG AND CHART	pletions: Attach wellbore of	diagram of
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN	tinent details, and For Multiple Con OVER TO REST G AND CHART CO Condi	tion of Approval: notif	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN	tinent details, and For Multiple Con OVER TO REST OG AND CHART CO Condi OCD	tion of Approval: notify Hobbs office 24 hours	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN	tinent details, and For Multiple Con OVER TO REST OG AND CHART CO Condi OCD	tion of Approval: notif	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN ORT WITH MIT CHART TO NMOC	tinent details, and For Multiple Con COVER TO REST CONTROL CONT	tion of Approval: notify Hobbs office 24 hours	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or reconstruction. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN	tinent details, and For Multiple Con COVER TO REST CONTROL CONT	tion of Approval: notify Hobbs office 24 hours	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQU 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN ORT WITH MIT CHART TO NMOC	tinent details, and For Multiple Con COVER TO REST CONTROL CONT	tion of Approval: notify Hobbs office 24 hours	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR I. 4. RE-RUN INJECTION EQU. 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT.	leted operations. (Clearly state all perbrk). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN ORT WITH MIT CHART TO NMOO	tinent details, and For Multiple Con COVER TO REST CONTROL CONT	tion of Approval: notify Hobbs office 24 hours running MIT Test & C	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR I. 4. RE-RUN INJECTION EQU. 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT.	leted operations. (Clearly state all perork). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN ORT WITH MIT CHART TO NMOC	tinent details, and For Multiple Con COVER TO REST CONTROL CONT	tion of Approval: notify Hobbs office 24 hours running MIT Test & C	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQUE 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT OF THE POOR TO SUBJECT S	leted operations. (Clearly state all perbrk). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASINORT WITH MIT CHART TO NMOO Rig Release Date	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours running MIT Test & C	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQUE 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT OF THE POOR TO SUBJECT S	leted operations. (Clearly state all perbrk). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASINORT WITH MIT CHART TO NMOO Rig Release Date	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours cunning MIT Test & Canada belief.	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQUE 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT OF THE POOR TO SUBJECT S	leted operations. (Clearly state all perbrk). SEE RULE 19.15.7.14 NMAC. ompletion. S MIT. PLAN TO PERFORM WORK FION EQUIPMENT F LEAK JIPMENT FNESS PRESSURE TEST OF CASIN ORT WITH MIT CHART TO NMOO	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours cunning MIT Test & Canada belief.	diagram of EGRITY AND
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete. THE SUBJECT WELL FAILED ITS RETURN TO INJECTION. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR IT 4. RE-RUN INJECTION EQUE 5. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT OF THE POOR TO SUBJECT S	Rig Release Date above is true and complete to the best A Complete to the best	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours cunning MIT Test & C and belief. DATE 09/2	egram of EGRITY AND hart
OTHER: 13. Describe proposed or composed of starting any proposed wo proposed completion or recompletion or recompletion or recompletion or recompletion. 1. MIRU, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR INTEGRATION EQUAL SERVING INJECTION EQUAL SERVING SE	Rig Release Date above is true and complete to the best A Complete to the best A Complete of the best	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours cunning MIT Test & C and belief. DATE 09/2	egram of EGRITY AND hart
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete or complete or complet	Rig Release Date above is true and complete to the best above is true and complete to the best	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours running MIT Test & C and belief. DATE 09/2 evron.com PHONE: 57	egram of EGRITY AND hart
OTHER: 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete of the Subject Well Failed Its Return to Injection. 1. Miru, NDWH, NU BOPE 2. POOH WITH ALL INJECT 3. TEST CASING, REPAIR I. 4. RE-RUN INJECTION EQUES. NOTIFY NMOCD TO WITH 6. FILE SUBSEQUENT REPORT. Spud Date: I hereby certify that the information is SIGNATURE Conductive Lindy Herrera.	Rig Release Date above is true and complete to the best A Complete to the best A Complete of the best	tinent details, and For Multiple Com OVER TO REST OCD Condi OCD prior of I	tion of Approval: notify Hobbs office 24 hours cunning MIT Test & C and belief. DATE 09/2	egram of EGRITY AND hart