Shuiti Con The Annual Plata	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		
Submit 1 Copy To Appropriate District Office	State of New Mex		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natur	al Resources WELL API NO	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		20.005.20102	•
811 S. First St., Artesia, NM 88210	OIL CONSERVATION		
District III – (505) 334-6178	1220 South Sp BB	5. Indicate Typ STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	Sonto En NM 974	505	
1220 S. St. Francis Dr., Santa Fe, NM	D TJA	6. State Oil & C	Jas Lease No.
87505	CES AND REPORTS ON WELLS		or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN CONTRACTOR	GEACK TO A	or Onit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC	ATION FOR PERMIT" (FORM C-101) FOR	R SUCH ROCK QUEEN	UNIT
PROPOSALS.)	Cas Wall M Other T	8. Well Numbe	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		9. OGRID Nun	
REMNANT OIL OPERATING. LLC		370922	ibei
3. Address of Operator		10. Pool name	or Wildcat
PO BOX 5375, Midland, TX 797	04	CAPROCK; QUEE	
4. Well Location			
Unit Letter R : 2145	feet from the N line and 1980	0 feet from the W line	
Section 26 Townshi		NMPM County	CHAVES
	11. Elevation (Show whether DR,		
	TT. Dievation (Snow Whether DA,	inte, m, on, etc.)	The second second second second second
	······································		en en lan annanan hanna ann an an ann an ann an
12 Check A	ppropriate Box to Indicate Na	ture of Notice, Report or Othe	r Data
	•••••		r Duiu
NOTICE OF IN	TENTION TO:	SUBSEQUENT R	EPORT OF:
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING 📋
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	P AND A
PULL OR ALTER CASING		CASING/CEMENT JOB	
OTHER: 13 Describe proposed or compl		OTHER: ertinent details and give pertinent da	tes including estimated date
13. Describe proposed or compl	eted operations. (Clearly state all pe	ertinent details, and give pertinent da	
13. Describe proposed or compl	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.		
13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da	
13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da	
13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da	
13. Describe proposed or compl of starting any proposed wo proposed completion or recoHOLE IN TUBING	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da For Multiple Completions: Attach	wellbore diagram of
 Describe proposed or compl of starting any proposed wo proposed completion or reco 	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da For Multiple Completions: Attach	wellbore diagram of
 13. Describe proposed or compl of starting any proposed wo proposed completion or reco HOLE IN TUBING 08/20/2018 	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da For Multiple Completions: Attach	wellbore diagram of
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	ertinent details, and give pertinent da For Multiple Completions: Attach	wellbore diagram of
 13. Describe proposed or compl of starting any proposed wo proposed completion or reco HOLE IN TUBING 08/20/2018 	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC.	reverse unit. ertinent details, and give pertinent da completions: Attach - Test sh on 100	wellbore diagram of ENIED ould have been of chart.
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	ertinent details, and give pertinent da For Multiple Completions: Attach	wellbore diagram of ENIED ould have been of chart.
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - No C-10	wellbore diagram of ENIED ould have been of chart. 3 Intent
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - No C-10	wellbore diagram of ENIED ould have been of chart. 3 Intent
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - No C-10	wellbore diagram of ENIED ould have been of chart. 3 Intent
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - No C-10	wellbore diagram of ENIFD ould have been of chart. 3 Intent hr. Notice or to test.
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - No C-10	wellbore diagram of ENIFD ould have been of chart. 3 Intent hr. Notice or to test.
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - No C-10	wellbore diagram of ENIFD ould have been of chart. 3 Intent hr. Notice or to test.
 13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the test of test o	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. ompletion.	reverse unit. - Test shi on 100 - No C-10 - No 24 Price	wellbore diagram of ENIED ould have been of chart. 3 Intent
 13. Describe proposed or completion of starting any proposed wo proposed completion or reconnected HOLE IN TUBING 08/20/2018 Move in rig up pulling unit. Unlesse ATTACHED: 	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. completion. bad B.O.P. and test B.O.P. wait for r	ertinent details, and give pertinent details, and give per	wellbore diagram of ENIED ould have been of chart. 3 Intent hr. Notice or to test. Mark 10/1/20BB
 13. Describe proposed or compl of starting any proposed wo proposed completion or reco HOLE IN TUBING <u>08/20/2018</u> Move in rig up pulling unit. Unle SEE ATTACHED: 	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. completion. bad B.O.P. and test B.O.P. wait for r	ertinent details, and give pertinent details, and give pertinent details. For Multiple Completions: Attach - Test shi - No C-10 - No C-10 - No 24 - Crice st of my knowledge and belief.	wellbore diagram of ENIFD ould have been of chart. 3 Intent hr. Notice or to test.
 13. Describe proposed or completion of starting any proposed wo proposed completion or reconnected to the set of the set of	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. completion.	ertinent details, and give pertinent details, and give pertinent details. For Multiple Completions: Attach - Test shi on 1000 - No C-10 - No C-10 - No 24 - St of my knowledge and belief. atory Affairs Coordinator DAT	wellbore diagram of ENIED ould have been of chart. 3 Intent hr. Notice or to test. MAB 10/1/2018 E: 09/21/2018
 13. Describe proposed or completion of starting any proposed wo proposed completion or reconnected to the set of the set of	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. completion. bad B.O.P. and test B.O.P. wait for r	ertinent details, and give pertinent details, and give pertinent details. For Multiple Completions: Attach - Test shi on 1000 - No C-10 - No C-10 - No 24 - St of my knowledge and belief. atory Affairs Coordinator DAT	wellbore diagram of ENIED ould have been of chart. 3 Intent hr. Notice or to test. MAB 10/1/2018 E: 09/21/2018
 13. Describe proposed or completion of starting any proposed wo proposed completion or record HOLE IN TUBING 08/20/2018 Move in rig up pulling unit. Unlesse ATTACHED: I hereby certify that the information a SIGNATURE Type or print name 	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. completion.	ertinent details, and give pertinent details, and give pertinent details. For Multiple Completions: Attach - Test shi - No C-10 - No C-10 - No 24 - No 24 - St of my knowledge and belief. atory Affairs Coordinator DAT oilfield.com PHONE: 432.664	wellbore diagram of ENIFD ould have been of chart. 3 Intent hr. Notice br. to test. MAB 10/1/2018 .7659
 13. Describe proposed or completion of starting any proposed wo proposed completion or reconnected to the set of the set of	eted operations. (Clearly state all perk). SEE RULE 19.15.7.14 NMAC. completion.	ertinent details, and give pertinent details, and give pertinent details. For Multiple Completions: Attach - Test shi - No C-10 - No C-10 - No 24 - No 24 - St of my knowledge and belief. atory Affairs Coordinator DAT oilfield.com PHONE: 432.664	wellbore diagram of ENIED ould have been of chart. 3 Intent hr. Notice or to test. MAB 10/1/2018 E: 09/21/2018

ROCK QUEEN UNIT 314

Continued:

08/21/2018

Check well pressure tbg and casing on vacuum, broke dwn pump –t and valve. NU 2 3/8 w/TIW. M/D well head and N/U B.O.P. Test B.O.P. p/u on tbg , unset prk and POH w/82 jts, found hole, P/O with 10 jts and on/off tool, close W/I.

08/22/2018

Check well press, was on vacuum open B.O.P. and RIH with on/off tool and 24 jts. 2 3/8 tbg (IPC) latch on to pkr and P/O/H standback tbg and L/D bad jts. and prk p/u new prk and RIH 83 jts. Pull tbg back out w/pkr to RBI with tbg sealant (seal lube) on threads. SDFN

<u>8/23/2018</u>

Check well press, was on vacuum open B.O.P. and TIW. Tally tbg and clean treads. P/U 10 jts. RIH p/u sub set prk @3020 and got on/off, circ prk fluid. Test csg 500psi. test good M/D B.O.P. flange dn rig dn mode rig SD.

Down hole equipment detail: 93 jts of 2 $^{3/8}$ ", 4.7", 8rd , EUE J-55 IPC tubing, + T-2 on/off tool, + 5 $^{1/2}$ " nickel plated AS-IT packer with 1.50" profile nipple. Total 3020'.

