
Office Energy Minerals and Note	exico Form C-103
	ural Resources May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	30-025-35199
District III 1220 South St. Fra	pcis Dr. STATE ST FEE ST
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 8	7.503 2018 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) F	
PROPOSALS.)	6. Well Number
 Type of Well: Oil Well ☐ Gas Well ☒ Other Name of Operator 	9. OGRID Number
Marathon Oil Permian, LLC	372098
3. Address of Operator	10. Pool name or Wildcat
5555 San Felipe Houston, TX 77056	Shoe Bar Atoka
4. Well Location	
Unit Letter H : 1650 feet from the FNL line and	000 feet from the F. line
Section 4 Township 17S Range 3	
11. Elevation (Show whether DR	
	GL
Pit or Below-grade Tank Application or Closure	, oc
1	vater well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material
12. Check Appropriate Box to Indicate N	lature of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
	OAGING/GEMENT 30B
OTHER:	
	OTHER:
13. Describe proposed or completed operations. (Clearly state all	pertinent details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multip	
of starting any proposed work). SEE RULE 1103. For Multip or recompletion.	pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multip or recompletion.	pertinent details, and give pertinent dates, including estimated date ble Completions: Attach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure test Case	pertinent details, and give pertinent dates, including estimated date ble Completions: Attach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure test Case 25sx @ 10,000' – 9700'.	pertinent details, and give pertinent dates, including estimated date ble Completions: Attach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure + 15+ Cas 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S & tag.	pertinent details, and give pertinent dates, including estimated date ble Completions: Attach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure fest Case 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT)	pertinent details, and give pertinent dates, including estimated date only completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure + 15+ Cas 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S & tag.	pertinent details, and give pertinent dates, including estimated date only completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure fest Case 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT)	pertinent details, and give pertinent dates, including estimated date on the Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure fest Case 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT)	pertinent details, and give pertinent dates, including estimated date on the Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +est Cass 2. 25sx @ 10,000° - 9700°. 3. 61sx @ 5060° - 4870° P.S. & tag. 4. 35sx @ 2000° - 1900° P.S. (T.SALT) 5. 140sx @ 509° - Surf. P.S verify. Instatll DHM.	pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +1st Cass 25sx @ 10,000° - 9700°. 2. 25sx @ 10,000° - 4870° P.S & tag. 4. 35sx @ 2000° - 1900° P.S. (T.SALT) 5. 140sx @ 509° - Surf. P.S verify. Instatll DHM.	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC & TAG (B, SALT)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass. 2. 25sx @ 10,000° - 9700°. 3. 61sx @ 5060° - 4870° P.S & tag. 4. 35sx @ 2000° - 1900° P.S. (T.SALT) 5. 140sx @ 509° - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. See Attache	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS CAT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC & TAG (B. SALT)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass. 2. 25sx @ 10,000° - 9700°. 3. 61sx @ 5060° - 4870° P.S & tag. 4. 35sx @ 2000° - 1900° P.S. (T.SALT) 5. 140sx @ 509° - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. See Attache	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS CAT 7300 (SPACER PLUG) PERF Q 3015'. SQ 7 W/35 SX WOC \$ TAG (B.SALT)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure fest Case 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT) 5. 140sx @ 509' - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility.	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS CAT 7300 (SPACER PLUG) PERF Q 3015'. SQ 7 W/35 SX WOC \$ TAG (B.SALT)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass. 2. 25sx @ 10,000° - 9700°. 3. 61sx @ 5060° - 4870° P.S & tag. 4. 35sx @ 2000° - 1900° P.S. (T.SALT) 5. 140sx @ 509° - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. See Attache	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS CAT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC & TAG (B. SALT)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass. 2. 25sx @ 10,000° - 9700°. 3. 61sx @ 5060° - 4870° P.S & tag. 4. 35sx @ 2000° - 1900° P.S. (T.SALT) 5. 140sx @ 509° - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. See Attache	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS CAT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC & TAG (B. SALT)
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass 2. 25sx @ 10,000° – 9700°. 3. 61sx @ 5060° – 4870° P.S. & tag. 4. 35sx @ 2000° – 1900° P.S. (T.SALT) 5. 140sx @ 509° – Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. See Attache Conditions of Ap	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion Sing. SPOT 25 SX CLASS C AT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC + TAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below-
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass 2. 25sx @ 10,000° – 9700°. 3. 61sx @ 5060° – 4870° P.S. & tag. 4. 35sx @ 2000° – 1900° P.S. (T.SALT) 5. 140sx @ 509° – Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. See Attache Conditions of Ap	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion Sing. SPOT 25 SX CLASS C AT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC + TAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below-
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Case 2. 25sx @ 10,000° – 9700°. 3. 61sx @ 5060° – 4870° P.S. & tag. 4. 35sx @ 2000° – 1900° P.S. (T.SALT) 5. 140sx @ 509° – Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. See Attache Conditions of Ap	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion Sing. SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG) PERF Q 3015'. SQ Z W/35 SX WOC + TAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below- a general permit or an (attached) alternative OCD, approved plan
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350° w/35sx cmt. Pressure +test Cass 2. 25sx @ 10,000° – 9700°. 3. 61sx @ 5060° – 4870° P.S. & tag. 4. 35sx @ 2000° – 1900° P.S. (T.SALT) 5. 140sx @ 509° – Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. See Attache Conditions of Ap	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion Sing. SPOT 25 SX CLASS C AT 7300 (SPACER PLUG) PERF @ 3015'. SQ 7 W/35 SX WOC + TAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below-
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure fest cases 2. 25sx @ 10,000' - 9700'. 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S. & tag. 4. 35sx @ 2000' - 1900' P.S. (T. SALT) 5. 140sx @ 509' - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. Conditions of April 1 hereby certify that the information above is true and complete to the b grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE TITLE	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion Sing. SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG) PERF @ 3015'. SQ Z W/35 SX WOC + TAG (B.SALT) Id Sproval est of my knowledge and belief. I further certify that any pit or below- a general permit or an (attached) alternative/OCD-approved plan . Agent
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure + 25+ Cass 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S. & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT) 5. 140sx @ 509' - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. Closed loop. All fluids to licensed facility. PC Conditions of April 1 hereby certify that the information above is true and complete to the b grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE Type or print name: Brody Pinkerton E-mail address: Brody@mayer.	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion Sing. SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG) PERF Q 3015'. SQ Z W/35 SX WOC + TAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below- a general permit or an (attached) alternative OCD, approved plan
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure + 25+ Cass 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S. & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT) 5. 140sx @ 509' - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. Closed loop. All fluids to licensed facility. Power and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE Type or print name: Brody Pinkerton E-mail address: Brody@mave. For State Use Only	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion sing. SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG) PERF @ 3015 '. SQ T W/35 SX WOC TTAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below— a general permit or an (attached) alternative/OCD-approved plan . Agent
of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 1. 5 ½ CIBP @ 12,350' w/35sx cmt. Pressure + 25+ Cass 2. 25sx @ 10,000' - 9700'. 3. 61sx @ 5060' - 4870' P.S. & tag. 4. 35sx @ 2000' - 1900' P.S. (T.SALT) 5. 140sx @ 509' - Surf. P.S verify. Instatll DHM. Closed loop. All fluids to licensed facility. P&A mud between all plugs. Closed loop. All fluids to licensed facility. PC Conditions of April 1 hereby certify that the information above is true and complete to the b grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE Type or print name: Brody Pinkerton E-mail address: Brody@mayer.	pertinent details, and give pertinent dates, including estimated date ole Completions: Attach wellbore diagram of proposed completion SPOT 25 SX CLASS C'AT 7300 (SPACER PLUG) PERF @ 3015 . SQ 7 w/35 SX WOC + TAG (B, SALT) d proval est of my knowledge and belief. I further certify that any pit or below- a general permit or an (attached) alternative/OCD-approved plan . Agent

Before

Marathon Oil

Wellbore Schematic Well Name: SHOEBAR 4 STATE 1

State/Province NEW MEXICO	Prospect Area	Field Name SHOE BAR	Well Subtype GAS WELL	Let/Long Datum NAD27	Letitude (*) 32,866761	Longitude (*) +103,456896
Well Configuration Type	Well Objective	Well St PRO	atus DUCING		und Elevation (ft) 179.00	KB-Graund Platance (ft) 30:00



After

MAVERICK WELL PLUGGERS

COMPANY: Marathon 0:1 Permian LLC

WELL NAME: Shoe Bar 4St


WELL#:

COUNTY: Lea

LEASE ID:

API# 30-025-35199

SURFACE CASING							
ΦO	WT/FT	GRADE	SETAT	TOC			
133/8"	48		425-	Circulated			
INTERMEDIATE CASING							
OD	WT/FT	GRADE	SETAT	TOC			
8 5/3"	32		5010	Circulatal			
PRODUCTION CASING							
OD	WT/FT	GRADE	SET AT	TOC			
5 1/2"	20		12,700	४०००			
TUBING							
OD	WT/FT	GRADE	SET AT	TAC			
				į.			



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.