
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy Minerals and Natural Resources	June 19, 2008
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-22226
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE I FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	OG-3846 & K-5061
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	SHELL STATE COM
PROPOSALS.)	8. Well Number 1
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Other Other	9. OGRID Number
JAY MANAGEMENT COMPANY, LLC	247692
3. Address of Operator	10. Pool name or Wildcat
1001 WEST LOOP SOUTH, SUITE 750 HOUSTON,TX 77027	North Bagley
4. Well Location Unit Letter H : 1980 feet from the NORTH line and 660 feet from the EAST line	
Section 17 Township 11S Range 33E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
4305 KB	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	
PULL OR ALTER CASING D MULTIPLE COMPL CASING/CEMENT	JOB 🗌
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att. or recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. 	See Attached Conditions of Approva
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. 	See Attached Conditions of Approva
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attoor recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. 	See Attached Conditions of Approva
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attorn recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. 	See Attached Conditions of Approva
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attorn recompletion. 1. Set CIBP at 8460'. Circulate MLF. Pressure test casing. 2. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 3. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 4. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 5. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 6. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 7. Perforate at 400'. Circulate cement to surface. 8. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. 4'' d Spud Date: 	See Attached Conditions of Approval Via 4'above ground
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attorn recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. 	See Attached Conditions of Approval Via 4'above ground
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attorn recompletion. 1. Set CIBP at 8460'. Circulate MLF. Pressure test casing. 2. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 3. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 4. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 5. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 6. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 7. Perforate at 400'. Circulate cement to surface. 8. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. 4'' d Spud Date: 	See Attached Conditions of Approval Via 4'above ground
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attorn recompletion. 1. Set CIBP at 8460'. Circulate MLF. Pressure test casing. 2. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 3. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 4. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 5. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 6. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 7. Perforate at 400'. Circulate cement to surface. 8. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. 4'' d Spud Date: 	See Attached Conditions of Approval Via 4'above ground
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 1. Set CIBP at 8460'. Circulate MLF. Pressure test casing. 2. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 3. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 4. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 5. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 6. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 7. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 8. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. 4 '' a Spud Date: I hereby certify that the information above is frue and complete to the best of my knowledge SIGNATURE MULTINE 	ach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. Set CIBP at 8460'. Circulate MLF. Pressure test casing. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. Perforate at 400'. Circulate cement to surface. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. Y '' a Spud Date: Rig Release Date: I hereby certify that the information abovOis frue and complete to the best of my knowledge SIGNATURE SIGNATURE TITLE_District Manager Type or print name_Qiay Griffin 	ach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 1. Set CIBP at 8460'. Circulate MLF. Pressure test casing. 2. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 3. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 4. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 5. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 6. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 7. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 8. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. Y '' a Spud Date: I hereby certify that the information above is frue and complete to the best of my knowledge SIGNATURE SIGNATURE TITLE_District Manager Type or print name_Clay Griffin E-mail address: cgriffin@jaymgt 	ach wellbore diagram of proposed completion Conditions of Approva! Ca 4'above ground and belief. DATE 01/21/2019 com PHONE: 574-707-5691
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 1. Set CIBP at 8460'. Circulate MLF. Pressure test casing. 2. Cap w/35' class H cement using wireline on CIBP or spot 25 sacks class H cement using tubing. 3. Perforate at 5460'. Sqz w/ 40 sx Class C cement. WOC. 4. Perforate at 3803'. Sqz w/ 40 sx Class C cement. WOC. 5. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 6. Perforate at 1707'. Sqz w/ 60 sx Class C cement. WOC. 7. Perforate at 2407'. Sqz w/ 60 sx Class C cement. WOC. 8. Cut off wellhead 4' below ground level. Verify cement to surface. Install dry hole marker. Y '' a Spud Date: I hereby certify that the information above is frue and complete to the best of my knowledge SIGNATURE SIGNATURE TITLE_District Manager Type or print name_Clay Griffin E-mail address: cgriffin@jaymgt 	ach wellbore diagram of proposed completion



GURRENT COMPLETION as of Nov 2018



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.