Submit 1 Copy To Appropriate District Office		ew Mexico		Form C-103		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013 WELL API NO.		
District II - (575) 748-1283	OIL CONSERVATION DIVISION		30-025-33696			
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178		St. Francis Dr.	5. Indicate Type			
1000 Rio Brazos Rd., Aztec, NM 87410		NM 87505	6. State Oil & Ga	FEE		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa I C, INVI 67505			302375		
87505	TICES AND REPORTS ON	WEIIS		· Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEEPE	N OR PLUG BACK TO A		Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM	C-101) FOR SUCH	WAWEIR			
1. Type of Well: Oil Well	Gas Well 🗌 Other	HOBBS OCD	8. Well Number	13		
2. Name of Operator			9. OGRID Numb	er		
Apache Corporation		MAR 2 6 2019	873	873 10. Pool name or Wildcat		
3. Address of Operator 303 Veterans Airpark Lane, Suite	1000 Midland TX 79705			MONUMENT-ABO		
4. Well Location		RECEIVED				
	feet from the N	line and	1650 feet from	n the Wline		
Section 35	Township 19S	Range 36E	NMPM	County LEA		
	11. Elevation (Show whe		etc.)			
an a				an An an Alexandra an an Alexandra an an an Alexandra		
				<b>D</b>		
12. Check	Appropriate Box to Ind	icate Nature of Notic	ce, Report or Other	Data		
NOTICE OF I	NTENTION TO:	l SI	UBSEQUENT RE	PORT OF:		
PERFORM REMEDIAL WORK		ALTERING CASING				
	IPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS 🗌 P AND A 🗌					
PULL OR ALTER CASING			ENT JOB			
CLOSED-LOOP SYSTEM		OTHER:				
13. Describe proposed or com	pleted operations. (Clearly s	tate all pertinent details,	, and give pertinent date	s, including estimated date		
	ork). SEE RULE 19.15.7.1	4 NMAC. For Multiple	Completions: Attach v	ellbore diagram of		
proposed completion or re	completion.					
Apache would like to RUN CBL SQU						
MONUMENT-ABO POOL THEN RE POOL (23000) MOVING INTO THE		TO THE GRAYBURG F	FORMATION IN THE EL	JNICE MONUMENT G/SA		
PERF GRAYBURG 4054-4130						
ACIDIZE 4054-4130 W/5000 GALS	5%HCL AND 150 BALL SE	ALERS AND PUT ON P	RODUCTION			
ONCE WORK IS COMPLETED WEI		L CHANGE TO NMGS	AU WORK TO BE COM	PLETED BY END OF 2019		
	<u> </u>	<b></b>				
Spud Date: 11-26-96	Rig Re	lease Date:   12-10-96				
Spud Date: 11-26-96	ing ite	12-10-90				
	;					
I hereby certify that the information	above is true and complete	to the best of my knowl	edge and belief.			
SIGNATURE alicia Fi	aton TITLE	Sr. Staff Reg Analyst	DA	TE 3/25/2019		
		· · · · · · · ·				
Type or print name Alicia Fulton	E-mai	address: alicia.fulton@a	pachecorp.com PH	ONE: (432) 818-1062		
For State Use Only						
APPROVED BY:	auto TITLE		ПΔ	TE <u>04/04/19</u> MIT C-1017 TO NETT, GA-SA		
Conditions of Approval (if any):	Internet Internet	11 NADURA	MULLET GILD	MIT /-1/1/2		
	11.46 DAC	K VENIEU	A. J. C. A. C. J.	TO CIUNT		
	-10	92 FUR 1	LUGPACK	IENT-GA-SA		
		F341	VICE MONT			

## W A Weir #13 (API: 30-025-33696) AFE: TBD Recomplete Grayburg – Bring into NMGSAU Waterflood

- Day 1:RU SU. PU workstring. RIH w/bit and scraper to >4500'. POOH. RU WL. Run CBL from±4500' surface. Send logs to Midland. Perforate squeeze holes @ ±3500' (or per<br/>results of CBL, discuss with Midland engineering prior to perforating). RIH w/tubing<br/>and establish circulation through squeeze holes. If full returns are established, pump<br/>dye and measure annular volume.
- Day 2/3: POOH w/tubing. RIH and set CICR @ ±3450'. RIH w/workstring and sting into CICR. Establish circulation. Squeeze 5-1/2" x 8-5/8" casing annulus w/30% excess cement volume based on annular capacity. WOC.
- Day 4: RIH and DO CICR and cement. Pressure test squeeze. If squeeze perfs don't pass pressure test, contact Midland engineering regarding how to proceed.
- Day 5: RU WL. RIH and perforate the Grayburg formation as follows w/2 SPF and 180 deg. Phasing.

## **NOTE:** CBL perf depths will be picked after running CBL by Midland engineering.

Zone	Porosity Log		CBL		Feeters	CDC	
Zone	Тор	Bottom	Тор	Bottom	- Footage	SPF	# Holes
Grayburg	4054	4061	TBD	TBD	7	2	14
Grayburg	4065	4098	TBD	TBD	33	2	66
Grayburg	4105	4130	TBD	TBD	25	2	50

RD WL. RIH w/RBP and packer. Set RBP at ±4300'. Set packer @ ±4000'.

Day 6/7: Acidize Grayburg w/5000 gals 15% HCl and 150 ball sealers.

Swab test Grayburg for pumping unit sizing.

Release packer. RIH and latch RBP. Release RBP and POOH. Lay down workstring.

Day 8: Finish POOH and lay down workstring. RIH w/tubing. RIH w/rods and pump. Set PU. POP.



