

Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office District I = (575) 393-6161 nergy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. Franch Dr. Habba NNA 99240	WELL API NO.
District II - (575) 748-1283 HOBBS OCD 811 S. First St., Artesia, NM 88210	30-025-27648 5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM APR 1 5 2019 1220 South St. Francis Dr. Sonto Fo. NIM 87505	STATE STATE
District IV - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	E-8077
87505 RECEIVED SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	State 731
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number #3
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator	9. OGRID Number
Providence Energy Services, Inc. dba Kelton Operating	012444
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 928, Andrews, TX 79714-0928	Jalmat; Tan-Yates-7 Rivers (Oil)
4. Well Location	70 0 40 41 75 15-
	30 feet from the E line
Section 26 Township 22S Range 35E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, et 3558' GL	c.)
3536 GE	
12. Check Appropriate Box to Indicate Nature of Notice	Papart or Other Data
	e, Report of Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	-
	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	NT JOB
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details,	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C	ompletions: Attach wellbore diagram of
proposed completion or recompletion.	
1. Tag CIBP (a) 3718'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cm	a @ 3718-3518'. WOC & Tag.
 Tag CIBP @ 3718'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 	@ 3718-3518'. WOC & Tag.
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 	e @ 3718-3518'. WOC & Tag.
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. 	
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. 	
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. 	
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. 	
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. See Attached	
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. See Attached	
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval	
 Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) Spot 25 sx cmt @ 100' to surface. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. See Attached	
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval	
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval Rig Release Date:	"dia 4'above ground MKR "Y cement to surp all STRINGS
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval	"dia 4'above ground MKR "Y cement to surp all STRINGS
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. See Attached Conditions of Approval Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	"dia 4 above ground MKR Y Cement to surf all STRINGS
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. See Attached Conditions of Approval Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled.	"dia 4'above ground MKR Y cement to surp aic STRings dige and belief. DATE 04/10/2019
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. See Attached Conditions of Approval Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled.	"dia 4'above ground MKR Y cement to surp aic STRings dige and belief. DATE 04/10/2019
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge of the standard of the stan	"dia 4'above ground MKR Y cement to surp aic STRings dige and belief. DATE 04/10/2019
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Abayai Anderson TITLE Agent Type or print name Abayai Anderson E-mail address: E-mail address:	"dia 4 above ground MKR Y Cement to surf all STRINGS
2. Spot 25 sx cmt @ 2350-2150'. WOC & Tag (B/Salt) 3. Perf & Sqz 50 sx cmt @ 1785-1585'. WOC & Tag (Shoe & T/Salt) 4. Spot 25 sx cmt @ 100' to surface. 5. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Y See Attached Conditions of Approval Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge of the standard of the stan	dia 4 above ground MKR y cement to surp all STRINGS dge and belief. DATE 04/10/2019 and associates corn PHONE: 432-580-716



32.3645401 -103.3307419



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.