SUNDRY Do not use thi abandoned we SUBMIT IN 1. Type of Well S Oil Well Gas Well Oth	UREAU OF LAND MANAGE NOTICES AND REPORT is form for proposals to dri II. Use form 3160-3 (APD) is TRIPLICATE - Other instruct	S ON WE ill or to re- for such p	OCD H E LLS •enter an proposals.	-		Lease Serial N	10. 23	ry 31, 2018		
Do not use thi abandoned we SUBMIT IN 1	is form for proposals to dri II. Use form 3160-3 (APD) i TRIPLICATE - Other instruc	ill or to re- for such p	enter an roposals.			If Indian, Alle		ihe Name		
SUBMIT IN 1	TRIPLICATE - Other instruc		-					ive i tallie		
I. Type of Well S Oil Well Gas Well Oth			page 2	BB		If Unit or CA	-	-	id/or No.	
		<u></u>		111	03.0.	Vell Name an	d No. ERAL SV	/D 01		
2. Name of Operator	Contact: JA	MES A SI	MITH.	<u> </u>	CEN 9	API Well No.				
3a. Address		Y@FOUND	(include are	RGY St		30-025-333). Field and Po	01 or Exp			
		h: 918-52	6-5592							
A. Location of Well (Footage, Sec., T					1	11. County or Parish, State				
Sec 7 T23S R32E SENE 1980	OFNL 660FEL					LEA COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES) TO) INDICA	TE NATU	RE OF	NOTICE, RI	EPORT, OR	OTHE	R DATA	<u></u>	
TYPE OF SUBMISSION			TY	PE OF	ACTION					
C Mating of Internet		Dee	pen		Production	luction (Start/Resume) 🔲 Water Shut-C				
Notice of Intent	Alter Casing	🗖 Hyd	raulic Fract	uring	C Reclamatio	'n	(Well Int	egrity	
Subsequent Report	Casing Repair	🗖 New	Constructi	on	Recomplet	e	C] Other		
Final Abandonment Notice	Change Plans		, and Aband	on		orarily Abandon				
	Convert to Injection	🗖 Plug	; Back		🛛 Water Disp	osal				
Management, LLC) to utilize the Injection can occur into the Des This well is currently complete 5301-5637, and 6166-6206 ft. Foundation Energy Managem from 4990 to 5020, 5040 to 50 perforations, which is not know additional perforations will be subsequent sundry notice.	elaware formation from 4660 In order to increase injectivi (ent, LLC proposes to add inj 070, and 5080 to 5110. The wn as this time will be detern	-6270 feet osal well th ty and red jection per exact loca nined by lo	rough perf uce the inju forations in tion of the g analysis	oration ection p the De addition	s from pressure, elaware forma nal ver, all	tion				
4. I hereby certify that the foregoing is	s true and correct.	· · · · · · · · · · · · · · · · · · ·						<u></u>		
	Electronic Submission #466 For FOUNDATION EN nmitted to AFMSS for process	NERGY MA	NAGEMENT SCILLA PEI	r, sent REZ on	to the Hobbs 06/03/2019 (19	PP2077SE)		•		
Name (Printed/Typed) JAMES A	SMITH		Title H		CULATORY (}	<u> </u>	
Signature (Electronic S	Submission)		Date 05	AUC /29/20			עאט			
	THIS SPACE FOR	FEDERA				<u>a</u> 2019				
			T				+		<u> </u>	
Approved By			Title			dmAsst.		Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease thich would entitle the applicant to conduct operations thereon.				Office						
	U.S.C. Section 1212, make it a crir				willfully to make	to any departm	ent or age	ncy of the l	Jnited	
States any false, fictitious or fraudulent	statements or representations as to a	anv matter w	ithin its iuriso	liction.	-					

Additional data for EC transaction #466939 that would not fit on the form

1

32. Additional remarks, continued

Upon completion of perforating and acidizing, plastic-coated injection tubing will be set in a packer located within 100 ft of the uppermost injection perforations.

Attached is a specific procedure describing the proposed operations.

1. MIRU WO Rig

- 2. Kill well if necessary, using 2% KCL.
- 3. ND WH. NU BOP

- Unseat Packer, PU joints and lower tubing to tag for fill.
 TOOH with TBG. Tally as POOH and note tagged depth.
 If fill is covering existing perfs, cleanout to TD before proceeding to next step.
- 7. MIRU wireline
 8. RIH with 3 1/8? gun and perf new injection perfs from 4490-5020, 5040-5070, and 5080-5110.
- 9. POOH with WL guns
- 10. RD Wireline
 11. PU and RIH with redressed packer and RIH with tubing.
 12. Hydrotest as RIH to 6000 psi.

13. Set packer above new peris at +/- 4910?
 14. MIRU acid crew and test flowlines
 15. Pump acid job according to pump schedule. 5,000-10,000 gals 7.5% NEFE HCl w/ scale inhibitor,

- clay stabilizer and ball sealers.
- 16. RDMO acid crew.
- RDMO action takes.
 Pressure test packer is holding to 500 psi and 1000 psi for 10 min each.
 Perform injection test to determine injection rate and pressure.
 RDMO Wo Rig.

- 20. Reconnect equipment for disposal.

Submit 1 Copy	/ To Appropriate	District		State of	New Me	xico			For	n C-103		
Office District 1 - (57	5) 393-6161		Ener			ral Resources			Revised Jul			
1625 N. Frencl District II – (5'	h Dr., Hobbs, NM	88240					WE	LL API NO. 30-025-33398				
	, Artesia, NM 88	210	Oll	L CONSER 1220 Sout			5. 1	5. Indicate Type of Lease				
1000 Rio Braz	os Rd., Aztec, NN	4 87410			e, NM 87			STATE	FEE [
<u>District IV</u> – (5 1220 S. St. Fra 87505	505) 476-3460 ncis Dr., Santa Fe	e, NM		Santa I	c, 14141 07	505	0. 2	State Oil & Gas L NM-86923	ease No.			
				REPORTS O			7. 1	Lease Name or U		t Name		
•				RILL OR TO DEE R PERMIT" (FOR				Bitsy Federal S	SWD			
PROPOSALS.) Well: Oil We	n 🗆 🧿	Gas Well	X Other S	WD		8. 1	Well Number 1				
2. Name of	Operator		9. (OGRID Number								
3. Address	Foundation E	Energy Ma	anagemen	nt, LLC			10	Pool name or Wi	ildeet			
		Springs R	d, Suite 6	50, Addison,	Texas 7500)1	. 10.	Delaware	nocat			
4. Well Loc												
	it Letter tion 7	_H:_	_1980	feet from the	North	line and	660 32 East		the <u>East</u>	line		
Sec			11. Eleva	Township ation (Show w	23 South hether DR.	Range RKB, RT, GR,		NMPM	Count	y Lea		
				0' GL								
	12	Check A	nnronria	te Boy to In	dicate Na	ture of Noti	ce Reno	ort or Other Da	to			
		•	••••				· •					
DEDEOOM	NOTICE REMEDIAL W			N TO: ND ABANDON		REMEDIAL W						
			CHANGE			COMMENCE		_	TERING CAS			
	LTER CASING	=		E COMPL		CASING/CEM						
	E COMMINGL											
)OP SYSTEM d Delaware Ir		erfe		X	OTHER:				П		
				tions. (Clearly			, and give	pertinent dates, i	ncluding estir	nated date		
	arting any pro osed completi			RULE 19.15.7	.14 NMAC	For Multiple	Completi	ons: Attach well	bore diagram	of		
								ergy Management, 1 4660-6270 feet.	LLC) to utilize	e the Bitsy		
This well is cur	rently complete	d as a prod	uced water	disposal well th	rough perfo	rations from 530	1-5637, an	d 6166-6206 ft. In	order to increas	e		
injectivity and a from 4990 to 50 determined by l	reduce the inject 020, 5040 to 50	tion pressur 70, and 508	re, Foundat 0 to 5110 f	tion Energy Mar feet. The exact	nagement, Ll location of th	LC proposes to a ne additional per	dd injectio forations, v	n perforations in th which is not known 1156, and will be r	e Delaware for as this time wil	mation Il be		
sundry notice.												
Upon completion perforations.	on of perforatin	g and acidiz	zing, plastic	c-coated injection	on tubing wil	l be set in a pack	ter located	within 100 ft of the	uppermost inje	ection		
Attached is a sp	ecific procedur	e describing	g the propo	sed operations.								
2												
mover Work												
Spud Date:	6/17/2019			Rig F	Release Date	e: 6/19/20	19	1				
I								J				
I hereby certif	w that the info	rmation-el	ove is tru	e and complet	e to the bes	t of my knowle	edge and l					
Thereby certif	y unat une mito		1	e and complet			cuge and t	Jenei.	,			
SIGNATURE	Â	hyte	L	TITI	E HSI	2-legleton.	Superior	DATE	5/29	19		
Type or print 1 <u>For State Use</u>		Mer	METH	E-ma	ail address:	shirth	Ctarle	Alacy, Phon	е: <u>918-5</u> 26	- 5592		
				TTTT	E	~		الله بر الله 1				
APPROVED I		<u></u>		TITL	с	····		DATE_				

Bitsy Federal #1 SWD


Sand Dunes Add Perfs to Increase Injection Capacity and Lower Pressure Lea, County NM

Casing /Tubular Details and Capacities:

TUBULAR	SIZE	GRADE	DEPTH (ft)	WEIGHT (ppf)	CEMENT (sx)	TOC (ft)	
Surface Casing	13-3/8"	H-40	858	.48	650	SFC	Circ
Intermediate Casing	8-5/8"	J-55	4338	32	1500	SFC	Circ
Production Casing	5-1/2"	Ķ-55	9442	17	1330	SFC	Circ
Producing Tubing	2- 7/8″	IPC	4900	6.4	n/a	n/a	n/a

Procedure:

- 1. MIRU WO Rig
- 2. Kill well if necessary, using 2% KCL.
- 3. ND WH. NU BOP
- 4. Unseat Packer, PU joints and lower tubing to tag for fill.
- 5. TOOH with TBG. Tally as POOH and note tagged depth.
- 6. If fill is covering existing perfs, cleanout to TD before proceeding to next step.
- 7. MIRU wireline
- 8. RIH with 3 1/8" gun and perf new injection perfs from 4490-5020, 5040-5070, and 5080-5110.
- 9. POOH with WL guns
- 10. RD Wireline
- 11. PU and RIH with redressed packer and RIH with tubing.
- 12. Hydrotest as RIH to 6000 psi.
- 13. Set packer above new perfs at +/- 4910'
- 14. MIRU acid crew and test flowlines
- 15. Pump acid job according to pump schedule. 5,000-10,000 gals 7.5% NEFE HCl w/ scale inhibitor, clay stabilizer and ball sealers.
- 16. RDMO acid crew.
- 17. Pressure test packer is holding to 500 psi and 1000 psi for 10 min each.
- 18. Perform injection test to determine injection rate and pressure.
- 19. RDMO Wo Rig.
- 20. Reconnect equipment for disposal.



. . . .

